

LIM MOTOR PTE LTD
 SIN MING AUTO CITY
 160 SIN MING DRIVE
 #05-20
 SINGAPORE 575722

*Not Authorized
 11 Smg @?
 Resurvey After Paint*

*Kenneth
 96910663*

21/04/2020

ESTIMATED REPAIR COST FOR VEHICLE NO: SJR6166C (MODEL: LEXUS IS300-2.0 (A))

ACCIDENT DATE : 15-04-2020 TIME : 07:40
 CLIENT'S NAME : LEOW CHAI HONG

S/NO	QTY	ITEMS	AMT (\$S)
	A	DESCRIPTION	
1	1	LHF RIM	1,289.00 ?
2	1	LHF WHEEL BEARING HUB	698.00 ?
3	1	LHF KNUCKLE ARM	1,231.00 ?
4	1	LHF LOWER ARM	491.00 ?
5	1	LHF UPPER ARM	505.00 ?
6	1	LHF LOWER BALLJOINT	140.00 ?
7	1	LHF STABILIZER LINK	134.00 X
8	1	LHF SPRING STRUT	1,067.00 ?
	B	LABOUR	
1	-	RENEW LHF RIM	30.00 ?
2	-	RENEW LHF UNDERCARRIAGES	280.00 ?
3	-	WHEEL ALIGNMENT	100.00 601
4	-	CONDUCT SPRAY PAINTING ON AFFECTED PANELS	500.00 X
5	-	COATING (FRONT BUMPER)	180.00 X
	TOTAL		6,645.00
		LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation (7% GST)	465.15
			7,110.15

Thank you.

LIM MOTOR PTE LTD

DATE: 22/4/2020



Acknowledged by Repairer
 Signature:
 Date:

1ST INSPECTION

27/4/20 1pm
 (DATE/TIME)

SURVEYOR NAME :

Kenneth

2ND INSPECTION

 (DATE/TIME)

COMPANY NAME: _____

3RD INSPECTION

 (DATE/TIME)