

LIM MOTOR PTE LTD
 SIN MING AUTO CITY
 160 SIN MING DRIVE
 #05-20
 SINGAPORE 575722

*Not Authorized
 11 Smg @?
 Resurvey After Paint*

*Kenneth
 96910663 1day*

21/04/2020

ESTIMATED REPAIR COST FOR VEHICLE NO: SJR6166C (MODEL: LEXUS IS300-2.0 (A))

ACCIDENT DATE : 15-04-2020 TIME : 07:40
 CLIENT'S NAME : LEOW CHAI HONG

S/NO	QTY	ITEMS	AMT (\$)
	A	DESCRIPTION	
1	1	LHF RIM	1,289.00
2	1	LHF WHEEL BEARING HUB	698.00
3	1	LHF KNUCKLE ARM	1,231.00
4	1	LHF LOWER ARM	491.00
5	1	LHF UPPER ARM	505.00
6	1	LHF LOWER BALLJOINT	140.00
7	1	LHF STABILIZER LINK	134.00
8	1	LHF SPRING STRUT	1,067.00
	B	LABOUR	
1	-	RENEW LHF RIM	30.00
2	-	RENEW LHF UNDERCARRIAGES	280.00
3	-	WHEEL ALIGNMENT	100.00
4	-	CONDUCT SPRAY PAINTING ON AFFECTED PANELS	500.00
5	-	COATING (FRONT BUMPER)	180.00
	TOTAL		6,645.00
		LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation (7% GST)	465.15
			7,110.15

?
?
?
?
?
?
X
?
?
601
X
X

Thank you.



LIM MOTOR PTE LTD
 DATE: 22/4/2020

Acknowledged by Repairer
 Signature:
 Date:

1ST INSPECTION 27/4/20 1pm
 (DATE/TIME)

SURVEYOR NAME: Kenneth

2ND INSPECTION _____
 (DATE/TIME)

COMPANY NAME: _____

3RD INSPECTION _____
 (DATE/TIME)