

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35390

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0382/2020/NS
Date : 20-Apr-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Cho Yoong Chow
Address : 34 Upper Bukit Timah Road
#04-05
Singapore 588197
Telephone : (HP) +65 96880475
Type of Claim : Own Damage Claims
Policy No. : 1700059687-02
Vehicle No : **SJS 2080 L**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 11/9/2017
Engine No : CVK 043491
Chassis No : WAUZZZF57JA021943
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Apr-20
Place of Accident : Bukit Timah Plaza Parking Area

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 2080 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	✓ X
2	To renew rhs 1/4 glass to facilitate fender renewal.	S/N	\$ 300.00	✓ X
3	To install solar film for 1/4 glass.	S/N	\$ 400.00	✓ X
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00	✓ X
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	✓ 280
SUB TOTAL LABOUR CHARGES		:	<u><u>\$ 3,860.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 2080 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
6	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	280.00	✓ ✓
7	To dismantle rear bumper, rhs rear door and rhs sillpanel trim. Cut out and weld rhs rear fender. To renew rhs rear door and rhs sillpanel trim. Re-organise crash management components. Reinstall all parts removed.	\$	7,200.00	3500. 2000
8	To respray rear bumper, rhs rear door, door handle, rhs rear fender, rhs sillpanel, door entrances, roof channel, drain panel, rhs sill panel trim and end panelling. To carry out stone chip treatment and joint sealer works.	\$	7,300.00	2850 3675 6 main pieces 3300. entrance, channel : 275 Handle : 100.
9	To renew rhs rear rim and carry out wheel alignment.	S/N \$	280.00	+ X
10	To carry out diagnostic check.	S/N \$	192.00	+ ✓
TOTAL LABOUR CHARGES		:	\$ 19,112.00	

✓ ✓
 Bumper, Fender, door, sill panel, sill panel trim
 = 550 X 5 = 2750
 Handle = $\frac{100}{2850}$

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 2080 L

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
1	REAR FENDER - RH <i>dent</i>	\$	2,354.00 ✓	1883.20
2	SIDE WINDOW - RH <i>over</i> X nn	\$	676.00 ✓	540.40
3	REAR DOOR - RH <i>dent</i>	\$	2,946.00 ✓	2356.80
4	REAR DOOR OUTER SEAL - RH <i>m</i>	NEC \$	209.00 ✓	167.20
5	BONDING AGENT <i>nee</i>	NEC \$	46.00 ?	36.72
6	CLEANING SOLUTION <i>nee</i>	NEC \$	64.00 ?	51.20
7	REAR DOOR CATCH <i>non damaged</i>	\$	113.00 +	90.40
8	CHROME TRIM - RH <i>ut</i>	\$	128.00 +	102.40
9	DOOR HANDLE TRIM PLATE - RH <i>nee</i>	\$	83.00 +	
10	DOOR HANDLE SENSOR - RH <i>nee</i>	\$	215.00 +	
11	EXTERIOR DOOR HANDLE - RH <i>Ris</i>	\$	40.00 +	
12	DOOR LOCK - RH <i>nee</i>	\$	623.00 +	
13	DOOR INNER PANEL COVER - RH <i>nee</i>	\$	30.00 +	
14	WINDOW REGULATOR - RH <i>nee</i>	\$	338.00 +	
15	WINDOW REGULATOR MOTOR - RH <i>nee</i>	\$	301.00 +	
16	SIDE MEMBER TRIM - RH <i>dent</i>	\$	778.00 ✓	622
17	SIDE MEMBER TRIM ATTACHMENT PARTS <i>nee</i>	\$	123.00 ?	98
18	SIDE MEMBER TRIM ADHESIE TAPES <i>nee</i>	\$	200.00 ✓	159.60
19	REAR ALUMINIUM RIM - RH <i>nee</i>	\$	964.00 +X	
20	ACRYLIC SEALANT	S/N \$	180.00 ✓ ✓	
21	CAITY WAX	S/N \$	140.00 ✓ ✓	
22	STONE CHIP	S/N \$	180.00 ✓ ✓	
23	METAL FILLER POWDER	S/N \$	280.00 ✓ ✓	
24	1/4 GLASS SEALANT X	S/N \$ nn	100.00 ✓ ✓	
25	SUNDRIES <i>nee</i>	\$	500.00 ?	218.14

TOTAL SPARE PARTS CHARGES

\$ 11,611.00

TOTAL LABOUR CHARGES

: \$ 19,112.00

GRAND TOTAL

\$ 30,723.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35390

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0382/2020/NS
Date : 20-Apr-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

13 days exclude 2 Sundays

jb 23 Dec 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Cho Yoong Chow
Address : 34 Upper Bukit Timah Road
#04-05
Singapore 588197
Telephone : (HP) +65 96880475
Type of Claim : Own Damage Claims
Policy No. : 1700059687-02
Vehicle No : **SJS 2080 L**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 11/9/2017
Engine No : CVK 043491
Chassis No : WAUZZZF57JA021943
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Apr-20
Place of Accident : Bukit Timah Plaza Parking Area

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Estimated Labour Charges for Accident Vehicle SJS 2080 L**

S/n	Nature of Jobs		Estimated Charges	Surveyor's recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	
2	To renew rhs 1/4 glass to facilitate fender renewal.	S/N	\$ 300.00	
3	To install solar film for 1/4 glass.	S/N	\$ 400.00	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00	
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	\$ 280.00
SUB TOTAL LABOUR CHARGES		:	\$ 3,860.00	\$ 280.00

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 2080 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's ecommendation
				\$ 280.00
6	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages. c/f	S/N	\$ 280.00	\$ 280.00
7	To dismantle rear bumper, rhs rear door and rhs sillpanel trim. Cut out and weld rhs rear fender. To renew ths rear door and rhs sillpanel trim. Re-organise crash management components. Reinstall all parts removed.		\$ 7,200.00	\$ 2,000.00
8	To respray rear bumper, rhs rear door, door handle, rhs rear fender, rhs sillpanel, door entrances, roof channel, drain panel, rhs sill panel trim and end panelling. To carry out stone chip treatment and joint sealer works.		\$ 7,300.00	\$ 2,850.00
9	To renew rhs rear rim and carry out wheel alignment.	S/N	\$ 280.00	
10	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES			\$ 19,112.00	\$ 5,602.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 2080 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR FENDER - RH	\$ 2,354.00	\$ 1,883.20
2	SIDE WINDOW - RH	\$ 676.00	\$ 540.40
3	REAR DOOR - RH	\$ 2,946.00	\$ 2,356.80
4	REAR DOOR OUTER SEAL - RH	NEC \$ 209.00	\$ 167.20
5	BONDING AGENT	NEC \$ 46.00	\$ 36.72
6	CLEANING SOLUTION	NEC \$ 64.00	\$ 51.20
7	REAR DOOR CATCH	\$ 113.00	\$ 90.40
8	CHROME TRIM - RH	\$ 128.00	\$ 102.40
9	DOOR HANDLE TRIM PLATE - RH	\$ 83.00	
10	DOOR HANDLE SENSOR - RH	\$ 215.00	
11	EXTERIOR DOOR HANDLE - RH	\$ 40.00	
12	DOOR LOCK - RH	\$ 623.00	
13	DOOR INNER PANEL COVER - RH	\$ 30.00	
14	WINDOW REGULATOR - RH	\$ 338.00	
15	WINDOW REGULATOR MOTOR - RH	\$ 301.00	
16	SIDE MEMBER TRIM - RH	\$ 778.00	\$ 622.00
17	SIDE MEMBER TRIM ATTACHMENT PARTS	\$ 123.00	\$ 98.00
18	SIDE MEMBER TRIM ADHESIE TAPES	\$ 200.00	\$ 159.60
19	REAR ALUMINIUM RIM - RH	\$ 964.00	
20	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00
21	CAITY WAX	S/N \$ 140.00	\$ 140.00
22	STONE CHIP	S/N \$ 180.00	\$ 180.00
23	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
24	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
25	SUNDRIES	\$ 500.00	\$ 218.14
TOTAL SPARE PARTS CHARGES		\$ 11,611.00	\$ 7,206.06
TOTAL LABOUR CHARGES		\$ 19,112.00	\$ 5,602.00
GRAND TOTAL		\$ 30,723.00	\$ 12,808.06

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant