

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35390

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0382/2020/NS
Date : 20-Apr-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Cho Yoong Chow
Address : 34 Upper Bukit Timah Road
#04-05
Singapore 588197
Telephone : (HP) +65 96880475
Type of Claim : Own Damage Claims
Policy No. : 1700059687-02
Vehicle No : **SJS 2080 L**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 11/9/2017
Engine No : CVK 043491
Chassis No : WAUZZZF57JA021943
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Apr-20
Place of Accident : Bukit Timah Plaza Parking Area

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 2080 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	✓
2	To renew rhs 1/4 glass to facilitate fender renewal.	S/N	\$ 300.00	✓
3	To install solar film for 1/4 glass.	S/N	\$ 400.00	✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00	✓
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 3,860.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6641 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 2080 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
6	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	280.00	✓
7	To dismantle rear bumper, rhs rear door and rhs sillpanel trim. Cut out and weld rhs rear fender. To renew rhs rear door and rhs sillpanel trim. Re-organise crash management components. Reinstall all parts removed.	\$	7,200.00 3500.	
8	To respray rear bumper, rhs rear door, door handle, rhs rear fender, rhs sillpanel, door entrances, roof channel, drain panel, rhs sill panel trim and end panelling. To carry out stone chip treatment and joint sealer works.	\$	7,300.00 3675	6 main pieces 3300. entrance, channel : 275 Handle : 100.
9	To renew rhs rear rim and carry out wheel alignment.	S/N \$	280.00	✗
10	To carry out diagnostic check.	S/N \$	192.00	✗
TOTAL LABOUR CHARGES		:	<u>\$ 19,112.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 2080 L

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR FENDER - RH <i>Dented</i>	\$	2,354.00	✓
2	SIDE WINDOW - RH <i>scr</i>	\$	676.00	✓
3	REAR DOOR - RH <i>Dented</i>	\$	2,946.00	✓
4	REAR DOOR OUTER SEAL - RH <i>new</i>	NEC \$	209.00	✓
5	BONDING AGENT <i>?</i>	NEC \$	46.00	?
6	CLEANING SOLUTION <i>?</i>	NEC \$	64.00	?
7	REAR DOOR CATCH <i>new</i>	\$	113.00	+
8	CHROME TRIM - RH <i>new</i>	\$	128.00	+
9	DOOR HANDLE TRIM PLATE - RH <i>new</i>	\$	83.00	+
10	DOOR HANDLE SENSOR - RH <i>new</i>	\$	215.00	+
11	EXTERIOR DOOR HANDLE - RH <i>Right</i>	\$	40.00	+
12	DOOR LOCK - RH <i>new</i>	\$	623.00	+
13	DOOR INNER PANEL COVER - RH <i>new</i>	\$	30.00	+
14	WINDOW REGULATOR - RH <i>new</i>	\$	338.00	+
15	WINDOW REGULATOR MOTOR - RH <i>new</i>	\$	301.00	+
16	SIDE MEMBER TRIM - RH <i>Dented</i>	\$	778.00	✓
17	SIDE MEMBER TRIM ATTACHMENT PARTS <i>?</i>	\$	123.00	?
18	SIDE MEMBER TRIM ADHESIE TAPES <i>new</i>	\$	200.00	✓
19	REAR ALUMINIUM RIM - RH <i>new</i>	\$	964.00	+
20	ACRYLIC SEALANT <i>} new</i>	S/N \$	180.00	✓
21	CAITY WAX	S/N \$	140.00	✓
22	STONE CHIP	S/N \$	180.00	✓
23	METAL FILLER POWDER	S/N \$	280.00	✓
24	1/4 GLASS SEALANT <i>?</i>	S/N \$	100.00	✓
25	SUNDRIES	\$	500.00	?
TOTAL SPARE PARTS CHARGES		\$	11,611.00	
TOTAL LABOUR CHARGES		:	\$ 19,112.00	
GRAND TOTAL		\$	30,723.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian
Surveyed Date : 23/04/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

