



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S0M02FNW

Date: 15th May 2020

Our Ref: CS3/ASM20002270/T1tf3s2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01
AXA Tower
Singapore 068811

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKG 2261H
INSURED VEHICLE: SKE 1492A ACCIDENT DATE: 24/01/2020**

We thank you for your instruction on 23/04/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKG 2261H from M/s C L Appraiser Pte Ltd.
- b) Final Repair Bill of SKG 2261H from M/s Teamwork Garage Pte Ltd.
- c) Singapore Accident Statement of Vehicle SKG 2261H.
- d) Colour damaged vehicle photographs of SKG 2261H.

Pre-Repair Inspection Date: 11/02/2020 at M/s Teamwork Garage Pte Ltd, 53 Ubi Avenue 1 #01-24 Singapore 408934.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKG 2261H
Make & Model	: Toyota Estima
Year of Registration	: 2008
Chassis Number	: ACR507056208
Engine Capacity	: 2362 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.