

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC4/FC120005376/Uka3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

FBIK 2469L

at Workshop m/s _____

BHH

of _____

Insured: _____

SH 8487J

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

4,550.00

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

5 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS _____

280c.

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

FBIK 2469 L

Yr Regn: _____

ST 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Yamaha YBR 125

c.c *124*

Colour _____

Black

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

12282

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

LBPKE1780E0028775

Gen. Cond: Good / Fair / Poor / Burnt

Steering: _____

In order / Jammed / Leaked / Burnt or other

Brake: _____

In order / Jammed / Leaked / Burnt or

Modi: _____

Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: *2-75-18*

R: *3-00-18 90-90-18*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

6 mm

Rear

R/Bal. _____

6 mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

15/3/20

D.O.I. _____

24/4/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

24 05, 15 30

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/4/20 LTA 3282 with 2218 after Raymond not work then etc.

23/6/20 confirmed r/s \$1850 with Raymond

Date/Time, File Pass to?

: Preli. Report
 : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

) \$ + RS. \$ _____

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

Empty box for totals and fees.



QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

*no. of Authored
H/L
1/5 \$1810
5 days.
24/4/20
Take photo of damage.*

NO. : 36003

DATE : 04/04/2020
CLAIM NO. : 11547
POLICY NO. : MC/00792920
FROM : RAYMOND

VEHICLE NO. : FBK2469L
MAKE/MODEL : YAM / YBR125

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 42062	REPLACE	1.00	\$70.00	70.00 ✓
2	BEARING STEERING CONE LOWER P/N: 26831	REPLACE	1.00	\$5.60	5.60 ✓
3	BRACKET DETACHABLE LOWER (NEW MODEL) P/N: 39055	REPLACE	1.00	\$140.00	140.00 X
4	BRACKET FOOTREST RH P/N: 45628	REPLACE	1.00	\$116.20	116.20 ✓
5	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$179.20	179.20 ✓
6	CALIPER BRAKE FRONT ASSY P/N: 45878	REPLACE	1.00	\$390.60	390.60 X
7	COVER CLUTCH P/N: 26825	REPLACE	1.00	\$128.10	128.10 ✓
8	COVER GUIDE AIR RH P/N: 65354	REPLACE	1.00	\$10.70	10.70 ✓
9	COVER SIDE LH (BLACK) P/N: 45775	REPLACE	1.00	\$117.60	117.60 ✓
10	COWLING FRONT (BLACK) P/N: 50000	REPLACE	1.00	\$282.80	282.80 ✓
11	CRASH BAR P/N: 35878	REPLACE	1.00	\$193.20	193.20 ✓
12	CROWN HANDLE P/N: 28100	REPLACE	1.00	\$74.40	74.40 X
13	EMBLEM (YAMAHA) FUEL TANK P/N: 54569	REPLACE	1.00	\$8.40	8.40 X
14	FOOTREST FRONT P/N: 42064	REPLACE	1.00	\$77.20	77.20 ✓

*36003 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
15	FORK FRONT ASSY LH P/N: 53024	REPLACE	1.00	\$532.00	532.00 X
16	FORK FRONT ASSY RH P/N: 53025	REPLACE	1.00	\$532.00	532.00 X
17	GASKET CLUTCH COVER P/N: 45295	REPLACE	1.00	\$19.60	19.60
18	GRIP HANDLE LH P/N: 26845	REPLACE	1.00	\$4.20	4.20
19	LABOUR P/N: 06766	Supply/Install	8.00	\$63.00	504.00
20	LAMP SIGNAL FRONT LH P/N: 43344	REPLACE	1.00	\$53.90	53.90 X
21	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	\$63.00	63.00 X
22	LEVER CLUTCH P/N: 52644	REPLACE	1.00	\$18.20	18.20 X
23	LOCK SIDE COVER P/N: 26827	REPLACE	1.00	\$14.00	14.00 X
24	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$280.00	280.00 X
25	MIRROR LH P/N: 52645	REPLACE	1.00	\$29.40	29.40
26	MIRROR RH P/N: 46219	REPLACE	1.00	\$29.40	29.40 X
27	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$96.60	96.60
28	NUT P/N: 21960	REPLACE	1.00	\$5.60	5.60
29	PEDAL BRAKE P/N: 44906	REPLACE	1.00	\$86.80	86.80
30	PIPE EXHAUST ASSY P/N: 26600	REPLACE	1.00	\$350.00	350.00 X
31	PLATE DISC BRAKE FRONT P/N: 46052	REPLACE	1.00	\$193.20	193.20
32	RACE BALL 1 P/N: 26829	REPLACE	1.00	\$11.20	11.20
33	RACE BALL 1 P/N: 26829	REPLACE	1.00	\$11.20	11.20
34	RACE BALL LOWER 2 P/N: 26828	REPLACE	1.00	\$11.20	11.20
35	RACE BALL UPPER 2 P/N: 26830	REPLACE	1.00	\$11.20	11.20
36	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00

*36003 *



S/N	Description	Action	Qty	Unit Price	Amount
37	SEAL OIL (20X30X4.5) SHAFT KICK STARTER P/N: 26826	REPLACE	1.00	\$3.70	3.70
38	STAY HEADLAMP P/N: 45750	REPLACE	1.00	\$67.20	67.20
39	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
40	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
41	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
42	SWITCH BRAKE REAR P/N: 26535	REPLACE	1.00	\$15.40	15.40
43	TANK FUEL ASSY (RED) P/N: 54335	REPLACE <i>\$120</i>	1.00	\$550.20	550.20
44	TRANSPORT CHARGES P/N: 07169		1.00	\$56.00	56.00
SUB TOTAL					\$5,483.20
GST @ 7 %					\$383.82
GRAND TOTAL					\$5,867.02

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

2 pcs. seal Dust fork @ 7.50 = 15 net ✓
 2 bol seal oil fork @ 12.00 = 24 net ✓
 2 pcs Tube inner fork @ 96.00 = 192 net ✓

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

9-1909.5
 102
 1718.55
 601
 2319.55
 252
 1888.64

*36003 *

bizSAFE₃





QUOTATION

Customer :

NO. : 36003

- Rev. 1

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

DATE : 04/04/2020
CLAIM NO. : 11547
POLICY NO. : MC/00792920
FROM : RAYMOND

VEHICLE NO. : FBK2469L
MAKE/MODEL : YAM / YBR125

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 42062	REPLACE	1.00	\$70.00 Disc %: 10.00	63.00
2	BEARING STEERING CONE LOWER P/N: 26831	REPLACE	1.00	\$5.60 Disc %: 10.00	5.04
3	BRACKET FOOTREST RH P/N: 45628	REPLACE	1.00	\$116.20 Disc %: 10.00	104.58
4	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$179.20 Disc %: 10.00	161.28
5	COVER CLUTCH P/N: 26825	REPLACE	1.00	\$128.10 Disc %: 10.00	115.29
6	COVER GUIDE AIR RH P/N: 65354	REPLACE	1.00	\$10.70 Disc %: 10.00	9.63
7	COVER SIDE LH (BLACK) P/N: 45775	REPLACE	1.00	\$117.60 Disc %: 10.00	105.84
8	COWLING FRONT (BLACK) P/N: 50000	REPLACE	1.00	\$282.80 Disc %: 10.00	254.52
9	CRASH BAR P/N: 35878	REPLACE	1.00	\$193.20 Disc %: 10.00	173.88
10	FOOTREST FRONT P/N: 42064	REPLACE	1.00	\$77.20 Disc %: 10.00	69.48
11	GASKET CLUTCH COVER P/N: 45295	REPLACE	1.00	\$19.60 Disc %: 10.00	17.64
12	GRIP HANDLE LH P/N: 26845	REPLACE	1.00	\$4.20 Disc %: 10.00	3.78
13	LABOUR P/N: 06766	Supply/Install	1.00	\$320.00	320.00
14	MIRROR RH P/N: 46219	REPLACE	1.00	\$29.40 Disc %: 10.00	26.46



*bizSAFE*₃



S/N	Description	Action	Qty	Unit Price	Amount
15	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$96.60 Disc %: 10.00	86.94
16	NUT P/N: 21960	REPLACE	1.00	\$5.60 Disc %: 10.00	5.04
17	PEDAL BRAKE P/N: 44906	REPLACE	1.00	\$86.80 Disc %: 10.00	78.12
18	PLATE DISC BRAKE FRONT P/N: 46052	REPLACE	1.00	\$193.20 Disc %: 10.00	173.88
19	RACE BALL 1 P/N: 26829	REPLACE	1.00	\$11.20 Disc %: 10.00	10.08
20	RACE BALL 1 P/N: 26829	REPLACE	1.00	\$11.20 Disc %: 10.00	10.08
21	RACE BALL LOWER 2 P/N: 26828	REPLACE	1.00	\$11.20 Disc %: 10.00	10.08
22	RACE BALL UPPER 2 P/N: 26830	REPLACE	1.00	\$11.20 Disc %: 10.00	10.08
23	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00 Disc %: 10.00	12.60
24	SEAL OIL (20X30X4.5) SHAFT KICK STARTER P/N: 26826	REPLACE	1.00	\$3.70 Disc %: 10.00	3.33
25	SPRAY PAINT FUEL TANK	Spray	1.00	\$120.00	120.00
26	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
27	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
28	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
29	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00
30	SEAL DUST FORK <i>ADD</i> P/N: 26833		2.00	\$7.50 Disc %: 10.00	13.50 ✓
31	SEAL OIL FORK (30X40.5X10.5) <i>ADD</i> P/N: 58118	Replace	2.00	\$12.00 Disc %: 10.00	21.60 ✓
32	TUBE INNER FORK <i>ADD</i> P/N: 27114	Replace	2.00	\$96.00 Disc %: 10.00	172.80 ✓

SUB TOTAL \$2,319.55
 GST @ 7 % \$162.37
GRAND TOTAL (SGD) \$2,481.92

50% deposit required before ordering of parts.

Validity: 30 days



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	For & on Behalf of				
	BAN HOCK HIN CO PTE LTD				

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001:2015