



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

*No. of Authorized
H/W
1/5 \$
5 days.
24/4/20
Take photo of lamp*

NO. : 36003

DATE : 04/04/2020
CLAIM NO. : 11547
POLICY NO. : MC/00792920
FROM : RAYMOND

VEHICLE NO. : FBK2469L
MAKE/MODEL : YAM / YBR125

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 42062	REPLACE	1.00	\$70.00	70.00 <i>Set ✓</i>
2	BEARING STEERING CONE LOWER P/N: 26831	REPLACE	1.00	\$5.60	5.60 <i>Set ✓</i>
3	BRACKET DETACHABLE LOWER (NEW MODEL) P/N: 39055	REPLACE	1.00	\$140.00	140.00 ?
4	BRACKET FOOTREST RH P/N: 45628	REPLACE	1.00	\$116.20	116.20 <i>Set ✓</i>
5	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$179.20	179.20 <i>Set ✓</i>
6	CALIPER BRAKE FRONT ASSY P/N: 45878	REPLACE	1.00	\$390.60	390.60 X
7	COVER CLUTCH P/N: 26825	REPLACE	1.00	\$128.10	128.10 ?
8	COVER GUIDE AIR RH P/N: 65354	REPLACE	1.00	\$10.70	10.70 <i>cm ✓</i>
9	COVER SIDE LH (BLACK) P/N: 45775	REPLACE	1.00	\$117.60	117.60 <i>cm ✓</i>
10	COWLING FRONT (BLACK) P/N: 50000	REPLACE	1.00	\$282.80	282.80 <i>cm ✓</i>
11	CRASH BAR P/N: 35878	REPLACE	1.00	\$193.20	193.20 <i>Set ✓</i>
12	CROWN HANDLE P/N: 28100	REPLACE	1.00	\$74.40	74.40 <i>Tw ✓</i>
13	EMBLEM (YAMAHA) FUEL TANK P/N: 54569	REPLACE	1.00	\$8.40	8.40 <i>Set ✓</i>
14	FOOTREST FRONT P/N: 42064	REPLACE	1.00	\$77.20	77.20 <i>Tw ✓</i>

*36003 *

bizSAFE₃



Address: No. 6, DeLu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price		Amount
15	FORK FRONT ASSY LH P/N: 53024	REPLACE	1.00	\$532.00	3rd	532.00 ✓
16	FORK FRONT ASSY RH P/N: 53025	REPLACE	1.00	\$532.00	3rd	532.00 ✓
17	GASKET CLUTCH COVER P/N: 45295	REPLACE	1.00	\$19.60	new	19.60 ✓
18	GRIP HANDLE LH P/N: 26845	REPLACE	1.00	\$4.20	7.00	4.20 ✓
19	LABOUR P/N: 06766	* Supply/Install	8.00	\$63.00	320	504.00 ✓
20	LAMP SIGNAL FRONT LH P/N: 43344	REPLACE	1.00	\$53.90	cut	53.90 ✓
21	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	\$63.00	cut	63.00 ✓
22	LEVER CLUTCH P/N: 52644	REPLACE	1.00	\$18.20	scr	18.20 ✓
23	LOCK SIDE COVER P/N: 26827	REPLACE	1.00	\$14.00		14.00 ?
24	METER IU (12V) NEW MODEL P/N: 34351	* REPLACE	1.00	\$280.00	one	280.00 ✓ 1755.00
25	MIRROR LH P/N: 52645	REPLACE	1.00	\$29.40	cut	29.40 ✓
26	MIRROR RH P/N: 46219	REPLACE	1.00	\$29.40	cut	29.40 ✓
27	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$96.60	cut	96.60 ✓
28	NUT P/N: 21960	REPLACE	1.00	\$5.60	new	5.60 ✓
29	PEDAL BRAKE P/N: 44906	REPLACE	1.00	\$86.80	3rd	86.80 ✓
30	PIPE EXHAUST ASSY P/N: 26600	REPLACE	1.00	\$350.00	n	350.00 X
31	PLATE DISC BRAKE FRONT P/N: 46052	REPLACE	1.00	\$193.20	3rd	193.20 ✓
32	RACE BALL 1 P/N: 26829	REPLACE	1.00	\$11.20	new	11.20 ✓
33	RACE BALL 1 P/N: 26829	REPLACE	1.00	\$11.20	new	11.20 ✓
34	RACE BALL LOWER 2 P/N: 26828	REPLACE	1.00	\$11.20	new	11.20 ✓
35	RACE BALL UPPER 2 P/N: 26830	REPLACE	1.00	\$11.20	new	11.20 ✓
36	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	7.00	14.00 ✓

*36003 *



S/N	Description	Action	Qty	Unit Price	Amount
37	SEAL OIL (20X30X4.5) SHAFT KICK STARTER P/N: 26826	REPLACE	1.00	\$3.70	3.70
38	STAY HEADLAMP P/N: 45750	REPLACE	1.00	\$67.20	67.20
39	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
40	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
41	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
42	SWITCH BRAKE REAR P/N: 26535	REPLACE	1.00	\$15.40	15.40
43	TANK FUEL ASSY (RED) P/N: 54335	REPLACE	1.00	\$550.20	550.20
44	TRANSPORT CHARGES P/N: 07169		1.00	\$56.00	56.00
SUB TOTAL					\$5,483.20
GST @ 7 %					\$383.82
GRAND TOTAL					\$5,867.02

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*36003 *

bizSAFE₃

