



QUOTATION

Customer :

NO. : 36003

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

DATE : 04/04/2020
CLAIM NO. : 11547
POLICY NO. : MC/00792920
FROM : RAYMOND

VEHICLE NO. : FBK2469L
MAKE/MODEL : YAM / YBR125

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 42062	REPLACE	1.00	\$70.00	70.00
2	BEARING STEERING CONE LOWER P/N: 26831	REPLACE	1.00	\$5.60	5.60
3	BRACKET DETACHABLE LOWER (NEW MODEL) P/N: 39055	REPLACE	1.00	\$140.00	140.00
4	BRACKET FOOTREST RH P/N: 45628	REPLACE	1.00	\$116.20	116.20
5	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$179.20	179.20
6	CALIPER BRAKE FRONT ASSY P/N: 45878	REPLACE	1.00	\$390.60	390.60
7	COVER CLUTCH P/N: 26825	REPLACE	1.00	\$128.10	128.10
8	COVER GUIDE AIR RH P/N: 65354	REPLACE	1.00	\$10.70	10.70
9	COVER SIDE LH (BLACK) P/N: 45775	REPLACE	1.00	\$117.60	117.60
10	COWLING FRONT (BLACK) P/N: 50000	REPLACE	1.00	\$282.80	282.80
11	CRASH BAR P/N: 35878	REPLACE	1.00	\$193.20	193.20
12	CROWN HANDLE P/N: 28100	REPLACE	1.00	\$74.40	74.40
13	EMBLEM (YAMAHA) FUEL TANK P/N: 54569	REPLACE	1.00	\$8.40	8.40
14	FOOTREST FRONT P/N: 42064	REPLACE	1.00	\$77.20	77.20

*36003 *

bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
15	FORK FRONT ASSY LH P/N: 53024	REPLACE	1.00	\$532.00	532.00
16	FORK FRONT ASSY RH P/N: 53025	REPLACE	1.00	\$532.00	532.00
17	GASKET CLUTCH COVER P/N: 45295	REPLACE	1.00	\$19.60	19.60
18	GRIP HANDLE LH P/N: 26845	REPLACE	1.00	\$4.20	4.20
19	LABOUR P/N: 06766	Supply/Install	8.00	\$63.00	504.00
20	LAMP SIGNAL FRONT LH P/N: 43344	REPLACE	1.00	\$53.90	53.90
21	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	\$63.00	63.00
22	LEVER CLUTCH P/N: 52644	REPLACE	1.00	\$18.20	18.20
23	LOCK SIDE COVER P/N: 26827	REPLACE	1.00	\$14.00	14.00
24	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$280.00	280.00
25	MIRROR LH P/N: 52645	REPLACE	1.00	\$29.40	29.40
26	MIRROR RH P/N: 46219	REPLACE	1.00	\$29.40	29.40
27	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$96.60	96.60
28	NUT P/N: 21960	REPLACE	1.00	\$5.60	5.60
29	PEDAL BRAKE P/N: 44906	REPLACE	1.00	\$86.80	86.80
30	PIPE EXHAUST ASSY P/N: 26600	REPLACE	1.00	\$350.00	350.00
31	PLATE DISC BRAKE FRONT P/N: 46052	REPLACE	1.00	\$193.20	193.20
32	RACE BALL 1 P/N: 26829	REPLACE	1.00	\$11.20	11.20
33	RACE BALL 1 P/N: 26829	REPLACE	1.00	\$11.20	11.20
34	RACE BALL LOWER 2 P/N: 26828	REPLACE	1.00	\$11.20	11.20
35	RACE BALL UPPER 2 P/N: 26830	REPLACE	1.00	\$11.20	11.20
36	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00

*36003 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
37	SEAL OIL (20X30X4.5) SHAFT KICK STARTER P/N: 26826	REPLACE	1.00	\$3.70	3.70
38	STAY HEADLAMP P/N: 45750	REPLACE	1.00	\$67.20	67.20
39	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
40	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
41	STICKER FUEL TANK	REPLACE	1.00	\$42.00	42.00
42	SWITCH BRAKE REAR P/N: 26535	REPLACE	1.00	\$15.40	15.40
43	TANK FUEL ASSY (RED) P/N: 54335	REPLACE	1.00	\$550.20	550.20
44	TRANSPORT CHARGES P/N: 07169		1.00	\$56.00	56.00
SUB TOTAL					\$5,483.20
GST @ 7 %					\$383.82
GRAND TOTAL					\$5,867.02

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*36003 *

