

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005379/KBA3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100496010

Claimant
Vehicle No : SMH2372S **Insured Vehicle No :** SGZ9733P

Date of Loss: 01/04/2020 Nature of Claim: TP Claim No: 7948231990SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2372S		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Engine No:	2ZR2B50524
Reg. Date:	16/01/2019 (Man. Year: 2018)	Chassis No:	ZYX102143441
Colour:	Metallic Grey	Odometer:	25428 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,501.50	1,625.00	4,876.50	75.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	415.00	995.00	70.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,911.50	2,040.00	5,871.50	74.21
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	7,911.50	1,600.00	6,311.50	79.78
+ GST 7.00/7.00% (S\$)	553.81	112.00	441.81	79.78
Nett Amount (S\$)	8,465.31	1,712.00	6,753.31	79.78
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		2,141.00		
Global Sum Settlement (S\$)		2,100.00		

INSPECTION

Date of Assignment: 23/04/2020

Date Inspected: 24/04/2020 Inspected At:

Kgc Workshop Pte Ltd (HQ)
176 SIN MING DRIVE, SIN MING
AUTOCARE #02-04
Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	1,380.70 F	*930.50 FL
2	1		*FRONT BUMPER SPONGE	Serviceable	279.60 F	*- FL
3	2		*FRONT BUMPER RETAINER	Serviceable	404.40 F	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	485.10 F	*- FL
5	1		*FRONT BUMPER GRILLE	Serviceable	449.00 F	*- FL
6	1		*FRONT LOWER BUMPER	Dented / Cut	486.80 F	*382.10 FL
7	1		*FRONT BUMPER LOWER GRILLE	Serviceable	360.60 F	*- FL
8	1		*EMBLEM	Dented / Scratched	727.40 F	*727.40 FL
9	1		*FRONT EMBLEM GARNISH COVER TRIM	Serviceable	348.80 F	*- FL
10	1		*RADAR SENSOR	Serviceable	860.30 F	*- FL
11	1		*RH FROG LAMP LED	Serviceable	488.80 F	*- FL
12	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
13	1		*SET FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
14	1		*NO.PLATE WITH CASING	Dented	80.00 FS	*45.00 FS
15	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,501.50	2,135.00
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	510.00
Total Parts (\$)	6,501.50	1,625.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS ,INCLUSIVE OF REPLACEMENT PARTS	New	550.00	200.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	400.00	200.00
3	ADAS CALIBRATION & PROGRAMING	New	350.00	0.00
4	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	60.00	15.00
5	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	0.00
Gross Labour Cost (\$\$)			1,410.00	415.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >