

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 2 of 5

Estimate No. : **b1 55075**
Date Estimated : **24/04/2020**
Prepared By : **Han Kwan Yong**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM8898H	WBA7E02040G245210	30/09/2016	730Li	0

DESCRIPTION	QTY	PRIC	VALUE
# RR LH FENDER <i>b1</i>	1	2,933.25	2,933.25
# Reinforcemen <i>?</i>	1	81.65	81.65
# LH REINFORCEMENT PLATE SILL <i>?</i>	1	81.65	81.65
RR LH DOOR ALUMINIUM <i>Join</i>	1	3,042.85	3,042.85
PLASTIC NUT <i>?</i>	5	0.85	4.25
# Carrier, out <i>?</i>	1	221.85	221.85
# SYSTEM LOCK REAR LH (SCA/ZS) <i>?</i>	1	694.00	694.00
BUMP STOP <i>?</i>	10	3.75	37.50
REAR WINDOW GREEN (ESG) <i>?</i>	1	1,276.50	1,276.50
# RR LH DOOR SIDE WINDOW GREEN <i>?</i>	1	261.30	261.30
# LH STRIP DOOR BOTTOM <i>?</i>	1	115.15	115.15
REAR RH DOOR CARRIER <i>?</i>	1	676.55	676.55
RR LH DOOR WINDOW FRAME COVER <i>?</i>	1	551.25	551.25
# REAR RH GASKET ENTRANCE <i>?</i>	1	57.10	57.10
(S/L) DOOR SEAL WITH TEMPLATES <i>?</i>	1	233.05	233.05
RH GASKET B PILLAR BOTTOM <i>?</i>	1	97.05	97.05
CAVITY PROTECTION WAX REMOVER 500ML <i>rec</i>	1	18.45	18.45
BLIND RIVET AVIBVLB <i>rec</i>	25	0.55	13.75
SCREW (SF PLUS M5X15) <i>rec</i>	5	0.55	2.75
(DG/SL) BODY ADHESIVE K5B (195ML) <i>rec</i>	1	331.80	331.80
PUNCH RIVET N5 <i>rec</i>	10	0.55	5.50
(DG) BODYWORK ADHESIVE K5A (50ML) <i>rec</i>	1	114.45	114.45
(DG) CLEANER R1 (100ML) <i>rec</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>rec</i>	2	131.55	263.10
PUNCH RIVET N4 <i>rec</i>	50	0.55	27.50
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>rec</i>	1	27.85	27.85
(S/L) SEAM SEAL 300ML <i>rec</i>	3	33.80	101.40

Total Parts : 11,297.65

Claims OD *3rd Party* / Uninsured losses / Direct Settlement

Regn No _____ Claim No. _____
Date & Time *15/06/2020 @ 1000* Excess \$S _____
Surveyor's Name *RPM* Sign _____
Surveyor's Tel *95010068* Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend *8 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed **1,076.00**
Labour is subject to final approval from Insurance Company **11,297.65**
Parts : _____
Labour Acknowledged by Repairer : 0.00
Excess Signature : 0.00
Date : _____
Total GST @ 7% : 1,776.16

Grand Total : 27,149.81



Mon 15/06 @ 10am

SDM8898H

S&R

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

24 APR 2020

E S T I M A T E

Estimate No. : b1 55075	Page No. : 1 of 5
Date Estimated : 24/04/2020	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Wong Kok Foo 299 Bedok Court #02-07 Bedok South Avenue 3 Singapore 469298	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM8898H	WBA7E02040G245210	30/09/2016	730Li	0

DESCRIPTION	VALUE
To replace rear left door, rear left fender including to knock out rear left wheel house and dented area caused by the accident	5950 6,800.00
To respray rear left door, rear left fender, left roof frame, tail panel, left side running board panel and boot compartment.	3886 4,318.00
To carry out body cavity preservation. (Per panel).	100 118.00
To carry out body cavity preservation. (For cut panel).	451 521.00
To remove and install rear windscreen glass to facilitate the repair job.	574.00
To conduct water leak tests.	75.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	231 271.00
To supply and install rear windscreen solar film.	? 451 531.00
To remove and install fuse box at the rear section to facilitate repairs.	451 531.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 150.00
Total Labour 1:	14,076.00

DESCRIPTION	QTY	PRIC	VALUE
-------------	-----	------	-------