

dealer

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

24 APR 2020

## ESTIMATE

Estimate No. : <b>b1 55075</b>	Page No. : <b>1 of 5</b>
Date Estimated : <b>24/04/2020</b>	
Prepared By : <b>Han Kwan Yong</b>	

<b>- ESTIMATE REPAIR FOR -</b> Wong Kok Foo 299 Bedok Court #02-07 Bedok South Avenue 3 Singapore 469298	<b>- ACCOUNT - 40000</b> Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM8898H	WBA7E02040G245210	30/09/2016	730Li	0

DESCRIPTION	VALUE
To replace rear left door, rear left fender including to knock out rear left wheel house and dented area caused by the accident	<del>5950</del> 6,800.00
To respray rear left door, rear left fender, left roof frame, tail panel, left side running board panel and boot compartment.	<del>3886</del> 4,318.00
To carry out body cavity preservation. (Per panel).	<del>100</del> 118.00
To carry out body cavity preservation. (For cut panel).	<del>451</del> 531.00
To remove and install rear windscreen glass to facilitate the repair job.	<del>574.00</del>
To conduct water leak tests.	<del>75.00</del>
To remove and install boot compartment carpet and garnish to facilitate repairs.	<del>231</del> 271.00
To supply and install rear windscreen solar film.	<del>451</del> 531.00
To remove and install fuse box at the rear section to facilitate repairs.	<del>451</del> 531.00
To check electrical wiring systems and lightings at the rear section for proper function.	<del>150</del> 177.00
Sundries.	? 150.00
<b>Total Labour 1:</b>	<b>14,076.00</b>

DESCRIPTION	QTY	PRIC	VALUE
-------------	-----	------	-------

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : **b1 55075**  
Date Estimated : **24/04/2020**  
Prepared By : **Han Kwan Yong**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SDM8898H</b>	<b>WBA7E02040G245210</b>	<b>30/09/2016</b>	<b>730Li</b>	<b>0</b>

DESCRIPTION	QTY	PRIC	VALUE
# RR LH FENDER <i>b1 ✓</i>	1	2,933.25	2,933.25
# Reinforcemen <i>? xsv ✓</i>	1	81.65	81.65
# LH REINFORCEMENT PLATE SILL <i>? b1 ✓</i>	1	81.65	81.65
RR LH DOOR ALUMINIUM <i>100mm ✓</i>	1	3,042.85	3,042.85
PLASTIC NUT <i>? xsv ✓</i>	5	0.85	4.25
# Carrier, out <i>? xsv ✓</i>	1	221.85	221.85
# SYSTEM LOCK REAR LH (SCA/ZS) <i>? xsv ✓</i>	1	694.00	694.00
BUMP STOP <i>? xsv ✓</i>	10	3.75	37.50
REAR WINDOW GREEN (ESG) <i>? nec ✓</i>	1	1,276.50	1,276.50
# RR LH DOOR SIDE WINDOW GREEN <i>? xsv ✓</i>	1	261.30	261.30
# LH STRIP DOOR BOTTOM <i>? xsv ✓</i>	1	115.15	115.15
REAR RH DOOR CARRIER <i>? xsv ✓</i>	1	676.55	676.55
RR LH DOOR WINDOW FRAME COVER <i>? nec ✓</i>	1	551.25	551.25
# REAR RH GASKET ENTRANCE <i>? nec ✓</i>	1	57.10	57.10
(S/L) DOOR SEAL WITH TEMPLATES <i>? nec ✓</i>	1	233.05	233.05
RH GASKET B PILLAR BOTTOM <i>? nec ✓</i>	1	97.05	97.05
CAVITY PROTECTION WAX REMOVER 500ML <i>nec xsv ✓</i>	1	18.45	18.45
BLIND RIVET AVIBVLB <i>nec ✓</i>	28/30	0.55	16.50
SCREW (SF PLUS M5X15) <i>nec ✓</i>	5	0.55	2.75
(DG/SL) BODY ADHESIVE K5B (195ML) <i>nec ✓</i>	1	331.80	331.80
PUNCH RIVET N5 <i>nec ✓</i>	10	0.55	5.50
(DG) BODYWORK ADHESIVE K5A (50ML) <i>nec ✓</i>	1	114.45	114.45
(DG) CLEANER R1 (100ML) <i>nec ✓</i>	2	26.15	52.30
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>nec ✓</i>	2	131.55	263.10
PUNCH RIVET N4 <i>nec xsv ✓</i>	50	0.55	27.50
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>nec ✓</i>	1	27.85	27.85
(S/L) SEAM SEAL 300ML <i>nec ✓</i>	2/1	33.80	33.80
Total Parts :			<b>11,297.65</b>

Claims OD *3rd Party* / Uninsured losses / Direct Settlement

Regn No \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time *15/06/2020 @ 1000* Excess S\$ \_\_\_\_\_

Surveyor's Name *Rafael* Sign \_\_\_\_\_

Surveyor's Tel *95010068* Authorised Yes/No \_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed



Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No \_\_\_\_\_ PML Yes/No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend *8 days*

Labour is subject to final approval from Insurance Company **1076.00**

Parts : **11,297.65**

Labour Acknowledged by Repairer : **0.00**

Excess Signature: : **0.00**

Date: \_\_\_\_\_

Total GST @ 7% : **1,776.16**

Grand Total : **27,149.81**

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

DSBIB  
/ Burnt  
aked / Burnt  
ed / Burnt  
7/20 R2  
22.5  
OHTSU  
STAYE  
8/8  
8/8  
7/20  
or  
ollision

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Supplementary

Estimate No. : **b1 55075**  
Date Estimated : **24/04/2020**  
Prepared By : **Han Kwan Yong**

**- ESTIMATE REPAIR FOR -**  
**Wong Kok Foo**  
**299 Bedok Court**  
**#02-07 Bedok South Avenue 3**

**Singapore 469298**

**- ACCOUNT - 219**  
**India Int'L Insurance Pte Ltd**  
**64 Cecil Street**  
**#04-05 IOB Building**  
**Singapore 049711**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SDM8898H</b>	<b>WBA7E02040G245210</b>	<b>30/09/2016</b>	<b>730Li</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT <b>nec</b> /	2.10	8.00		16.80
# CLIP BOTTOM PART <b>nec</b> /	4.30	2.00		8.60
# 3M S/F PREMIUM FRONT WINDSCREEN <b>nec</b> /	252.34	1.00		252.34
# LH REINFORCEMENT PLATE C PILLAR <b>bt</b> /	81.65	1.00		81.65
# TORX-BOLT WITH WASHER <b>nec</b> /	1.45	1.00		1.45
# REAR DOOR BRAKE <b>nec</b> /	177.45	1.00		177.45
# RR LH DOOR SIDE WINDOW (ESG) <b>nec</b> /	445.95	1.00		445.95

### # SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	984.24
Total Labour & Parts :	984.24