



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLQ8977Y

Date of Accident : 25 April 2020

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Skytruck Forwarders (S) Pte Ltd

Date : 27 April 2020

Estimate To Repair YP4957H - Mitsubishi FUSO FK62FMZ1RDEB
Chassis No : FK62FMA30243

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	rear licence plate lamp <i>cna</i>	\$ 100.00
02	2 ps	rear licence plate bracket @ \$200.00 <i>sn</i>	\$ 400.00
03	1 pc	rear cross-member <i>R</i>	\$ 500.00
		Less 10 % <i>25%</i>	\$ 1,000.00
			\$ 100.00
			\$ 900.00
SPECIAL NETT ITEMS			
04	2 ps	rear cross-member wooden bar (straight and long) @ \$1200.00 <i>cna</i>	\$ 2,400.00
05	1 pc	rear step wooden bar <i>cna</i>	\$ 300.00
06	1 pc	rear end panel wooden (top) <i>11</i>	\$ 700.00
07	8 ps	rear cross-member wooden bar u-bolt @ \$100.00 <i>11</i>	\$ 800.00
08	20 ps	rear cross-member wooden screw @ \$30.00 <i>11</i>	\$ 600.00
09	1 pc	rear licence plate <i>sn</i>	\$ 50.00
10	1 pc	rear safety bar <i>sn</i>	\$ 1,000.00
11	2 pc	rear safety bar bracket @ \$250.00 <i>del/ym</i>	\$ 500.00
			\$ 6,350.00
LABOUR & MISC. CHARGES			
01		To check electrical lighting concerned.	\$ 100.00
02		To lift-up the rear cargo for facilities repair.	\$ 800.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00
		Putty and spray painting of the affected portion.	\$ 850.00
			\$ 2,500.00
			\$ 9,750.00

04 LK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to total estimation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
24/4/20
27/4/20
wh pre. Aff. rep.
4 days.

P-300
252
P-225
S.N-3414
L-1000
9639
202
3711