

HUP MOTOR TRADING & SERVICE

9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091809

Ref: TP 2992/04/20

Your Ref:

Date: 27th APRIL 2020

MR KEE KIAN KEONG
BLK 196, #06-33
WESTWOOD AVENUE,
SINGAPORE 648153

not allowed
2/s \$5200
4 days.

Estimate cost of repair to TOYOTA ESTIMA AERAS 2.4 (A) S/Wgn - SLF 8056 M

1 pc front bumper	987.10	Dis \$ 1,662.60	
16 pcs front bumper clips		3.90	62.40
2 pcs front bumper o/s & n/s side retainer		82.80	165.60 X
1 pc front bumper reinforcement			401.20
2 pcs front bumper reinforcement o/s & n/s stay		185.00	370.00 X
1 pc front bumper o/s tow bar cover			28.80
1 pc front bumper o/s air scoop garnish			67.90
1 pc front bumper centre lower air scoop grille			231.90
1 pc front bumper centre lower grille moulding chrome			160.30
1 pc front grille			607.60
8 pcs front grille clips		3.90	31.20 X
1 pc front grille top garnish			460.30 X
2 pcs o/s & n/s head lamp assy (HID)		2,223.10	4,446.20
1 pc o/s head lamp bracket			133.50 X
1 pc front o/s fender inner shield			253.80 X
8 pcs front o/s fender inner shield clips		3.90	31.20 X
1 pc front top panel			262.90 X
1 pc front top panel garnish			222.80 X
8 pcs front top panel garnish clips		3.90	31.20 X
2 pcs front o/s & n/s head lamp panel		262.90	525.80 X
8 pcs front engine duct cover clips		3.90	31.20 X
1 pc air cond condenser			1,463.80 X
1 pc front n/s wheel sport rim			1,582.70 X
1 pc front number plate & frame			60.00 40 s.n
1 pc front bumper sponge damper			65.60
		\$	13,360.50
	Less 25%	\$	3,340.13
		\$	10,020.37

To wiring check up & adjust headlight alignment. 60.00 20

To check & adjust front wheel alignment & balancing. 120.00 60

To remove, refix air cond parts & refill R4134 gas. 11 150.00 X

To respray Tuff-Kote on all affected accident parts. 11 120.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front top panel, head lamp panel, wheel house panel, front lower member & necessary parts, to weld, renew & align above parts. 1,550.00 500

\$ 12,020.37

Balance C/F.....

車 貿 易 服 務 MOTOR TRADING & SERVICE

Business Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

TP 2992/04/20

Your Ref: _____

Date: 27th APRIL 2020

KEE KIAN KEONG.,

Balance B/F... \$ 12,020.37

jack, straighten & knocking out front o/s chassis
frame member.

RM 450.00 X

putty & respray painting (Pearl Colour) on all affected
ident parts.


600 1,650.00

\$ 14,120.37

=====

Dollars : Forteen Thousand One Hundred Twenty And Cents Thirty Seven Only.

HUP MOTOR TRADING & SERVICE



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____