



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 8402R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	WINDSHIELD GLASS	BROKEN	846.70	846.70
1	WINDSCREEN PLATE	SERVICEABLE	26.03	-
1	WINDSCREEN RUBBER PAD	NECESSARY	2.04	2.04
1	WINDSCREEN PIN	NECESSARY	3.69	3.69
1	SOLAR FILM (FIAT DOBLO)	NECESSARY	288.87	288.87
1	BONNET	BENT	1,067.55	1,067.55
1	BONNET, HINGE - LH	NOT NECESSARY	99.82	-
1	BONNET, HINGE - RH	NOT NECESSARY	101.84	-
1	HEADLAMP LHS	NOT NECESSARY	1,021.15	-
1	HEADLAMP RHS	CRACKED	1,021.15	1,021.15
1	FRONT BUMPER, TOP	NOT NECESSARY	898.08	-
1	BUMPER BRACKET LHS	SERVICEABLE	35.40	-
1	BUMPER BRACKET RHS	SERVICEABLE	35.40	-
1	FRONT FENDER RHS	TO REPAIR SEE LABOUR	298.80	-
1	BONNET LOCK	SERVICEABLE	175.88	-
1	MOULDING, FR PILLAR - RH	CRACKED	120.08	120.08
1	WIPER ARM RH	SCRATCHED	221.78	221.78
			6,264.26	3,571.86
<u>SPECIAL NETT ITEMS</u>				
1	SEALANT (SN)	NECESSARY	40.00	40.00
1	IU BRACKET (SN)	NECESSARY	20.00	20.00
1	SUNDRIES (SN)	NECESSARY	80.00	30.00
			140.00	90.00
<u>LABOUR</u>				
	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC. INCLUSIVE OF THE REPAIR OF FRONT FENDER RHS.		2,600.00	1,800.00
	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK.		180.00	180.00
	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC.		1,750.00	1,400.00

Report Ref No. CS/LPC20005397/R1qf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX FRONT WINDSCREEN.		200.00	120.00
			4,730.00	3,500.00
GRAND TOTAL			11,134.26	7,161.86

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00
LESS EXCESS			-500.00
NETT LIABILITY			4,500.00

Report Ref No. CS/LPC20005397/R1qf3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.