

REPAIR ESTIMATE

INSURANCE: First Capital

VEHICLE NO.: SHA 3346 H

Description	Qty	List Price	Amount
Bonnet <i>Dented</i>	1	\$ 2,253.80	\$ 2,253.80
Bonnet Hinge (LH/RH) <i>bt</i>	2	\$ 118.70	\$ 237.40
Bonnet Insulator <i>NH</i>	1	\$ 230.10	\$ 230.10
Bonnet Insulator Clips <i>NH</i>	1	\$ 15.00	\$ 15.00
Radiator Grille <i>broken</i>	1	\$ 1,227.50	\$ 1,227.50
Flap Assy Active Air Upper, (LH/RH) <i>N/S broken o/s NH</i>	2	\$ <u>824.60</u>	\$ 1,649.20
Unit Assy-SMART CRU (Radar Sensor) <i>broken</i>	1	\$ 2,910.90	\$ 2,910.90
Flap Assy Active wire <i>NH</i>	1	\$ 765.30	\$ 765.30
Front Number Plate garnish <i>cut/damaged</i>	1	\$ 137.60	\$ 137.60
Front Bumper Cover <i>torn</i>	1	\$ 418.30	\$ 418.30
Front bumper top cover <i>NH</i>	1	\$ 476.30	\$ 476.30
Front Bumper Sponge <i>torn</i>	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement <i>Dented</i>	1	\$ 1,075.10	\$ 1,075.10
Front Bumper Reinforcement ABSORBER (LH/RH) <i>N/S Dented o/s NH</i>	2	\$ <u>186.50</u>	\$ 373.00
Front Bumper Towing Cover <i>NH</i>	1	\$ 29.00	\$ 29.00
Front Bumper Moulding Centre Upper <i>broken</i>	1	\$ 368.50	\$ 368.50
Front Bumper Lower Stiffener <i>bt</i>	1	\$ 285.10	\$ 285.10
Front bumper lower grille <i>broken</i>	1	\$ 365.30	\$ 365.30
front bumper lower grille moulding <i>cut</i>	1	\$ 127.60	\$ 127.60
Front Bumper Lip <i>NH</i>	1	\$ 35.10	\$ 35.10
Front Bumper Bracket Top (LH/RH) <i>NH</i>	1	\$ 35.00	\$ 35.00
Front Bumper Bracket (LH/RH) <i>N/S broken o/s NH</i>	1	\$ <u>28.00</u>	\$ 28.00
Front Bumper Retainer Mounting (LH/RH) <i>NH</i>	1	\$ 65.30	\$ 65.30
Front Bumper Clips 10 pcs <i>NH</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH/RH) <i>N/S cut o/s NH</i>	1	\$ <u>186.90</u>	\$ 186.90
Front bumper air duct (LH/RH) <i>NH</i>	1	\$ 153.80	\$ 153.80
Day Light ,LH <i>broken mounting</i>	1	\$ 642.50	\$ 642.50
Day Light Wire, LH <i>NH</i>	1	\$ 585.50	\$ 585.50
BUZZER ASSY - PIEZO (LH) <i>broken</i>	1	\$ 388.00	\$ 388.00
Headlamp Support Panel Assy <i>broken photo</i>	1	\$ 949.30	\$ 949.30
Headlamp(LH/RH) <i>broken / crack 1198.80 x 2</i>	2	\$ 3,987.30	\$ 7,974.60
Horn Unit (LH/RH) <i>o/s NH N/S 3 crack</i>	2	\$ <u>72.80</u>	\$ 145.60
Horn Wire <i>NH</i>	1	\$ 386.70	\$ 386.70
Radiator Inverter <i>2 bt</i>	1	\$ 884.80	\$ 884.80
Radiator <i>2 bt</i>	1	\$ 710.50	\$ 710.50
COOLANT <i>NH</i>	1	\$ 45.00	\$ 45.00
Radiator fan blower motor assy <i>NH broken</i>	1	\$ 1,226.60	\$ 1,226.60
Radiator Air Guard (LH) <i>broken</i>	1	\$ 76.40	\$ 76.40
Radiator Air Guard, Up <i>NH</i>	1	\$ 127.50	\$ 127.50
Dam-AIR <i>NH</i>	1	\$ 28.00	\$ 28.00
Front Fender(LH) <i>Dented</i>	1	\$ 490.70	\$ 490.70
Front Fender Apron Panel (LH) <i>NH</i>	1	\$ 756.20	\$ 756.20

Front Fender Apron Panel Upper(LH) <i>HH</i>	1	\$ 229.60	\$ 229.60	X
Front Fender Shield (LH) <i>deformed</i>	1	\$ 164.70	\$ 164.70	✓
Air Duct <i>HH</i>	1	\$ 156.80	\$ 156.80	X
air duct hose <i>HH</i>	1	\$ 86.40	\$ 86.40	X
Aircon Condenser <i>to be</i>	1	\$ 663.60	\$ 663.60	X
Front Door Hinge Upper (LH) <i>HH</i>	1	\$ 165.76	\$ 165.76	X
Front Door Hinge Lower (LH) <i>HH</i>	1	\$ 153.70	\$ 153.70	X
Front Door Check (LH) <i>HH</i>	1	\$ 72.98	\$ 72.98	X
Front Wheel Rim (LH) <i>HH</i>	1	\$ 1,124.20	\$ 1,124.20	X
Front Wheel Hub Cap and hub assy (LH) <i>HH</i>	1	\$ 678.50	\$ 678.50	X
Front Shock Absorber(Assy)(LH) <i>HH</i>	1	\$ 372.50	\$ 372.50	X
Front Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 206.90	\$ 206.90	X
Front Drive Shaft (LH) <i>HH</i>	1	\$ 1,136.70	\$ 1,136.70	X
Knuckle Arm (LH) <i>HH</i>	1	\$ 663.60	\$ 663.60	X
Auto Gear Oil <i>HH</i>	1	\$ 163.70	\$ 163.70	X
electronic clutch pump <i>HH</i>	1	\$ 4,386.50	\$ 4,386.50	X
Wiring-ECM <i>crack housing / wire torn</i>	1	\$ 2,872.70	\$ 2,872.70	X

22411.80

SUB TOTAL

\$ 42,377.74

LESS 20%

\$ 8,475.55

17929.44

DISCOUNTED TOTAL

\$ 33,902.19

Front Number Plate <i>disloyal</i>	SN	1	\$ 25.00	\$ 25.00	✓
Front No Plate Trim Cover <i>broken</i>	SN	1	\$ 30.00	\$ 30.00	✓
Emblem-Blue Drive (LH) <i>Hee</i>	SN	1	\$ 26.60	\$ 26.60	✓
Front Door Comfort Logo (LH) <i>svc</i>	SN	1	\$ 75.00	\$ 75.00	X
Front Tyre(LH) <i>HH</i>	SN	1	\$ 216.00	\$ 216.00	X

45.00

SUB TOTAL

\$ 372.60

Labour Charge

Panel Beating	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____	1	\$1,600.00	\$1,600.00	800/-
Spray Painting Charge		1	\$1,200.00	\$1,200.00	700/-
Wiring Charge		1	\$180.00	\$180.00	30/-
Tuff Kote		1	\$180.00	\$180.00	40/-
Towing Charge		1	\$80.00	\$80.00	20/-
Four Wheel Alignment		1	\$120.00	\$120.00	20/-
Remove/Refix Undercarriage (FR)		1	\$400.00	\$400.00	200/-
Re-set Frt ABS System		1	\$200.00	\$200.00	200/-
Remove/Refix Radiator		1	\$90.00	\$90.00	80/-
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00	80/-
Remove/Refix Fuse Box		1	\$120.00	\$120.00	100/-
Remove/Refix Engine		1	\$600.00	\$600.00	100/-
Remove/Refix Dashboard		1	\$350.00	\$350.00	100/-
Front Chassis Alignment Charge		1	\$220.00	\$220.00	100/-
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	320/-

2250.00

TOTAL LABOUR

\$6,020.00

ESTIMATE TOTAL

\$ 40,294.79

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

27/04/2020 e170dm

Nt Antun

P/Pat 9 days.

LKK Auto

20224.44 PTP

Supp 375.32

20599.96

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 30-Apr-20

INSURANCE: First Capital

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 3346 H (S)

Description	Qty	List Price	Amount
Engine Under Cover tom	1	\$ 469.40	\$ 469.40
SUB TOTAL			\$ 469.40
LESS 20%			\$ 93.88
DISCOUNTED TOTAL			\$ 375.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ryan

KK Ando