

Front Fender Apron Panel Upper(LH) <i>HH</i>		1	\$ 229.60	\$ 229.60	X
Front Fender Shield (LH) <i>deformed</i>		1	\$ 164.70	\$ 164.70	X
Air Duct <i>HH</i>		1	\$ 156.80	\$ 156.80	X
air duct hose <i>HH</i>		1	\$ 86.40	\$ 86.40	X
Aircon Condenser <i>ET BT</i>		1	\$ 663.60	\$ 663.60	X
Front Door Hinge Upper (LH) <i>HH</i>		1	\$ 165.76	\$ 165.76	X
Front Door Hinge Lower (LH) <i>HH</i>		1	\$ 153.70	\$ 153.70	X
Front Door Check (LH) <i>HH</i>		1	\$ 72.98	\$ 72.98	X
Front Wheel Rim (LH) <i>HH</i>		1	\$ 1,124.20	\$ 1,124.20	X
Front Wheel Hub Cap and hub assy (LH) <i>HH</i>		1	\$ 678.50	\$ 678.50	X
Front Shock Absorber(Assy)(LH) <i>HH</i>		1	\$ 372.50	\$ 372.50	X
Front Shock Absorber Mounting (LH) <i>HH</i>		1	\$ 206.90	\$ 206.90	X
Front Drive Shaft (LH) <i>HH</i>		1	\$ 1,136.70	\$ 1,136.70	X
Knuckle Arm (LH) <i>HH</i>		1	\$ 663.60	\$ 663.60	X
Auto Gear Oil <i>HH</i>		1	\$ 163.70	\$ 163.70	X
electronic clutch pump <i>HH</i>		1	\$ 4,386.50	\$ 4,386.50	X
Wiring-ECM <i>crack housing / wire torn</i>		1	\$ 2,872.70	\$ 2,872.70	X
SUB TOTAL				\$ 42,377.74	
LESS 20%				\$ 8,475.55	
DISCOUNTED TOTAL				\$ 33,902.19	
Front Number Plate <i>disloyed</i>	SN	1	\$ 25.00	\$ 25.00	X
Front No Plate Trim Cover <i>broken</i>	SN	1	\$ 30.00	\$ 30.00	X
Emblem-Blue Drive (LH) <i>HH</i>	SN	1	\$ 26.60	\$ 26.60	X
Front Door Comfort Logo (LH) <i>SVC</i>	SN	1	\$ 75.00	\$ 75.00	X
Front Tyre(LH) <i>HH</i>	SN	1	\$ 216.00	\$ 216.00	X
SUB TOTAL				\$ 372.60	
Labour Charge					
Panel Beating	<div style="border: 1px solid black; padding: 5px;"> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ </div>	1	\$1,600.00	\$1,600.00	800/-
Spray Painting Charge		1	\$1,200.00	\$1,200.00	700/-
Wiring Charge		1	\$180.00	\$180.00	30/-
Tuff Kote		1	\$180.00	\$180.00	40/-
Towing Charge		1	\$80.00	\$80.00	15/-
Four Wheel Alignment		1	\$120.00	\$120.00	15/-
Remove/Refix Undercarrage		1	\$400.00	\$400.00	15/-
Re-set Frt ABS System		1	\$200.00	\$200.00	15/-
Remove/Refix Radiator		1	\$90.00	\$90.00	15/-
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00	80/-
Remove/Refix Fuse Box		1	\$120.00	\$120.00	50/-
Remove/Refix Engine		1	\$600.00	\$600.00	15/-
Remove/Refix Dashboard		1	\$350.00	\$350.00	180/-
Front Chassis Alignment Charge		1	\$220.00	\$220.00	15/-
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	180/-
TOTAL LABOUR				\$6,020.00	320/-
ESTIMATE TOTAL				\$ 40,294.79	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

27/04/2020 e 1700m
 NT Andrew
 P/Part 7 days.
 LKK Auto

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

INSURANCE: First Capital

DATE: 30-Apr-20

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 3346 H (S)

Description	Qty	List Price	Amount
Engine Under Cover <i>tom</i>	1	\$ 469.40	\$ 469.40
SUB TOTAL			\$ 469.40
LESS 20%			\$ 93.88
DISCOUNTED TOTAL			\$ 375.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

yan

KK Ando

[Handwritten signature]