

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

To: China Taiping Insurance

Address:

Business Reg. No.: 201626438D

6744 0777

6744 2377

Veron

Estimate Quotation

Quotation No	-
Date	24/4/2020
Vehicle No	SGP8758C
Make / Model	Suzuki Swift

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	front bumper <i>Deland</i>		\$ 768.00 <i>523</i>
2 pcs	front bumper side retainer <i>ren</i>	\$ 55.00	\$ 110.00 ✓
1 pc	front bumper reinforcement (top) <i>Best</i>		\$ 248.00 ✓
1 pc	front bumper reinforcement (low) <i>Best</i>		\$ 272.00 ✓
2 pc	front fog lamp <i>cracked RH</i>	\$ 195.00	\$ 390.00 <i>2195</i>
2 pc	front fog lamp garnish <i>cut RH</i>	\$ 85.00	\$ 170.00 <i>85</i>
1 set	front bumper clip <i>ren</i>		\$ 30.00 ✓
1 pc	front grille <i>cracked</i>		\$ 193.00 ✓
2 pc	front bumper lower grille <i>Deland</i>	\$ 72.50	\$ 145.00 ✓
1 pc	front grille "S" emblem <i>ren</i>		\$ 48.00 ✓
2 pc	headlamp <i>RH cracked, LH cracked</i>	\$ 475.00	\$ 950.00 <i>950</i>
1 pc	bonnet <i>Buckled</i>		\$ 587.00 ✓
1 pc	o/s front fender <i>Ren Dented</i>		\$ 285.00 ✓
1 pc	o/s front fender inner garnish <i>ren</i>		\$ 87.00 ✓
1 set	o/s front fender inner garnish clip <i>ren</i>		\$ 30.00 ✓
2 pcs	front bumper lower spoiler <i>Deland RH</i>	\$ 455.00	\$ 910.00 <i>300/su</i>
1 pc	aircon condenser <i>ren</i>		\$ 570.00 ✓
1 pc	condenser bracket <i>ren</i>		\$ 47.00 ✓
1 pc	lower air resonator <i>ren</i>		\$ 85.00 ✓
1 pc	front support panel <i>Buckled</i>		\$ 655.00 ✓
1 pc	front lock top garnish <i>ren</i>		\$ 72.00 ✓
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 1,000.00 <i>700</i>
2	to putty and spray painting on affected area		\$ 800.00 <i>700</i>
3	anti rust		\$ 150.00 <i>80</i>
4	R&R wiring		\$ 80.00 <i>30</i>
5	R&R aircon		\$ 120.00 ✓
	Subtotal:		\$ 8,802.00

Adrian
2/5 27/04/20

06 Days

BEST SOLUTION AUTOCARE PTE LTD

Total: 558710

A/S: AIC (Nett Value)

CLOSE: 26/6/2020

Authorised Signature

