



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 8622C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID	BENT	1,240.00	1,240.00
1	REAR BUMPER	BUCKLED	1,120.00	570.00
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	38.00	-
1	REAR BUMPER BEAM	NO SUCH PARTS	340.00	-
1	REAR BUMPER REFLECTOR	SERVICEABLE	45.00	-
1	REAR BOOTLID EMBLEM	NECESSARY	40.00	40.00
1	REAR BOOTLID EMBLEM	NECESSARY	55.00	55.00
	LESS 20% DISCOUNT		-575.60	-
	LESS 25% DISCOUNT		-	-476.25
			2,302.40	1,428.75
<u>SPECIAL NETT ITEMS</u>				
2	REVERSE SENSORS @\$280.00 (SN)	SHORTED	560.00	220.00
			560.00	220.00
<u>LABOUR</u>				
	SPRAY PAINTING.		500.00	450.00
	LABOUR TO RENEW ABOVE PARTS.		600.00	500.00
			1,100.00	950.00
GRAND TOTAL			3,962.40	2,598.75

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00
---	--	--	-----------------

Report Ref No. CS/TP20005414/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.