



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

R C AUTO

Ref : CS/TP20005414/Kqf3e2

BLK 18 SIN MING INDUSTRIAL ESTATE
SECTOR A #01-43 SINGAPORE 575676

Date : 27-05-2020



Code : TP393

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLK 8622C
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	24/04/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDGG20W90J006366	Colour	METALLIC MAROON
Odometer	83685	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	8 mm
L/H Front Tyre	195/65 R15	MICHELIN	8 mm
R/H Rear Tyre	195/65 R15	MICHELIN	8 mm
L/H Rear Tyre	195/65 R15	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/04/2020	Inspection Date	24/04/2020
Survey held at	R C AUTO BLK 18 SIN MING INDUSTRIAL ESTATE SECTOR A #01-43 SINGAPORE 575676		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------