

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SKL9192B

Not Authorised
11 Rep &?
Recovery After Paint
4 days

No.	Qty	List Items		
			<i>Buc / mgum</i>	
1	1	Front bumper (AMG)	\$ 1,951.00	✓
2	2	Front bumper parking sensor	\$ 612.00	?
3	1	Front bumper RH tow cover	\$ <i>sn</i> 51.00	X
4	1	Front bumper RH fog lamp grille	\$ 80.00	?
5	1	Front bumper centre grille	\$ <i>sn</i> 151.00	X
6	1	Front bumper number plate garnish	\$ <i>nd</i> 159.00	✓
7	1	Front bumper RH side retainer	\$ <i>di</i> 92.00	✓
8	1	Front bumper inner reinforcement	\$ 489.00	?
9	1	Front bumper inner foam	\$ 192.00	?
10	1	RH headlamp	<i>mg</i> <i>cm</i> \$ 3,654.00	✓
11	1	Front grille	\$ 879.00	?
12	1	Front RH fender	\$ <i>n</i> 1,035.00	X
			\$ 9,345.00	
		Less 10%	\$ 934.50	
		Total :	\$ 8,410.50	
		<u>Special Nett Items</u>		
13	1	Front number plate	\$ <i>cm</i> 50.00	<i>45sn</i>
14	1	Front bumper lower carbon fiber skirting (AMG)	\$ <i>cm</i> 1,500.00	✓
		Total :	\$ 1,550.00	
		<u>Labour</u>		
1		Labour Charges for remove/refit, panel beating, cutting	\$ 700.00	<i>500l</i>
		welding and replacement of damages.		
2		To putty and spray Spray Paintings charges.	\$ 800.00	<i>500l</i>
3		To check wirings/re-install & reset front parking sensors.	\$ 80.00	<i>60l</i>
4		To apply anti rust treatment	\$ <i>nn</i> 50.00	X
		Total :	\$ 1,630.00	
		Total Parts and Labour :	\$ 11,590.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: