

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SKL9192B

\$9,255.42

Not Authorised
11 Rep &?
Recovery After Paint
4 days

No.	Qty	List Items		
1	1	Front bumper (AMG)	Buc / mgum 1,951.00 ✓	
2	2	Front bumper parking sensor	\$ 612.00 ✓	ad q shen ✓ 285.00 X 2
3	1	Front bumper RH tow cover	\$ sm 51.00 X	
4	1	Front bumper RH fog lamp grille	\$ SVC 80.00 X	
5	1	Front bumper centre grille	\$ sm 151.00 X	
6	1	Front bumper number plate garnish	\$ na 159.00 ✓	102.50
7	1	Front bumper RH side retainer	\$ DII 92.00 ✓	
8	1	Front bumper inner reinforcement	\$ BENT 489.00 ✓	392.30
9	1	Front bumper inner foam	\$ CRACM 192.00 ✓	
10	1	RH headlamp	mg cam 3,654.00 ✓	
11	1	Front grille	na 5/11 879.00 ✓	680.00
12	1	Front RH fender	\$ n 1,035.00 X	
			\$ 9,345.00	
		Less 10%	\$ 934.50	
		Total :	\$ 8,410.50	

		Special Nett Items		
13	1	Front number plate	\$ CM 50.00 45sm	
14	1	Front bumper lower carbon fiber skirting (AMG)	\$ CM 1,500.00 ✓	1,280.00
		Total :	\$ 1,550.00	

		Labour		
1		Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 700.00 500l	
2		To putty and spray Spray Paintings charges.	\$ 800.00 500l	
3		To check wirings/re-install & reset front parking sensors.	\$ 80.00 60l	
4		To apply anti rust treatment	\$ na 50.00 X	
		Total :	\$ 1,630.00	

Total Parts and Labour : \$ 11,590.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: