

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20005437/AEA3Q2**Date:** 23/05/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLF1449J	Insured Vehicle No :	SHC3931H
Date of Loss:	20/02/2020	Nature of Claim:	TP
		Claim No:	MCT20020471

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF1449J	Engine No:	HR15118284B
Make & Model:	NISSAN LATIO, 1.5 L (A)	Chassis No:	JN1BAAC11Z0021681
Reg. Date:	11/11/2009 (Man. Year: 2009)	Odometer:	110603 km
Colour:	Gold		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,756.40	813.87	942.53	53.66
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	550.00	350.00	200.00	36.36
Paintwork Labour	400.00	400.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,717.40	1,574.87	1,142.53	42.04
Approved Total (Overridden) (\$\$)		1,250.00		
(\$\$)	2,717.40	1,250.00	1,467.40	54.00
+ GST 7.00/7.00% (\$\$)	190.22	87.50	102.72	54.00
Nett Amount (\$\$)	2,907.62	1,337.50	1,570.12	54.00
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	30/04/2020	Present Location:	Progressive Car Care Pte Ltd (HQ)
Date Inspected:	28/04/2020	Inspected At:	Progressive Car Care Pte Ltd (HQ)
			Blk 3022A Ubi Road 1, #01-45/46
			Singapore 408716
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2022)
Parts:	143	NISSAN LATIO 1.5 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF1449J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER	Deformed	465.30 F	*465.30 FL
2	10	NA	*FRONT BUMPER CLIPS	Necessary	44.00 F	*44.00 FL
3	1	NA	*FRONT BUMPER SIDE HOLDER - RH	Not Necessary	23.00 F	*- FL
4	1	NA	*FRONT BUMPER SIDE HOLDER - LH	Necessary	23.00 F	*23.00 FL
5	1	NA	*FRONT BUMPER FOG LAMP COVER - LH	Not Necessary	95.90 F	*- FL
6	1	NA	*FRONT BUMPER TOWING COVER - LH	Not Necessary	23.20 F	*- FL
7	1	NA	*FRONT BUMPER CENTRE GRILLE	Not Necessary	0.00 F	*- FL
8	1	NA	*FRONT BUMPER FOAM	Not Necessary	215.30 F	*- FL
9	1	NA	*FRONT BUMPER REINFORCEMENT	Not Necessary	446.30 F	*- FL
10	1	NA	*HEADLAMP - LH	Cut	372.00 F	*372.00 FL
11	11	NA	*GRILLE TOP CLIPS	Not Necessary	48.40 F	*- FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$\$)	1,756.40 904.30
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 90.43
					Total Parts (\$\$)	1,756.40 813.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	400.00	400.00
<u>Labour Items</u>				
2	TO CHECK WIRING	New	20.00	20.00
3	TO TUFF-KOTE	New	30.00	30.00
4	TO KNOCK OUT DENTS; REMOVE & REPLACE ACCIDENT PARTS	New	500.00	300.00
Gross Labour Cost (\$\$)			950.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >