

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17000184/KPA3Q2
-1
Date: 17/09/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd	Policy No:	GA049815
Claimant		
Vehicle No : SJU102K	Insured Vehicle No :	SJM6492L
Date of Loss: 25/12/2016	Nature of Claim:	TP
	Claim No:	C0415213

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU102K		
Make & Model:	CITROEN GRAND C4 PICASSO, 1.6 D e-HDi ETG6 Intensive (A)	Engine No:	HIDDEN
Reg. Date:	01/10/2011 (Man. Year: 2011)	Chassis No:	VF7UA5FV8BJ699459
Colour:	White	Odometer:	103333 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50Z R17	Rear Tyre Size:	215/50Z R17
Front Left Side:	Verenti 8 mm	Rear Left Side:	Verenti 8 mm
Front Right Side:	Verenti 8 mm	Rear Right Side:	Verenti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,935.00	4,179.60	3,755.40	47.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,595.00	1,295.00	1,300.00	50.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,530.00	5,474.60	5,055.40	48.01
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	10,530.00	3,300.00	7,230.00	68.66
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,623.00		
Global Sum Settlement (S\$)		3,300.00		

INSPECTION

Date of Assignment:	04/01/2017	
Date Inspected:	04/01/2017 Inspected At:	Autoworx House (HQ) 111 North Bridge Road, #21-01 Peninsula Plaza Singapore 179098
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2019)
Parts:	M1-MPV	CITROEN GRAND C4 PICASSO 1.6 D e-HDi ETG6 Intensive (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU102K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Serviceable	1,070.00 F	*- FL
2	1		*FRONT BUMPER FOG LAMP COVER	Serviceable	460.00 F	*- FL
3	1		*FRONT FENDER (CONSISTENT)	Repair	656.00 F	*- FL
4	1		*FRONT FENDER STICKER PICASSO (CONSISTENT)	Necessary	89.00 F	*89.00 FL
5	1		*FRONT DOOR (CONSISTENT)	Dented / Warped	1,070.00 F	*1,070.00 FL
6	1		*FRONT DOOR PROTECTOR (CONSISTENT)	Necessary	340.00 F	*340.00 FL
7	1		*FRONT BUMPER FOG LAMP COVER CHROME MOULDING (CONSISTENT)	Serviceable	175.00 F	*- FL
8	1		*FRONT DOOR SIDE MIRROR ASSY (CONSISTENT)	Cracked	1,077.00 F	*1,077.00 FL
9	1		*FRONT ALLOY RIM (CONSISTENT)	Dented	680.00 F	*680.00 FL
10	1		*FRONT ALLOY RIM COVER (CONSISTENT)	Dented / Cut	180.00 F	*180.00 FL
11	1		*FRONT LOWER ARM (CONSISTENT)	Serviceable	315.00 F	*- FL
12	1		*FRONT SHOCK ABSORBER (CONSISTENT)	Bent	478.00 F	*478.00 FL
13	1		*FRONT KNUCKLE ARM (CONSISTENT)	Bent	560.00 F	*560.00 FL
14	1		*FRONT WHEEL BEARING (CONSISTENT)	Necessary	170.00 F	*170.00 FL
15	1		*FRONT WHEEL HUB (CONSISTENT)	Serviceable	240.00 F	*- FL
16	1		*FRONT STEERING TIE ROD (CONSISTENT)	Serviceable	215.00 F	*- FL
17	1		*FRONT STEERING ROD END BALL JOINT (CONSISTENT)	Serviceable	160.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,935.00	4,644.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	464.40
Total Parts (\$\$)	7,935.00	4,179.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	860.00	450.00
2	TO CHECK WIRING SYSTEM AND REPAIR WIRING SYSTEM	New	50.00	15.00
3	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	100.00	30.00
4	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	680.00
5	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT	New	85.00	60.00
6	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	300.00	60.00
Gross Labour Cost (S\$)			2,595.00	1,295.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >