

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Feb 2020 Edit Reg		27 Apr 2020 00:00 Edit Adj Rpt	S\$2,272.72 Edit Estimates	S\$2,272.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -									
Main Claimant: TAN GIM KUAY , ID: S7609998G									
Vehicle Reg. No.:	SLR2356Z	Date of Loss:	07/12/2019 10:00 - :59 [28 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19120152	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA4015G	Policy No. (Claimant):	PNPV2018-00009711-01						
		Excess:							
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 30/04/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
III_SG (27/05/2020): Alert - Adj Mandate Approved (S\$2781.81) - SLR2356Z - Claim Handler: Priya									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR2356Z (MCT19120152)
[SHA4015G]
TP
TAN GIM KUAY
Dec 7 2019 10:00AM
[COMFORT TRANSPORTATION PTE LTD]
ETHOZ Protect Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser ▼

Video					1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print	
1	29/04/20 09:44	Video - Accident-IV		Load MP4		

Photos / Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	18/12/19 18:30	General View		Load JPG	☒	
2	18/12/19 18:30	General View		Load JPG	☒	
3	18/12/19 18:30	General View		Load JPG	☒	
4	18/12/19 18:30	General View		Load JPG	☒	
5	18/12/19 18:30	General View		Load JPG	☒	
6	18/12/19 18:30	Odometer Reading		Load JPG	☒	
7	18/12/19 18:30	Chassis Number		Load JPG	☒	
8	18/12/19 18:30	General View		Load JPG	☒	
9	18/12/19 18:30	General View		Load JPG	☒	
10	18/12/19 18:30	General View		Load JPG	☒	
11	18/12/19 18:30	General View		Load JPG	☒	
12	18/12/19 18:30	General View		Load JPG	☒	
13	18/12/19 18:30	General View		Load JPG	☒	
14	18/12/19 18:30	General View		Load JPG	☒	
15	18/12/19 18:30	General View		Load JPG	☒	
16	18/12/19 18:30	General View		Load JPG	☒	
17	18/12/19 18:30	General View		Load JPG	☒	
18	18/12/19 18:30	General View		Load JPG	☒	
19	18/12/19 18:30	General View		Load JPG	☒	
20	13/02/20 19:12	Reinspection Photo		Load JPG	☒	
21	13/02/20 19:12	Reinspection Photo		Load JPG	☒	
22	13/02/20 19:12	Reinspection Photo		Load JPG	☒	
23	13/02/20 19:12	Reinspection Photo		Load JPG	☒	
24	13/02/20 19:12	Reinspection Photo		Load JPG	☒	
25	13/02/20 19:12	Reinspection Photo		Load JPG	☒	
26	13/02/20 19:12	Reinspection Photo		Load JPG	☒	
27	13/02/20 19:12	Reinspection Photo		Load JPG	☒	
28	13/02/20 19:12	Reinspection Photo		Load JPG	☒	

Documentation					1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	27/05/20 11:01	Marked Estimate		Load PDF		
2	18/06/20 17:53	TP GIA REPORT		Load PDF		
3	24/06/20 10:29	INVOICE NO DATED 17.02.2020		Load PDF		
4	24/06/20 10:48	Authorisation to Act		Load PDF		
5	24/06/20 10:48	DISCHARGE VOUCHER		Load PDF		
6	24/06/20 10:48	GIA SEARCH		Load PDF		
7	24/06/20 10:48	LOD		Load PDF		
8	24/06/20 10:48	RENTAL RECEIPT		Load PDF		

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
9	24/06/20 10:48	WORKSHOP INVOICE		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	17/12/19 09:14	Singapore Accident Statement		Load PDF	
2	27/04/20 10:47	Letter of Demand from Third Party TPD LOD FROM ETHOZ GROUP LIMITED (SLR2356Z)		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III19022076/EKA3S2-1**Date:** 24/06/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLR2356Z	Insured Vehicle No :	SHA4015G
Date of Loss:	07/12/2019	Nature of Claim:	TP
		Claim No:	MCT19120152

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR2356Z	Engine No:	G4FGHU687104
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU527321
Reg. Date:	07/08/2017 (Man. Year: 2017)	Odometer:	35743 km
Colour:	Beige		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,160.64	1,482.72	1,677.92	53.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,275.00	790.00	485.00	38.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,435.64	2,272.72	2,162.92	48.76
+ GST 7.00/7.00% (S\$)	310.49	159.09	151.40	48.76
Nett Amount (S\$)	4,746.13	2,431.81	2,314.32	48.76
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		2,781.81		

INSPECTION

Date of Assignment:	27/04/2020		
Date Inspected:	18/12/2019	Inspected At:	Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2020)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR2356Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH (NPA)	Not Necessary	0.00 FL	*- FL
2	1		*REAR DOOR RH	Dented	1,775.20 FL	*1,775.20 FL
3	1		*REAR DOOR HINGE RH (UPPER)	Not Necessary	59.40 FL	*- FL
4	1		*REAR DOOR HINGE RH (LOWER)	Not Necessary	59.40 FL	*- FL
5	1		*SET REAR DOOR STICKER RH (BLACK)	Necessary	78.20 FL	*78.20 FL
6	1		*REAR DOOR GLASS REGULATOR RH	Not Necessary	299.10 FL	*- FL
7	1		*REAR DOOR GLASS REGULATOR MOTOR RH	Not Necessary	246.70 FL	*- FL
8	1		*REAR DOOR PROTECTOR STICKER RH	Not Necessary	39.10 FL	*- FL
9	1		*REAR DOOR LOCK RH	Not Necessary	314.50 FL	*- FL
10	1		*REAR DOOR TRIMBOARD RH	Not Necessary	891.70 FL	*- FL
11	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
12	1		*REAR SPORT RIM RH	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,913.30	1,853.40
- List Item Discount on L Items 20.00/20.00% (\$)	752.66	370.68
Total Parts (\$)	3,160.64	1,482.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR.	New	500.00	300.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.	New	35.00	20.00
3	TO SPRAY PAINT ON AFFECTED AREAS.	New	600.00	400.00
4	TO TRANSFER REAR DOOR RH FITTING.	New	100.00	50.00
5	SPRAY RUST PROOF ON AFFECTED AREA.	New	40.00	20.00
Gross Labour Cost (\$)			1,275.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >