

Steve (LKK)
83778813

18/12/19, 12:00pm
TNA N/A
3 days
P/P

Ry DPL S/T

[Signature]
3/12/19

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 14/12/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN GIM KUAY
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009711

Accident Date : 07/12/2019

Vehicle No : SLR-2356-Z

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	FRT DOOR RH X <i>AIN</i>	RESTORE	
1	REAR DOOR RH / <i>00</i>	1,775.20	/
1	REAR DOOR HINGE RH (UPPER) X <i>AIN</i>	59.40	
1	REAR DOOR HINGE RH (LOWER) X <i>AIN</i>	59.40	
1	REAR DOOR STICKER RH (SET)(BLACK) / <i>REC</i>	78.20	/
1	REAR DOOR GLASS REGULATOR RH ? X <i>AIN</i>	299.10	X
1	REAR DOOR GLASS REGULATOR MOTOR RH X <i>AIN</i>	246.70	
1	REAR DOOR PROTECTOR STICKER RH X <i>AIN</i>	39.10	
1	REAR DOOR LOCK RH X <i>AIN</i>	314.50	

185340
-20%
148272

Date : 14/12/2019

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : TAN GIM KUAY

: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009711

Accident Date : 07/12/2019

Vehicle No : SLR-2356-Z

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR DOOR TRIMBOARD RH <i>X NN</i>	891.70	
1	REAR FENDER RH <i>X R</i> RESTORE		
	Sub Total	3763.30	
	Discount 20% On Parts	(752.66)	
	<u>Special Nett Item</u>		
1	REPAIR - REAR SPORT RIM RH <i>X NN</i>	150.00	
	Sub Total	150.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILIATE REPAIR	<i>300</i> 500.00	
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	<i>20</i> 35.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ETHOZ

Date : 14/12/2019

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : TAN GIM KUAY
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009711

Accident Date : 07/12/2019

Vehicle No : SLR-2356-Z

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO SPRAY PAINT ON AFFECTED AREAS	400 / 600.00	
	TO TRANSFER REAR DOOR RH FITTING	50 / 100.00	
	SPRAY RUST PROOF ON AFFECTED AREA	20 / 40.00	
	Sub Total	1275.00	790

P- 1482.72
L- 790
2272.72

4,435.64

Remarks:

SUB TOTAL

GST 7.0 % 310.49

TOTAL 4,746.13

Surveyor's name: _____

Principal's name: TAN GIM KUAY

Survey Date & Time: _____

PAGE : 3

Date : 13/02/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : TAN GIM KUAY

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009711

Accident Date : 07/12/2019

Vehicle No : SLR-2356-Z

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	FRT DOOR RH RESTORE	0.00	0.00
1	REAR DOOR RH	1775.20	1775.20
1	REAR DOOR HINGE RH (UPPER)	59.40	0.00
1	REAR DOOR HINGE RH (LOWER)	59.40	0.00
1	REAR DOOR STICKER RH (SET)(BLACK)	78.20	78.20
1	REAR DOOR GLASS REGULATOR RH	299.10	0.00
1	REAR DOOR GLASS REGULATOR MOTOR RH	246.70	0.00
1	REAR DOOR PROTECTOR STICKER RH	39.10	0.00
1	REAR DOOR LOCK RH	314.50	0.00
1	REAR DOOR TRIMBOARD RH	891.70	0.00
1	REAR FENDER RH RESTORE	0.00	0.00



Date : 13/02/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : TAN GIM KUAY

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009711

Accident Date : 07/12/2019

Vehicle No : SLR-2356-Z

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	3763.30	1853.40
	Discount 20% On Parts (0.00)	(752.66)	(370.68)
Special Nett Item			
1	REPAIR - REAR SPORT RIM RH	150.00	0.00
	Sub Total	150.00	0.00
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	500.00	300.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	20.00
	TO SPRAY PAINT ON AFFECTED AREAS	600.00	400.00
	TO TRANSFER REAR DOOR RH FITTING	100.00	50.00
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	20.00

PAGE : 2

ETHOZ

Date : 13/02/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : TAN GIM KUAY

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009711

Accident Date : 07/12/2019

Vehicle No : SLR-2356-Z

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	1275.00	790.00

Sub Total	4,435.64	2,272.72
GST 7.0 %	310.49	159.09
Total	4,746.13	2,431.81

CCR - \$2,272.72 (PART BY PART)

3 DAYS REPAIR

Surveyor Name : STEVEN LEONG - LKK PARTS - \$1,853.40 - 20%

Date & Time : 18/12/2019 12:00:00 PM - \$1,482.72

Lee Chen Sin LABOUR - \$790.00

CLAIM DEPARTMENT

DID : 66547520

FAX :

PAGE : 3

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Feb 2020 08:54 Edit Reg		16 Dec 2019 00:00 Edit Adj Rpt	S\$2,272.72 Edit Estimates	S\$2,272.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: TAN GIM KUAY , ID: S7609998G									
Vehicle Reg. No.: SLR2356Z		Date of Loss: 07/12/2019 10:00 - :59 [28 Months From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHA4015G		Policy No. (Claimant):							
		Excess:							
Repairer: Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 26/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									