



Section A - Accident Details

Registration Number	SHB1861U
Case Reference Number	TAX/04/20/2023
Registration Date	16/7/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	WANG BOON YEOW (YUAN WENYAO)
Type of Accident	Side Swipe
Accident Date and Time	26/4/2020 2:35 PM
Accident Reported Date and Time	27/4/2020 11:14 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	27/4/2020 3:25 AM
Replacement Vehicle issued?	No
Job Card Number	24106706
Special Instruction to ARC, if any	TP/ RIGHT PORTION
Prepared Date and Time	27/4/2020 11:43 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,314.00	\$200.00
Total Spare Part Cost	\$2,372.56	\$71.52
Total Other Cost	\$805.32	\$148.44
TOTAL COST	\$4,998.88	\$619.96
Lump Sum Total	\$5,000.00	\$600.00 (L/S)
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / ERGO
ARC / Surveyor Sign Off Date	28/04/2020 4:52 PM	28/04/2020 3:49 PM
Signature		
Remarks		L/S, after paint

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2005-0107	Invoice Number	
Quotation Date	11.05.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
RESPRAY MIRROR COVER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,314.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$445.32	\$148.44
Total Other Costs	\$805.32	\$148.44

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		87910-47330	MIRROR ASSY,RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given X
		81730-52090	MIRROR LAMP RH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given X
		879157-4010	COVER, OUTER MIRROR, RH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given X
		67003-47080	DOOR RR/RH	0.00	\$954.50	0.00	\$0.00	Replace	Not Given X
		61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair R
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace
		65637-47021	FENDER LINE RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given X
		52159-47905	BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given X
		90467-07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace
Total					\$3,892.50		\$89.40		

89.40 /
-20 %
71.52 /
+200.00 /
+348.44 /
619.96

45 \$600 /
2 days

Nec
Nec

Nec