



## Case Details

Case Reference Number : TAX/04/20/2023  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB1861U

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-11297-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : ERGO Insurance Pte Ltd  
 Accident Date and Time : 26/04/2020 06:35 AM  
 Vehicle Age(In Months) : 69

## Documents / Photographs

View Documents / Photographs

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MIRROR ASSY,RH	1	1,307.10	1,307.10	25.00	980.32	Replace	0	0	Not Given	X Svc
One Time Key In	Main			MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Given	X Svc
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Given	X Svc
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	0	0	Not Given	X Svc
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair	X R
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ Nec
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ Nec
One Time Key In	Main			FENDER LINE RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Given	X Svc
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	0	0	Not Given	X Svc
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	0	0	Not Given	X Svc

Total Spare Part Cost 3,025.70

Surveyor Total 149.40

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 2,420.56

Final Sur Total 119.52

SMRT Recommendation											Surveyor Approval			
SM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	1	120.00 60.00	Replace	Nec.

Total Spare Part Cost 3,025.70

Surveyor Total 149.40

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 2,420.56

Final Sur Total 119.52

#### Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	507.00	200	
Total:			507.00	200.00	

#### Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR FENDER RH	378.00	200	
2	Main	TO RESPRAY REAR DOOR RH	378.00	0	
3	Main	TO RESPRAY REAR BUMPER	378.00	0	
4	Main	RESPRAY MIRROR COVER RH	180.00	0	
Total:			1,314.00	200.00	

#### Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPLACE SUNDRY PARTS	100.00	0	
2	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
4	Main	TO WASH AND VACUUM	60.00	0	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	445.32	148.44	Nec
Total:			805.32	148.44	

## Summary

Estimator Assessment(\$)

Surveyor Assessment(\$)

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,420.88	119.62
Total Labour Cost	507.00	200.00
Total Spray Painting	1,314.00	200.00
Other	805.32	148.44
Overall Total	5,048.88	667.96
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	5,050.00	650.00
Surveyor Approved Amount		650.00
No of Repair Days*	5	2 <i>2 days</i>
Remarks		L/S, after paint
Surveyor Name		Sun Pin (LKK)
Signature		
Survey Date	28/04/2020	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: