

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20005447/KEA3Q2**Date:** 14/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993973
Claimant Vehicle No :	SGC6K	Insured Vehicle No :	SGH4401A
Date of Loss:	23/04/2020	Nature of Claim:	TP
		Claim No:	7024864201SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC6K		
Make & Model:	TOYOTA C-HR, 1.2 (A)	Engine No:	8NRU084707
Reg. Date:	29/12/2017 (Man. Year: 2017)	Chassis No:	NGX502007611
Colour:	Metallic Pearl White	Odometer:	21950 km
Engine Capacity:	1196 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R16	Rear Tyre Size:	225/50 R16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,671.50	717.75	2,953.75	80.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	860.00	1,640.00	65.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,171.50	1,577.75	4,593.75	74.43
Approved Total (Overridden) (\$\$)		1,250.00		
(\$\$)	6,171.50	1,250.00	4,921.50	79.75
+ GST 7.00/7.00% (\$\$)	432.01	87.50	344.51	79.75
Nett Amount (\$\$)	6,603.51	1,337.50	5,266.01	79.75
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	28/04/2020	
Date Inspected:	29/04/2020	Inspected At: MBM Wheelpower Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-15, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT FENDER SUB-ASSY	Bent	850.00 FL	*850.00 FL
2	1		*RH FRONT FENDER LINER	Serviceable	250.00 FL	*- FL
3	1		*RH FRONT FENDER APRON SUB-ASSY	Repair	980.00 FL	*- FL
4	1		*RH FRONT FENDER SIDE PANEL PROTECTOR	Dented	107.00 FL	*107.00 FL
5	1		*RH FRONT SIDE PANEL BRACKET	Repair	70.00 FL	*- FL
6	1		*RH FRONT SUB-ASSY	Repair	1,400.00 FL	*- FL
7	1		*RH FRONT DOOR UPPER HINGE ASSY	Repair	90.00 FL	*- FL
8	1		*RH FRONT DOOR LOWER HINGE ASSY	Repair	90.00 FL	*- FL
9	1		*RH FRONT DOOR WEATHERSTRIP	Serviceable	190.00 FL	*- FL
10	1		*RH FRONT DOOR REAR OUTSIDE SEAL	Serviceable	50.00 FL	*- FL
11	1		*RH FRONT DOOR OUTSIDE STRIPE	Serviceable	50.00 FL	*- FL
12	1		*RH FRONT DOOR NO.4 STRIPE	Not Necessary	40.00 FL	*- FL
13	1		*RH WHEEL ARCH BLACK GARNISH	Serviceable	195.00 FL	*- FL
14	1		*BODY SEALANT	Not Necessary	200.00 FS	*- FS
15	1		*DOOR TAPE	Not Necessary	200.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	4,762.00 957.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,090.50 239.25
					Total Parts (\$\$)	3,671.50 717.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REFIT & REPAIR AFFECRED DAMAGED PARTS ,INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,200.00	400.00
2	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	100.00	20.00
3	TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW DOOR /FACILITATE REPAIR	New	100.00	0.00
4	TO REMOVE,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	100.00	0.00
5	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	440.00
Gross Labour Cost (\$)			2,500.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >