

2

AlGAsia Insured's Veh No : SJP2468T
Date of Accident : 28 April 2020


陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Kek Siew Sin

Date : 30 April 2020

Estimate To Repair SMH6984A - Mercedes Benz E200 AVG (R18 LED)
Chassis No : WDD2130422A578313

S/No	Quantity	Description	Amount
NETT ITEMS			
01	1 pc	bonnet ✓	\$ 2,200.00
02	2 ps	bonnet hinge @ \$185.00 ✓	\$ 370.00
03	2 ps	bonnet hinge actuator @ \$190.00 ✓	\$ 380.00
04	1 pc	n/s front fender ✓	\$ 945.00
05	1 pc	n/s front fender inner cowling ✓	\$ 270.00
06	6 ps	n/s front fender inner cowling clips @ \$7.00 ✓	\$ 42.00
07	1 pc	front bumper ✓	\$ 1,200.00
08	1 pc	front bumper centre moulding ✓	\$ 105.00
09	1 pc	front bumper mounting n/s ✓	\$ 65.00
10	1 pc	front bumper absorber foam ✓	\$ 160.00
11	1 pc	front bumper side retainer n/s ✓	\$ 12.00
12	1 pc	front bumper engine lower cover centre ✓	\$ 230.00
13	1 pc	front bumper engine lower cover n/s ✓	\$ 85.00
14	1 pc	front bumper parking sensor n/s ✓	\$ 250.00
15	1 pc	n/s headlamp ✓	\$ 3,180.00
16	1 pc	n/s headlamp control unit ✓	\$ 630.00
17	1 pc	n/s headlamp bracket ✓	\$ 28.00
18	1 pc	n/s front wheel rim ✓	\$ 1,050.00
Less 10 %			\$ 11,202.00
			\$ 1,120.20
			\$ 10,081.80
LABOUR & MISC. CHARGES			
01		Towing charges.	\$ 120.00
02		To check electrical lighting concerned.	\$ 150.00
03		To transfer of tyre, rim and on wheel balancing.	\$ 50.00
04		To reinstall of front bumper parking sensor.	\$ 120.00
05		To rust-proofing of the affected areas.	\$ 350.00
06		To check steering geometry and computer wheel alignment.	\$ 100.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,800.00
08		Putty and spray painting of the affected portion	\$ 1,000.00
Total			\$ 3,690.00
			\$ 13,771.80

LKR Auto Consultants notice notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

L66 - Marcus
28/04/2020 1430h

P-10952-2
102
9857-11

AlGAsia Insured's Veh No : SJP2468T
Date of Accident : 28 April 2020


陳林路摩私人有限公司
TAN LIM MOTOR PTE LTD
1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Kek Siew Sin

Date : 05 May 2020

Supplementary To Repair SMH6984A - Mercedes Benz E200 AVG (R18 LED)
Chassis No : WDD2130422A578313

S/No	Quantity	Description	Amount
		<u>NETT ITEMS</u>	
01	1 pc	tie rod end n/s	\$ 280.00
02	1 pc	rack end n/s	\$ 195.00
			\$ 475.00
		Less 10 %	\$ 47.50
			\$ 427.50
		<u>LABOUR & MISC. CHARGES</u>	
01		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 350.00
			\$ 350.00
		Total	\$ 777.50

1-11427.35
182
7-10284.61
L-1860.00
12144.61

150



SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

Date: 28/4/20

BY Name/Company

CASH

Vehicle No. SMH 6984A Model MB E200

From Upper Thomson Rd

To No. 1 Defu Lane 6 Tan Lim Motor

Remarks

Time: [] : [] - [] : [] : []

- ☐ Jump Start
- ☐ Tyre Replacement
- ☒ Accident Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☒ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo Payment
- ☐ Trips

Amount \$ 100+

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misadventure to your vehicle whilst being towed.

24 HRS TOWING SERVICE
6841 0080

www.speedwayrecovery.com

Email: speedwaytowing@gmail.com

Tow Truck

Received By