MESSAGES

CLAIMS



General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	
General Details	•		Work	shop Details			
Involving	HINO FS1ETKA-12.9 D (M) (XD4205U)	Total F	Rebate Amount	24389		
Date of Loss	17 April 2020		Nett L	oss Amount	\$75,611.00		
Time of Loss	12.00	Assign	ed Workshop	LKK AUTO C	ONSULTANTS PTE LTD (TP)		
Loss Description	SKW2158P (INSD) C/W XD4	Days o	of work completion	20			
Comment							

MESSAGES

CLAIMS



General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	
Vehicle & Driver Details							
Vehicle Registration#	XD4205U		Purcha	se Date	dd/mm/yyyy	,	
Registration State	SINGAPORE		Registr	ration Date *	16/06/2010		
Mileage	250638		Age of	Vehicle	9		
POLIC CATEGORY INFO	CY ASSESSMEN	IT INFORMATION	Driver	Details			
Manufacturing	2010		CAT	EGORY	FNOL INFORMATION	POST SURVEY INFORMATION	
Year			Driv	ver Name	ARUMUGAM MATHIYALAGAN		
Make HING	O HINO				MATTITALAGAN		
FS1E	ETKA-12.9 D		Dat	e of Birth		dd/mm/yyyy	
Model (M)	FS1ETKA		Age	·	0		

Type CATEGORY	POLICY INFORMATION	ADDEDDIMENT HALOUMATION	6ATEGORY n	ENOLUNEORMATION	POST SURVEY
Type of Paint			Education Qualification	Other	~
Chassis No		JHDFS1ETKXXX12074	Driving Experience	0	
Engine No		E13CUN15374	Driver License #		
Engine Capacity		12913	License Type		~
Sum Insured		0	License Issue Date		dd/mm/yyyy 🎬
Market Value		100000	License Expiration Date		dd/mm/yyyy ##
			Address	Singapore	
			Address type	Personal Correspondence	•

Correspondence

CATEGORY Gender	FNOL INFORMATION Unknown	POST SURVEY
Marital status	Unknown	•
Identification #	G8483890Q	

MESSAGES

CLAIMS



General & Workshop Details	Vehicle & Driver Details Vehic	le Condition Taxe	Taxes & Ratio Parts & Labour Miscellaneous Summary							
Detailed Assessment			Condition of Vehicle at time of survey							
Inspection Date *	28/04/2020		General condition	Fair			•			
Total Loss	Yes No		Steering (Serviceable)	Yes	No					
Towing Charges	0		Footbrake (Serviceable)	Yes	No					
Voluntary Excess	0		Handbrake (Serviceable)	Yes	No					
Compulsory Excess	0									
Young/Inexperienced/Un named Driver Excess	0		Engine Modification	Yes	No					
Other Excess			Pre-accident condition	Fair			•			
			Tyre Condition							
Age of Tyres			Spare wheel							

Front Tyre Size	295/80R22.5	Rear Tyre Size	295/80R22.5
Front left side	BRIDGESTONE5mm	Rear left side	BRIDGESTONE5mm
Front right side	BRIDGESTONE5mm	Rear right side	BRIDGESTONE5mm

MESSAGES

CLAIMS



General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary 	
Tax Eligibility & Additional [Deduction for Parts						
Depr./Bttr%			Salvag	e%			
Discount%	10		Settle	ment%	100		
Paint Labour/Material Ratio)						
Paint Labour Ratio	20		Paint I	Material Ratio	80		
Cash Loss		Yes	No				
Part Supplied by AXA		Yes	No				

MESSAGES

CLAIMS

Genera	l & Worksh	nop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary							
Parts															
Add	Approve	Deny	Submit All												
	EDIT	SR NO	QUAN MATERIAL TITY	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
	Ø	0	1	REAR CARGO PLATE	Serviceable	0	0	No		10			0	Deny	m
	Ø	O	2	REAR CARGO GATE HINGE LOWER	Serviceable	0	0	No		10			0	Deny	ŵ
	P	0	4	REAR CARGO GATE STOPPER	Serviceable	0	0	No		10			0	Deny	ŵ
	Ø	0	2	REAR CARGO GATE STOPPER BRACKET	Serviceable	0	0	No		10			0	Deny	ŵ
	P	0	1	REAR CARGO GATE LOWER PANEL	Repair	0	0	No		10			0	Deny	ŵ

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
	0	1		TAIL LAMP PANEL (2PCS)	Bent	0	383	No		10			344.7	Reviewing	ŵ
0	0	1		TAIL LAMP LH	Broken	0	573	No		10			515.7	Reviewing	ŵ
0	0	1		TAIL LAMP RH	Serviceable	0	0	No		10			0	Deny	ŵ
P	0	1		REAR LICENCE PLATE LAMP	Cut	0	177	No		10			159.3	Reviewing	ŵ
P	0	2		REVERSE LAMP	Serviceable	0	0	No		10			0	Deny	ш
P	0	2		REAR CARGO GATE LOCK	Serviceable	0	0	No		10			0	Deny	ı
Ø	0	1		REAR SPARE TYRE CARRIER	Serviceable	0	0	No		10			0	Deny	î
P	0	4		REAR CARGO GATE LOWER RIVET	Serviceable	0	0	No		10			0	Deny	ŵ
Ø	0	2		REAR CARGO GATE LOCK HOLDER	Serviceable	0	0	No		10			0	Deny	til
P	0	1		REAR CARGO GATE LOWER MEMBER	Repair	0	0	No		10			0	Deny	ŵ

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
ø	0	4		REAR CARGO GATE LOWER MEMBER HOOK	Serviceable	0	0	No		10			0	Deny	ŵ
Ø	0	1		EXHAUST SILENCER	Serviceable	0	0	No		10			0	Deny	ш
ø	0	1		EXHAUST HANGER	Serviceable	0	0	No		10			0	Deny	ŵ
P	0	1		REAR FLOOR PANEL	Dented	0	1487	No		10			1338.3	Reviewing	ı
0	0	2		REAR CRASH BAR BRACKET	Dented	0	397	No		10			714.6	Reviewing	ŵ
Ø	0	1		REAR LICENCE PLATE BASE PANEL	Bent	0	979	No		10			881.1	Reviewing	ı
Ø	0	1		REAR CRASH BAR	Dented	0	1909	No		10			1718.1	Reviewing	ш
Ø	0	1		REAR TOOL BOX	Dented	0	2800	No		10			2520	Reviewing	m
Ø	0	2		REAR TOOL BOX BRACKET	Bent	0	400	No		10			720	Reviewing	ı
Ø	0	1		CRANE CONTROL BOX ASSY	Serviceable	0	0	No		10			0	Deny	ı
P	0	1		CRANE CONTROL PANEL	Serviceable	0	0	No		10			0	Deny	î

	EDIT	SR NO	QUAN MATERIAI TITY	L PART NAME CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
	0	0	2	FRONT HYDRAULIC SUPPORT ARM ASSY	e 0	0	No		10			0	Deny	â
	Ø	0	2	FRONT HYDRAULIC SUPPORT ARM BASE	e 0	0	No		10			0	Deny	ш
	P	0	2	REAR HYDRAULIC SUPPORT ARM BASE	e 0	0	No		10			0	Deny	â
Labour														
Add	Approve	Deny	Submit All											
	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUST AMOUN	ED LABOUR	ESTIMATE PAINT	Г	ADJUSTED PAINT		TION BOUR)	COMMENT	REMOVE
	Ø	0		TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	0	2200		0		0	Re	viewing		ŵ
	Ø	0		TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	0	80		0		0	Re	viewing		ŵ
	<i>D</i>	0		TO REMOVE AND REPLACE, STRAIGHTEN AND READJUST EXHAUST PIPE	. 0	0		0		0	De	ny		â

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
P	0		TO ALIGN, REMOVE & INSTALL FRONT AND REAR HYDRAULIC SUPPORT ARMS AND TO CONDUCT BASE ALIGNMENT	0	0	0	0	Deny		ŵ
P	0		SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY TAILGATE, TOOLS BOX, CRANE CONTROL BOX, FLOOR PANEL AND OTHER AFFECTED AREA / PANEL	0	700	0	0	Reviewing		ŵ
D	0		TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	0	70	0	0	Reviewing		ŵ



MESSAGES

CLAIMS



Genera	l & Worksh	nop Details	Vehicle & Driver De	tails Vehicle	e Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE	
	P	0	DAYS OF REPAIR : 10 DAYS	Reviewing		0		ш	
	Ď	0	REAR NUMBER PLATE	Reviewing		35	BENT	ŵ	
	Ď	0	REAR NUMBER PLATE LAMP BULB	Deny		0	NOT NECESSARY	ŵ	
	Ď	0	REAR CARGO GATE "60KM/H" STICKER	Reviewing		15	NECESSARY	iii	
	Ø	0	SPARE TYRE	Deny		0	NOT NECESSARY	ŵ	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
ø	0	REAR CARGO GATE COMPANY STICKER	Reviewing		200	NECESSARY	ŵ
Ø	0	REAR CARGO GATE LOWER MEMBER " PALFINGER" STICKERS - 2 PCS	Reviewing		120	NECESSARY	ш
Ø	0	FRONT HYDRAULIC SUPPORT ARM ASSY OIL SEAL - 8 PCS	Deny		0	NOT NECESSARY	ŵ
Ø	0	REAR HYDRAULIC SUPPORT ARM ASSY OIL SEAL - 8 PCS	Deny		0	NOT NECESSARY	ш
Ø.	0	FRONT HYDRAULIC	Deny		0	NOT	ŵ

EDIT	SR NO	SUPPORT ARM	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
Ø	0	REAR HYDRAULIC SUPPORT ARM ASSY OIL	Deny		0	NOT NECESSARY	d
Ď	0	SUNDRIES	Reviewing		50	NECESSARY	ŵ
Ø	0	REAR HYDRAULIC SUPPORT ARM ASSY - 2 PCS }	Reviewing		0	BENT / LEAKING OIL	ŵ
P	0	SEAL, KIT, TD 596B - 2 PCS }	Reviewing		650	NECESSARY	ŵ
P	0	ELBOW, L/N 12S X BSP 3/8, EA1749 }	Reviewing		39	NECESSARY	m
P	0	LAMP, WORK, LED, TU-01F08 - 2 PCS }	Reviewing		312	BROKEN	ŵ
		PAD,					

NECESSAKY

SUPPUKT AKM

. LDII	6R NO	STABILIZER, vame g, HXE3506 }	Reviewing ACTION	ESTIMATED AMOUNT	@DJUSTED AMOUNT	NOT SEEMMENA RY	NEOVE
Ø	0	PIPE-1.0M X 12MM }	Reviewing		78	BENT	1
Ď	0	REAR BUMPER WITH BRACKET }	Reviewing		455	BENT	d
P	0	MS CHEQ PLATE (NPA) }	Deny		0	NOT NECESSARY	ŵ
P	0	WOODEN BLOCK (NPA) - 2 PCS }	Deny		0	NOT NECESSARY	ш

	O	CHECKED AND FOUND B/S REAR STABILIZER CYL LEAKING. DISMANTLE B/S STABILIZER CYL AND FOUND SEAL-KIT DEFECTIVE. DISMANTLE AND REPLACEMENT OF NEW SEAL-KIT COMPLETED. REINSTALL BACK B/S REAR STABILIZER CYL COMPLETED }	Reviewing	1690	

ESTIMATED

AMOUNT

ACTION

ADJUSTED

AMOUNT

COMMENT

REMOVE

SR

NO

NAME

EDIT

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	CHECKED AND FOUND R/S REAR STABILIZER PIPE LEAKING. DISMANTLE AND REPLACEMENT OF NEW PIPE COMPLETED }	Reviewing		0		Î
	0	CHECKED AND FOUND R/S REAR STABILIZER PIPE ELBOW LEAKING. DISMANTLE AND REPLACEMENT OF NEW ELBOW COMPLETED }	Reviewing		0		ů

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	CHECKED AND FOUND R/S REAR STABILIZER CYL PLATE BEND & DEFECTIVE DISMANTLE AND REPLACEMENT OF NEW SUPPORT PLATE COMPLETED }	Reviewing		0		Ш

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		CHECKED AND					
		FOUND REAR DECK MS CHEQ PLATE DEFECTIVE. CONDUCT HOTWORK TO REMOVE THE DAMAGED CHEQ PLATE.					
	0	FABRICATE OF NEW CHEQ PLATE WITH CUT INTO SIZE BY MACHINING & REPLACEMENT TO POSITION BY WELDING & GRIND COMPLETED }	Reviewing		0		

ESTIMATED

ADJUSTED

SR

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	CHECKED AND FOUND REAR DECK WOODEN DEFECTIVE (BOTTOM). CONDUCT HOTWORK TO REMOVE THE TOP CHEQ PLATE. FABRICATE OF NEW WOODEN BLOCK WITH CUT INTO SIZE BY MACHINING. REPLACEMENT OF NEW WOODEN BLOCK TO POSITION COMPLETED }	Reviewing		0		
Ø	0	RE-WELD BACK OF NEW CHEQ PLATE TO POSITION COMPLETED 3	Reviewing		0		ŵ

CONTILLE LED

NAME

SR

NO

EDIT

0	CHECKED AND FOUND REAR BUMPER & BRACKET DEFECTIVE. FABRICATE OF NEW SUPPORT BRACKET WITH CUT INTO SIZE BY MACHINING & NEW BUMPER COMPLETED. REPLACEMENT OF NEW BUMPER WITH NEW SUPPORT BRACKET TO POSITION BY	Reviewing	0	
0	WELDING & GRIND COMPLETED } REINSTALL BACK COMPLETED. S }	Reviewing	0	i

ESTIMATED

AMOUNT

ACTION

ADJUSTED

AMOUNT

COMMENT

REMOVE

EDIT	NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	CHECKED AND FOUND L/S TOOLBOX BRACKET DEFECTIVE. DISMANTLE TOOLBOX AND RE-	Reviewing		0		1
		FABRICATE OF BRACKET & REINSTALL BACK COMPLETED }					
	0	CHECKED AND FOUND B/S REAR ROTATING LIGHT DEFECTIVE. DISMANTLE AND REPLACEMENT OF NEW ROTATING LIGHT COMPLETED. RE-WIRING & CABLE TO RE-	Reviewing		0		

EDIT	SR NO	RAGE NEW ROTATING	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		LIGHT					
		COMPLETED }					

MESSAGES

CLAIMS



Assessment Details

Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
\$0.00		Adjust	ed Claim Amount	\$15,605.80	
ESTIMATE	ADJUSTED				
\$0.00	\$8,911.80				
\$0.00	\$3,050.00				
\$0.00	\$3,644.00				
	\$0.00 ESTIMATE \$0.00 \$0.00	\$0.00 ESTIMATE ADJUSTED \$0.00 \$8,911.80 \$0.00 \$3,050.00	\$0.00 Adjusted ESTIMATE ADJUSTED \$0.00 \$8,911.80 \$0.00 \$3,050.00	\$0.00 Adjusted Claim Amount ESTIMATE ADJUSTED \$0.00 \$8,911.80 \$0.00 \$3,050.00	\$0.00 Adjusted Claim Amount \$15,605.80 ESTIMATE ADJUSTED \$0.00 \$8,911.80 \$0.00 \$3,050.00

Submit for Review

MESSAGES

CLAIMS



General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labou	r Miscellaneous	Summary	
Add	Approve	Deny	Submit All			•		•	
	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE	
		0	FINAL LUMP SUM	Reviewing		12500		ŵ	

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	
Estimated Claim Amount	timated Claim Amount \$0.00		Adjusted Claim Amount		\$12,500.00		
CATEGORY	ESTIMATE	ADJUSTED					
Miscellaneous	\$0.00	\$12,500.00)				

Submit for Review