

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32925

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0289/2020/NS
Date : 17-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

4 days - ok - jb - 27 Jun 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Cole Graham Mottram
Address : 52 Marine Parade Rd
#12-20
Singapore 449308
Telephone : (HP) +65 96800284
Type of Claim : Own damage Claims
Policy No. : 1800138769
Vehicle No : **SKR 4885 L**
Model Code : Q5 SPORT 2.0 TFSI QU
Model / Year : Nov-18
Engine No : DAX 047098
Chassis No : WAUZZZF2J2244797
Mileage : -
Date In : -
Estimated By : Allan Wu
Accident Date : 15-Mar-20
Place of Accident : Amber Road & Marine Parade Road Corner Roundabout

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 4885 L

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper. To repair rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,600.00	\$ 500.00
3	To respray rear bumper, rear lower bumper, rear lid and both rear wheel arch trims.	\$ 4,000.00	\$ 1,750.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
SUB TOTAL LABOUR CHARGES		: \$ 6,152.00	\$ 2,802.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 4885 L

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
1	REAR TOP BUMPER	\$ 1,619.00	\$	1,295.20
2	REAR LOWER BUMPER	\$ 1,114.00	\$	891.20
3	REAR BUMPER SPOILER	\$ 780.00	\$	624.00
4	REAR BUMPER TOWING EYE COVER - LH	\$ 45.00		
5	REAR BUMPER TOWING EYE COVER - RH	\$ 27.00		
6	REAR BUMPER CLOSING ELEMENT - LH / RH	2 \$ 180.00		
7	REAR BUMPER TRIM - LH / RH	2 \$ 442.00		
8	TAIL LIGHT - LH / RH	2 \$ 1,296.00		
9	BOOT LID CONTROL UNIT	\$ 396.00		
10	REAR BUMPER CARRIER	\$ 857.00		
11	REAR BUMPER HOLDING STRAP	\$ 156.00	\$	124.80
12	REAR PARKING AID SENSOR	2 TBC		
13	REAR PARKING AID SEAL RING	4 \$ 14.00		
14	PACKING ADHESIVE	\$ 18.00		
15	AUDI EMBLEM	\$ 117.00	\$	93.20
16	Q5 INSCRIPTION	\$ 90.00	\$	71.76
17	TFSI INSCRIPTION	\$ 90.00	\$	71.76
18	QUATTRO INSCRIPTION	\$ 90.00	\$	71.76
19	REAR WHEEL COVER - LH / RH	2 \$ 1,004.00	\$	803.20
20	REAR NO PLATE	S/N \$ 60.00		
21	SUNDRIES	\$ 300.00		
TOTAL SPARE PARTS		: \$ 8,695.00	\$	4,046.88
TOTAL LABOUR CHARGES		: \$ 6,152.00	\$	2,802.00
GRAND TOTAL		: \$ 14,847.00	\$	6,848.88

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant