



CC3/R1620005461/2083
ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MY
To inspect Vehicle No: _____
at Workshop no/s: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: 4500/-
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
-----	-----

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 04 days Res: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
Vehicle: IN / OUT
Date: _____ Person Contacted: _____

Days Of Repair: 4
Resurvey No. of Trip: 1

Survey Fee: _____
Transportation: _____
3 + PS _____
Phone _____
Fax _____
E-mail _____

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Meet. Site (\$)

Report Format: _____
Lump Sum: 86,848.83 R/P

Front: _____ Rear: _____
R/Bal. 06 mm R/Bal. 06 mm
L/Bal. 06 mm L/Bal. 06 mm
D.O.A. _____ D.O.I. 28/04/20
Survey held at: Premium
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
00 AIG.
MV: 170K
PV: 66.9K
Nett: 103.1K.
R/P \$ 6,848.83 @ 4 days, finalize with JB.
(43,998.12 / Red - 54%)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32925

Telefax


Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0289/2020/NS
Date	:	17-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.
Your insured vehicle no : SMN 9136 E

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Cole Graham Mottram
Address	:	52 Marine Parade Rd #12-20 Singapore 449308
Telephone	:	(HP) +65 96800284
Type of Claim	:	Own damage Claims
Policy No.	:	1800138769
Vehicle No	:	SKR 4885 L
Model Code	:	Q5 SPORT 2.0 TFSI QU
Model / Year	:	Nov-18
Engine No	:	DAX 047098
Chassis No	:	WAUZZZF2J2244797
Mileage	:	-
Date In	:	-
Estimated By	:	Allan Wu
Accident Date	:	15-Mar-20
Place of Accident	:	Amber Road & Marine Parade Road Corner Roundabout



Premium Automobiles

33 Ubi Road 1, Singapore 408009
Tel: 9398 2323 Fax: 9394 1193

Telefax

Estimated Labour Charges for Accident Vehicle SKR 4885 L

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	✓
2	To dismantle and renew rear bumper. To repair rear lid. Re-organise rear crash management components. Reinstall all parts removed. 550 / 350	\$ 1,600.00	500
3	To respray rear bumper, rear lower bumper, rear lid and both rear wheel arch trims. 550 / 1500, 300	\$ 4,000.00	1750
4	To carry out diagnostic check.	S/N \$ 192.00	✓
SUB TOTAL LABOUR CHARGES		: \$ 6,152.00	



Premium Automobiles

33 Ulu Road, Singapore 408629
Tel: 6346 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 4885 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR TOP BUMPER <i>Del'd</i>	S	1,619.00 / 1295.20
2	REAR LOWER BUMPER <i>Del'd</i>	S	1,114.00 / 891.20
3	REAR BUMPER SPOILER <i>Del'd</i>	S	780.00 / 624.00
4	REAR BUMPER TOWING EYE COVER - LH <i>Alf</i>	S	45.00 x
5	REAR BUMPER TOWING EYE COVER - RH <i>Alf</i>	S	27.00 x
6	REAR BUMPER CLOSING ELEMENT - LH / RH <i>Neu</i>	S	180.00 x
7	REAR BUMPER TRIM - LH / RH <i>Neu</i>	2 S	442.00 x
8	TAIL LIGHT - LH / RH <i>Neu</i>	2 S	1,296.00 x
9	BOOT LID CONTROL UNIT <i>Neu</i>	S	396.00 x
10	REAR BUMPER CARRIER <i>Neu</i>	S	857.00 x
11	REAR BUMPER HOLDING STRAP <i>Neu</i>	S	156.00 / 124.80
12	REAR PARKING AID SENSOR <i>Neu</i>	2	TBC *
13	REAR PARKING AID SEAL RING <i>Neu</i>	4 S	14.00 x
14	PACKING ADHESIVE <i>Neu</i>	S	18.00 x
15	AUDI EMBLEM <i>Neu</i>	S	117.00 / 93.20
16	Q5 INSCRIPTION <i>Neu</i>	S	90.00 / 71.76
17	TFSI INSCRIPTION <i>Neu</i>	S	90.00 / 71.76
18	QUATTRO INSCRIPTION <i>Neu</i>	S	90.00 / 71.76
19	REAR WHEEL COVER - LH / RH <i>Neu</i>	2 S	1,004.00 / 803.20
20	REAR NO PLATE <i>Neu</i>	S/N S	60.00 x
21	SUNDRIES <i>Neu</i>	S	300.00 x
TOTAL SPARE PARTS		:	\$ 8,695.00
TOTAL LABOUR CHARGES		:	\$ 6,152.00
GRAND TOTAL		:	\$ 14,847.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.



Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adam King.
Surveyed Date : 28/04/20.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Part prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant