

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT120005466/4vf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLW 5989
stytech

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

200k.

IDAC Accident Rpt:

Consistent? : Yes or No

PR Seen:

2

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Dep 24h.

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLW 5989B

Yr Regn:

11/16

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Mer Benz 5400L c.c 2996

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

90912

T/Radio: Insured / Std / NI / NA

Eng/No:

WDD2221652A205446

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/45R19
R: 275/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MTS / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/4/20

D.O.I.

30/4/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/5/20 4/5 27A 144074 am. by estimate
confirmed with Winston (Red 4881, 52%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 22/5/20 - Typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format : Merimen

Lump Sum / I.B.I: (\$ LS \$4500)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Vehicle: SLW5898B

Make & Model: MERCEDES S400

Chassis No: WDD2221652A205446

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Boot lid <i>do ✓</i>		<i>2551</i>	<i>2927.00</i>	<i>✓</i>
2	Rear Boot Inner Garnish Chips <i>17X</i>			<i>50.00 S.N</i>	<i>X</i>
3	Rear Boot Chrome Moulding <i>5m ✓</i>			<i>205.00</i>	<i>✓</i>
4	Emblem Rear logo <i>1m ✓</i>			<i>53.00</i>	<i>✓</i>
5	"S400" Wording <i>m ✓</i>			<i>94.00</i>	<i>✓</i>
6	C & C Plate <i>1m ✓</i>			<i>35.00 S.N</i>	<i>✓</i>
7	rear Bumper <i>do/ce ✓</i>		<i>2250</i>	<i>2298.00</i>	<i>✓</i>
8	Rear Bumper Chips <i>1m ✓</i>			<i>50.00 S.N</i>	<i>✓</i>
9	Rear Taillamp (Left) <i>ALS</i>		<i>1</i>	<i>1126.00</i>	<i>X</i>
10	Reinforcement <i>12X</i>			<i>285.00</i>	<i>X</i>
11	Reverse Sencer <i>ALS</i>		<i>10h</i>	<i>198.00</i>	<i>✓</i>
	Labour				
1	Check Wiring			\$ 80.00	<i>20</i>
2	Anti Rust Proof			\$ 80.00	<i>30</i>
3	Panel Beating			\$ 900.00	<i>300</i>
4	Paint WORK <i>70 putty & spray painting</i>			\$ 1,000.00	<i>450</i>
				9,381.00	
				<i>not added</i>	
				<i>2m</i>	
				<i>h/s 4500</i>	
				<i>3 days</i>	
				<i>Chapman Hargreaves</i>	

9.381
100
4815.9
1700.9

SIYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #02-30 Q1-03

Kaki Bukit Autohub Singapore 417921

Tel: 6444 8125 Fax: 6445 2370

GST Reg. No.: 201601539K

Co. Reg. No.: 201601539K

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: