

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5411D**AAD2004-093***Not Withheld**21 May 81700h*

Vehicle No.:

Chassis No.:

Vehicle Make:

28 APR 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5411D

VF1ABL15AUC279614

RENAULT

LATITUDE

26.4.2020

FCIL

4/11/2014

PART

- 1 BUMPER COVER FRT
- 1 BUMPER SPOILER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER RETAINER FRT LH
- 1 BUMPER RETAINER FRT RH
- 1 BUMPER UNDERTRAY FRT
- 1 BUMPER GRILLE LOWER FRT
- 1 BUMPER FOG LAMP GRILLE LH
- 1 BUMPER FOG LAMP GRILLE RH
- 1 BUMPER BEAM FRT
- 1 RADIATOR GRILLE
- 1 RADIATOR GRILLE BADGE 'RENAULT'
- 1 RADIATOR GRILLE FRAME
- 1 FRAME FULL SUPPORT PANEL
- 1 FRAME FULL SUPPORT BRACKET
- 1 HEADLAMP LH
- 1 HEADLAMP RH
- 1 BONNET
- 1 FENDER PANEL FRT LH
- 1 WHEELARCH FRT LH
- 1 FENDER BRACKET LOWER LH
- 1 FENDER PANEL FRT RH
- 1 WHEELARCH FRT RH
- 1 FENDER BRACKET LOWER RH
- 1 WIPER RESERVOIR

LIST

\$	<i>Avic/NA</i>	747.20	✓
\$	<i>SL</i>	344.70	×
\$	<i>SL</i>	394.68	×
\$	<i>SL</i>	101.40	×
\$	<i>DR</i>	101.40	✓
\$	<i>SL</i>	292.50	×
\$	<i>CM</i>	147.00	✓
\$	<i>SL</i>	207.21	} X
\$	<i>SL</i>	207.21	
\$	<i>R</i>	663.70	
\$	<i>SL</i>	969.90	
\$	<i>SL</i>	225.36	
\$	<i>SL</i>	686.00	}
\$	<i>SL</i>	592.70	
\$	<i>R</i>	41.60	
\$	<i>SL</i>	743.60	×
\$	<i>mgent</i>	743.60	✓
\$	<i>R</i>	1,312.70	} A
\$	<i>R</i>	414.40	
\$	<i>SL</i>	112.30	
\$	<i>SL</i>	11.80	
\$	<i>R</i>	437.10	
\$	<i>SL</i>	191.40	}
\$	<i>SL</i>	11.80	
\$	<i>SL</i>	179.60	

Trans-cab Auto Services Pte Ltd

AAD2004-093

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5411D

1	WIPER RESERVOIR NECK	\$	29.30	X
1	WIPER RESERVOIR MOTOR	\$	82.60	X
1	AIR CLEANER BOX	\$	464.20	X
1	AIR CLEANER HOSE	\$	175.85	X
1	AIR CLEANER LOWER	\$	271.26	X

TOTAL	\$	10,904.07
10%	\$	1,090.41
	\$	9,813.66

Special Nett

1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	X
1SET	BUMPER CLIP FRT	\$	66.00	✓
1SET	BUMPER BRACKET CLIP FRT LH	\$	12.00	} X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
1	BUMPER BRACKET CLIP FRT RH	\$	12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	
1	RADIATOR GRILLE SCREW	\$	16.00	
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
1SET	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	} 455m
1	FRONT RENAULT TYRE 215/60/16	\$	300.00	
1	FRONT RENAULT TYRE RIM	\$	380.00	
1	Front licence plate with holder	\$	80.00	
1SET	WHEELARCH CLIP FRT LH	\$	30.50	X
1SET	WHEELARCH CLIP FRT RH	\$	30.50	X

TOTAL	\$	1,189.00
--------------	-----------	-----------------

TOTAL PARTS	\$	11,002.66
--------------------	-----------	------------------

Labour

To rust-proofing of the affected areas.	\$	170.00	X
---	----	--------	---

Trans-cab Auto Services Pte Ltd

AAD2004-093

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5411D

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	2001
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To Transfer Of Front Fender Fittings, Attachments And Perform Water Seepage Test.	\$	4 170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
Putty and spray painting of the affected portion.	\$	6,000.00	2201
TOTAL	\$	14,000.00	

Over All Total \$ 25

(LUMP SUM) Repair Days

20 DAY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary charges must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: