

ASS. REC. BY:

REF:

AG / 2000 3468 / Kg a3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S/HO 25814 Yr Regn: 11, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude c.c. 1998Colour M. White / Red A/C: Insured / Std / NI / NASp. Reading 559427 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABL15AUC 282299Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sailun

Front

Rear

R/Bal. P mmR/Bal. P mmL/Bal. P mmL/Bal. P mmD.O.A. 27/4/20D.O.I. 28/4/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/

21 Sep @ 2400h

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

S + RS. \$

Fuel

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H**AAD2004-088***Not Authorized**11 Sep @ 2400h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

26 APR 2020**SHD 258H**

VF1ABL15AUC282299

RENAULT

LATITUDE

27.4.2020

AIG

20/11/2015

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER GRILL WING HOLDER RH
1	FENDER BRACKET FRT RH
1	FENDER INSULATOR RH
1	TOW COVER FRT
1	FRONT BRACE PANEL
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	BONNET
1	BONNET INSULATOR

	LIST	
\$	<i>Bu</i> 747.20	✓
\$	<i>Sn</i> 344.70	X
\$	<i>Sn</i> 394.68	X
\$	<i>Dis</i> 101.40	✓
\$	<i>Sn</i> 10.70	X
\$	<i>Sn</i> 292.50	X
\$	<i>Sn</i> 147.00	X
\$	<i>Sn</i> 207.21	X
\$	<i>R</i> 663.70	X
\$	<i>my cm</i> 743.60	✓
\$	<i>R</i> 128.30	X
\$	<i>B</i> 437.10	✓
\$	<i>Dis</i> 191.40	✓
\$	<i>Sn</i> 11.80	} X
\$	<i>Sn</i> 80.70	
\$	<i>R</i> 106.40	
\$	<i>Sn</i> 66.30	
\$	<i>Sn</i> 60.90	
\$	<i>R</i> 177.22	
\$	<i>Sn</i> 969.90	
\$	<i>Sn</i> 225.36	
\$	<i>Sn</i> 686.00	
\$	<i>Sn R</i> 592.70	
\$	<i>R</i> 41.60	
\$	<i>R</i> 1,312.70	
\$	<i>Sn</i> 294.30	

Trans-cab Auto Services Pte Ltd

AAD2004-088

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H

1	BONNET STRUT RH	\$	53.30
1	BONNET HINGE RH	\$	237.40
1	BONNET LOCK	\$	152.80
1	LOWER ARM RH L70Y	\$	192.70
1	KNUCKLE ARM RH L70Y	\$	481.50
1	ABSORBER FRT RH L70Y	\$	203.50
1	ABSORBER MOUNTING KIT FRT RH	\$	273.60
1	DRIVESHAFT RH	\$	1,355.70
1	STABILIZER BAR FRT	\$	427.90
1	KNUCKLE HUB+BEARING RH L70Y	\$	272.30
1	STEERING PINION RACK L70Y	\$	3,765.30
1	WIPER RESERVOIR MOTOR	\$	82.60
1	WIPER RESERVOIR	\$	179.60
1	WIPER RESERVOIR NECK	\$	29.30
1	SUBFRAME OUTER FRT	\$	1,094.20
1	SUBFRAME BRACKET OUTER RH	\$	49.00
1	SUBFRAME INNER FRT L70Y	\$	746.00
1	SUBFRAME SUPPORT INNER L70Y	\$	69.50
1	SUBFRAME BRACKET INNER RH L70Y	\$	101.00
1	FENDER PANEL SUPPORT FRT RH	\$	432.00
1	FENDER PANEL INNER FRT RH	\$	838.40
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	DOOR PANEL FRT RH	\$	2,844.66
1	DOOR MIRROR ASSY RH	\$	1,483.40
1	DOOR HARNESS WIRE RH	\$	2,670.00
1	A/C CONDENSER	\$	1,537.80

TOTAL \$ 31,285.12**10% \$ 3,128.51****\$ 28,156.61**X S₂**Special Nett**

1 BUMPER CLIP FRT

\$

12 68.00 ✓

Trans-cab Auto Services Pte Ltd

AAD2004-088

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H

1 BUMPER BRACKET CLIP FRT RH	\$	nn	15.00	X
1 BUMPER SUPPORT CLIP FRT RH	\$	nn	15.00	X
1 BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2 FRAME FULL SUPPORT PANEL NUT	\$	nn	25.00	X
2 FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1 WHEELARCH CLIP FRT RH	\$	nn	35.00	✓
1 FRONT RENAULT TYRE	\$	Sn	300.00	} X
1SET Front licence plate with holder	\$	Sn	80.00	
1 FRONT RENAULT TYRE RIM	\$	Sn	380.00	
1SET RADIATOR GRILLE SCREW	\$	nn	20.00	
1SET RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	
1 FRONT RENAULT TYRE RIM COVER	\$	Sn	60.00	
1 Front Door Sticker "Trans-Cab"	\$	nn	80.00	
1 Front Door Sticker "Classic"	\$	nn	80.00	
1 Windscreen moulding	\$	nn	180.00	
2 FRONT WINDSCREEN SEALANT	\$	nn	150.00	
1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	120.00	
TOTAL	\$		1,829.00	

TOTAL PARTS \$ 29,985.61**LABOUR**

Putty and spray painting of the affected portion.	\$	7,500.00	4401
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	4001

Trans-cab Auto Services Pte Ltd**AAD2004-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H

To check steering geometry and computer wheel alignment	\$	nn	220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	nn	380.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	nn	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn	380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H**AAD2004-088**

To rust-proofing of the affected areas.	\$	170.00	30%
To Check Electrical Lighting Concerned.	\$	170.00	20%
TOTAL	\$	18,860.00	
Over All Total	\$	48,845.61	

LUMP SUM (REPAIR DAY)~~25 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD258H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Apr 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002899
Chassis No.:	VF1ABL15AUC282299
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Nov 2015
First Registration Date:	20 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2023
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	19 Nov 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,267.00
COE Rebate Amount:	\$20,163.00
Total Rebate Amount:	\$35,161.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Apr 2020

OK