

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H**AAD2004-088***Not Authored
1/10/2020 @ 2400h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

26 APR 2020

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 258H

VF1ABL15AUC282299

RENAULT

LATITUDE

27.4.2020

AIG

20/11/2015

PART		LIST	
1	BUMPER COVER FRT	\$	Bu 747.20 ✓
1	BUMPER SPOILER FRT	\$	Sn 344.70 X
1	BUMPER ABSORBER FRT	\$	Sn 394.68 X
1	BUMPER RETAINER FRT RH	\$	Dir 101.40 ✓
1	BUMPER SUPPORT FRT	\$	Sn 10.70 X
1	BUMPER UNDERTRAY FRT	\$	Sn 292.50 X
1	BUMPER GRILLE LOWER FRT	\$	Sn 147.00 X
1	BUMPER FOG LAMP GRILLE RH	\$	Sn 207.21 X
1	BUMPER BEAM FRT	\$	R 663.70 X
1	HEADLAMP RH	\$	Myum 743.60 ✓
1	HEADLAMP PANEL FRT RH	\$	R 128.30 X
1	FENDER PANEL FRT RH	\$	R 437.10 ✓
1	WHEELARCH FRT RH	\$	Dir 191.40 ✓
1	FENDER BRACKET LOWER RH	\$	Sn 11.80
1	FENDER GRILL WING HOLDER RH	\$	Sn 80.70
1	FENDER BRACKET FRT RH	\$	R 106.40
1	FENDER INSULATOR RH	\$	Sn 66.30
1	TOW COVER FRT	\$	Sn 60.90
1	FRONT BRACE PANEL	\$	R 177.22
1	RADIATOR GRILLE	\$	Sn 969.90
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	Sn 225.36
1	RADIATOR GRILLE FRAME	\$	Sn 686.00
1	FRAME FULL SUPPORT PANEL	\$	Sn R 592.70
1	FRAME FULL SUPPORT BRACKET	\$	R 41.60
1	BONNET	\$	R 1,312.70
1	BONNET INSULATOR	\$	Sn 294.30

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H**AAD2004-088**

1	BONNET STRUT RH	\$	53.30
1	BONNET HINGE RH	\$	237.40
1	BONNET LOCK	\$	152.80
1	LOWER ARM RH L70Y	\$	192.70
1	KNUCKLE ARM RH L70Y	\$	481.50
1	ABSORBER FRT RH L70Y	\$	203.50
1	ABSORBER MOUNTING KIT FRT RH	\$	273.60
1	DRIVESHAFT RH	\$	1,355.70
1	STABILIZER BAR FRT	\$	427.90
1	KNUCKLE HUB+BEARING RH L70Y	\$	272.30
1	STEERING PINION RACK L70Y	\$	3,765.30
1	WIPER RESERVOIR MOTOR	\$	82.60
1	WIPER RESERVOIR	\$	179.60
1	WIPER RESERVOIR NECK	\$	29.30
1	SUBFRAME OUTER FRT	\$	1,094.20
1	SUBFRAME BRACKET OUTER RH	\$	49.00
1	SUBFRAME INNER FRT L70Y	\$	746.00
1	SUBFRAME SUPPORT INNER L70Y	\$	69.50
1	SUBFRAME BRACKET INNER RH L70Y	\$	101.00
1	FENDER PANEL SUPPORT FRT RH	\$	432.00
1	FENDER PANEL INNER FRT RH	\$	838.40
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	DOOR PANEL FRT RH	\$	2,844.66
1	DOOR MIRROR ASSY RH	\$	1,483.40
1	DOOR HARNESS WIRE RH	\$	2,670.00
1	A/C CONDENSER	\$	1,537.80

TOTAL \$ 31,285.12
10% \$ 3,128.51
\$ 28,156.61

X *Sh***Special Nett**

1 BUMPER CLIP FRT

\$

Mr 68.00 ✓

Trans-cab Auto Services Pte Ltd

AAD2004-088

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H

1 BUMPER BRACKET CLIP FRT RH	\$	nn	15.00	X
1 BUMPER SUPPORT CLIP FRT RH	\$	nn	15.00	X
1 BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2 FRAME FULL SUPPORT PANEL NUT	\$	nn	25.00	X
2 FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1 WHEELARCH CLIP FRT RH	\$	nn	35.00	✓
1 FRONT RENAULT TYRE	\$	nn	300.00	} X
1SET Front licence plate with holder	\$	nn	80.00	
1 FRONT RENAULT TYRE RIM	\$	nn	380.00	
1SET RADIATOR GRILLE SCREW	\$	nn	20.00	
1SET RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	
1 FRONT RENAULT TYRE RIM COVER	\$	nn	60.00	
1 Front Door Sticker "Trans-Cab"	\$	nn	80.00	
1 Front Door Sticker "Classic"	\$	nn	80.00	
1 Windscreen moulding	\$	nn	180.00	
2 FRONT WINDSCREEN SEALANT	\$	nn	150.00	
1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	120.00	
TOTAL	\$		1,829.00	

TOTAL PARTS	\$	29,985.61
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	7,500.00	4401
---	----	----------	------

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn	380.00	X
---	----	----	--------	---

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	4001
---	----	----------	------

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H**AAD2004-088**

To check steering geometry and computer wheel alignment	\$	220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	380.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	170.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

AAD2004-088

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H

To rust-proofing of the affected areas.

\$ 170.00 30/

To Check Electrical Lighting Concerned.

\$ 170.00 20/

TOTAL \$ 18,860.00**Over All Total \$ 48,845.61****LUMP SUM (REPAIR DAY)**~~25~~ DAYS

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: