

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

26 APR 2020

PART

- 1 BUMPER COVER FRT
- 1 BUMPER SPOILER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER RETAINER FRT RH
- 1 BUMPER SUPPORT FRT
- 1 BUMPER UNDERTRAY FRT
- 1 BUMPER GRILLE LOWER FRT
- 1 BUMPER FOG LAMP GRILLE RH
- 1 BUMPER BEAM FRT
- 1 HEADLAMP RH
- 1 HEADLAMP PANEL FRT RH
- 1 FENDER PANEL FRT RH
- 1 WHEELARCH FRT RH
- 1 FENDER BRACKET LOWER RH
- 1 FENDER GRILL WING HOLDER RH
- 1 FENDER BRACKET FRT RH
- 1 FENDER INSULATOR RH
- 1 TOW COVER FRT
- 1 FRONT BRACE PANEL
- 1 RADIATOR GRILLE
- 1 RADIATOR GRILLE BADGE 'RENAULT'
- 1 RADIATOR GRILLE FRAME
- 1 FRAME FULL SUPPORT PANEL
- 1 FRAME FULL SUPPORT BRACKET
- 1 BONNET
- 1 BONNET INSULATOR

AAD2004-088*Not Authorized**11 Sep @ 2400h***SHD 258H**

VF1ABL15AUC282299

RENAULT

LATITUDE

27.4.2020

AIG

20/11/2015

LIST

\$	<i>Bu</i>	747.20	✓
\$	<i>Sn</i>	344.70	X
\$	<i>Sn</i>	394.68	X
\$	<i>DIY</i>	101.40	✓
\$	<i>Sn</i>	10.70	X
\$	<i>Sn</i>	292.50	X
\$	<i>Sn</i>	147.00	X
\$	<i>Sn</i>	207.21	X
\$	<i>R</i>	663.70	X
\$	<i>my car</i>	743.60	✓
\$	<i>R</i>	128.30	X
\$	<i>Bu</i>	437.10	✓
\$	<i>DIY</i>	191.40	✓
\$	<i>Sn</i>	11.80	} X
\$	<i>Sn</i>	80.70	
\$	<i>R</i>	106.40	
\$	<i>Sn</i>	66.30	
\$	<i>Sn</i>	60.90	
\$	<i>R</i>	177.22	
\$	<i>Sn</i>	969.90	
\$	<i>Sn</i>	225.36	
\$	<i>Sn</i>	686.00	
\$	<i>Sn R</i>	592.70	
\$	<i>R</i>	41.60	
\$	<i>R</i>	1,312.70	
\$	<i>Sn</i>	294.30	

Trans-cab Auto Services Pte Ltd**AAD2004-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H

1	BONNET STRUT RH	\$	53.30
1	BONNET HINGE RH	\$	237.40
1	BONNET LOCK	\$	152.80
1	LOWER ARM RH L70Y	\$	192.70
1	KNUCKLE ARM RH L70Y	\$	481.50
1	ABSORBER FRT RH L70Y	\$	203.50
1	ABSORBER MOUNTING KIT FRT RH	\$	273.60
1	DRIVESHAFT RH	\$	1,355.70
1	STABILIZER BAR FRT	\$	427.90
1	KNUCKLE HUB+BEARING RH L70Y	\$	272.30
1	STEERING PINION RACK L70Y	\$	3,765.30
1	WIPER RESERVOIR MOTOR	\$	82.60
1	WIPER RESERVOIR	\$	179.60
1	WIPER RESERVOIR NECK	\$	29.30
1	SUBFRAME OUTER FRT	\$	1,094.20
1	SUBFRAME BRACKET OUTER RH	\$	49.00
1	SUBFRAME INNER FRT L70Y	\$	746.00
1	SUBFRAME SUPPORT INNER L70Y	\$	69.50
1	SUBFRAME BRACKET INNER RH L70Y	\$	101.00
1	FENDER PANEL SUPPORT FRT RH	\$	432.00
1	FENDER PANEL INNER FRT RH	\$	838.40
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	DOOR PANEL FRT RH	\$	2,844.66
1	DOOR MIRROR ASSY RH	\$	1,483.40
1	DOOR HARNESS WIRE RH	\$	2,670.00
1	A/C CONDENSER	\$	1,537.80

TOTAL \$ 31,285.12**10% \$ 3,128.51****\$ 28,156.61***X S₂***Special Nett**

1 BUMPER CLIP FRT

\$

Mr 68.00 ✓

Trans-cab Auto Services Pte Ltd

AAD2004-088

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H

1 BUMPER BRACKET CLIP FRT RH	\$	nn	15.00	X
1 BUMPER SUPPORT CLIP FRT RH	\$	nn	15.00	X
1 BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2 FRAME FULL SUPPORT PANEL NUT	\$	nn	25.00	X
2 FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1 WHEELARCH CLIP FRT RH	\$	nn	35.00	✓
1 FRONT RENAULT TYRE	\$	Sh	300.00	} X
1SET Front licence plate with holder	\$	Sh	80.00	
1 FRONT RENAULT TYRE RIM	\$	Sh	380.00	
1SET RADIATOR GRILLE SCREW	\$	nn	20.00	
1SET RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	
1 FRONT RENAULT TYRE RIM COVER	\$	Sh	60.00	
1 Front Door Sticker "Trans-Cab"	\$	nn	80.00	
1 Front Door Sticker "Classic"	\$	nn	80.00	
1 Windscreen moulding	\$	nn	180.00	
2 FRONT WINDSCREEN SEALANT	\$	nn	150.00	
1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	120.00	
TOTAL	\$		1,829.00	

TOTAL PARTS \$ 29,985.61**LABOUR**

Putty and spray painting of the affected portion.	\$	7,500.00	4401
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	4001

Trans-cab Auto Services Pte Ltd**AAD2004-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H

To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	<i>nn</i>	380.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	<i>nn</i>	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nn</i>	380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i>	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 258H**AAD2004-088**

To rust-proofing of the affected areas.	\$	170.00	30%
To Check Electrical Lighting Concerned.	\$	170.00	20%
TOTAL	\$	18,860.00	
Over All Total	\$	48,845.61	

LUMP SUM (REPAIR DAY)~~25 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: