

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD	F	Ref:	CS4/ASM20005470/Dvy3e2	
	8 SHENTON WAY AXA TOWERSING		С	Date:	09/01/2023	
	ATTN: VALE OH		C	Code:	ASM	
1.	1. Policy Particulars :- OWN DAMAGE					
	Insured Veh.		Veh. Inspected		SKE 9898K	
	Policy No.	GA385315/1	Coverage (\$)		0.00	
	Claim No.	S0M02MH6	Excess (\$)		700.00	
	Assign From	VALE OH	Assign Date		29/04/2020	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ SL350	c.c		3498	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	WDB2304582F149888	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	245/40 R19	GOODYEAR		6 mm	
	L/H Front Tyre	245/40 R19	GOODYEAR		6 mm	
	R/H Rear Tyre	275/35 R19	GOODYEAR		6 mm	
	L/H Rear Tyre	275/35 R19	GOODYEAR		6 mm	
4.	Description of Damages					
	THE VEHICLE CAUGHT FIRE DUE TO ELECTRICAL ORIGIN OF THE REAR BOOT COMPARTMENT.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	15/04/2020	Inspection Date		29/04/2020	
	Survey held at	160 SIN MING DRIVE #05-02 CYCLE & CARRIAGE INDUSTRIES (1986) PL				
	Repairer					
5a.	Remarks					
	A)THE MARKET VALUE IS S\$90,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 24 Working Days					