



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

Finalization

# ESTIMATE FOR SKE9898K

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh  
#07-721  
Singapore 310215

Mobile: +6596662278

Bryan

## Vehicle & Document Information

WIP No 43219  
Reg No/Reg Date SKE9898K / 30/09/2008  
Date In/Mileage 07/07/2020/ 136152  
Chassis No WDB2304582F149888  
Engine No 27296831298168  
Make/Model MB/SL 350 (New Generation)  
Colour/Trim 021 197 Obsidian Bl/ 042 217 Leather Fla

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	27/09/2021/ 12:20	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN								
POLICY NO/ACC DATE :GA385315 // 15-04-2020								
DRIVE IN/EXCESS :10-06-2020 // \$700								
DATE IN/DATE SURVEY:25-06-2020 // LKK BRYAN								
BY/AUTHORIZED ON :VERON CHEN // 07-07-2020								
A BPILAB								480.00
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT								
A BPILAB								960.00
REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR								
A BPILAB								960.00
REMOVE VARIO ROOF HYDRAULIC AND CYLINDER FOR NECESSARY REPAIR								
A BPILAB								11300/13440.00
REMOVE,RECTIFY & INSTALL ELECTRONIC WIRING HARNESS SYSTEM.								
A BPILAB								300.00
REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL								
A BPILAB								480/1920.00
REMOVE & INSTALL INTERIOR GARNISH,SEAT AND UPHOLSTERY FOR NECESSARY REPAIR.								
A BPILAB								480 1920.00
REMOVE & INSTALL INSTRUMENT PANEL.								
A BPIRES								600.00
RESPRAY REAR BOOT LID								
X BPNEXC								-700.00
INSURANCE EXCESS								
* REAR SAM CONTROL UNIT					1.00	3033.40	00.00	3033.40
* REAR COMPARTMENT SPRING FOR VARIO ROOF					1.00	171.39	00.00	171.39
* REAR VARIO ROOF PUMP					1.00	5777.16	00.00	5777.16
* REAR VARIO ROOF PUMP TOP COVER					1.00	98.42	00.00	98.42
* HYDRAULIC LINE CYLINDER					1.00	753.31	00.00	753.31
* HYDRAULIC LINE CYLINDER					1.00	753.31	00.00	753.31
* HYDRAULIC LINE CYLINDER					1.00	1043.01	00.00	1043.01

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SKE9898K

Finalization

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh  
#07-721  
Singapore 310215

Mobile: +6596662278

WIP No

43219

Reg No/Reg Date

SKE9898K / 30/09/2008

Date In/Mileage

07/07/2020/ 136152

Chassis No

WDB2304582F149888

Engine No

27296831298168

Make/Model

MB/SL 350 (New Generation)

Colour/Trim

021 197 Obsidian Bl/ 042 217 Leather Fla

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	27/09/2021/ 12:20	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X HYDRAULIC LINE CYLINDER					1.00	1043.01	00.00	1043.01
X HYDRAULIC LINE CYLINDER					1.00	753.31	00.00	753.31
X HYDRAULIC LINE CYLINDER					1.00	753.31	00.00	753.31
X HYDRAULIC LINE CYLINDER					1.00	579.43	00.00	579.43
X HYDRAULIC LINE CYLINDER					1.00	579.43	00.00	579.43
X HYDRAULIC LINE CYLINDER					1.00	1101.03	00.00	1101.03
X HYDRAULIC LINE CYLINDER					1.00	753.31	00.00	753.31
X HYDRAULIC LINE CYLINDER					1.00	1101.03	00.00	1101.03
X RH/R BOOT COMPARTMENT TRIM					1.00	582.10	00.00	582.10
X CT/R BOOT COMPARTMENT TRIM					1.00	515.03	00.00	515.03
X FRONT FLOOR WIRING HARNESS					1.00	6999.42	00.00	6999.42
X REAR VARIO ROOF PANEL TRIM					1.00	772.09	00.00	772.09
X REAR BOOT LID ELECTRIC MOTOR					1.00	1773.79	00.00	1773.79
X REAR SOFT TOP COVER					1.00	6522.90	00.00	6522.90
X REAR SOFT TOP END COVER					1.00	1889.65	00.00	1889.65
X HEADLINER					1.00	986.05	00.00	986.05
X RIGHT C PILLAR INNER TRIM					1.00	507.87	00.00	507.87
X LEFT C PILLAR INNER TRIM					1.00	507.87	00.00	507.87
X PARTITION PANEL					1.00	1293.31	00.00	1293.31
X INFORMATION LABEL					1.00	38.51	00.00	38.51
X RH/R BOOT LID HINGE					1.00	668.74	00.00	668.74
X PROFILE SEAL					1.00	20.98	00.00	20.98
X FUELING LABEL					1.00	39.20	00.00	39.20
X AUXILIARY PUMP					1.00	1066.47	00.00	1066.47
X FUEL FILTER					1.00	303.50	00.00	303.50
X RIVET					4.00	2.95	00.00	11.80
X LOOM TIE					1.00	5.50	00.00	5.50
X LOOM TIE					3.00	4.37	00.00	13.11
X PLUG					1.00	5.15	00.00	5.15
X CLAMP					4.00	6.75	00.00	27.00
X CLAMP					4.00	1.01	00.00	4.04
X STOPPER WASHER PLUG					1.00	3.99	00.00	3.99
X BOOT PLUG					1.00	12.60	00.00	12.60

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-6500111-X

Finalization

## ESTIMATE FOR SKE9898K

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh  
#07-721  
Singapore 310215

Mobile: +6596662278

### Vehicle & Document Information

WIP No **43219**  
Reg No/Reg Date **SKE9898K / 30/09/2008**  
Date In/Mileage **07/07/2020/ 136152**  
Chassis No **WDB2304582F149888**  
Engine No **27296831298168**  
Make/Model **MB/SL 350 (New Generation)**  
Colour/Trim **021 197 Obsidian Bl/ 042 217 Leather Fla**

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	27/09/2021/ 12:20	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X RIVET					6.00	3.68	00.00	22.08
X NUT					1.00	6.75	00.00	6.75
X HEAD BOLT					1.00	0.97	00.00	0.97
X FUEL STRAINER					1.00	61.98	00.00	61.98
X RUBBER PLUG					1.00	15.52	00.00	15.52
X CLIP					1.00	9.77	00.00	9.77
X FRT SAM CONTROL UNIT RELAY					1.00	92.11	00.00	92.11
X FUEL HOSE					1.00	143.44	00.00	143.44
X FUEL TANK					1.00	3677.70	00.00	3677.70
X HOSE					1.00	27.05	00.00	27.05
X HOSE					1.00	15.33	00.00	15.33
X HOSE					1.00	28.68	00.00	28.68
X REAR CONTROL UNIT BOTTOM PLATE BRACKET					1.00	274.78	00.00	274.78
X REAR CONTROL UNIT SIDE PLATE BRACKET					1.00	109.98	00.00	109.98
X INFORMATION LABEL					1.00	15.68	00.00	15.68
X INFORMATION LABEL					1.00	44.11	00.00	44.11
X FUEL TANK RECESS HOLDER					1.00	90.76	00.00	90.76
X RH/R INSULATION SIDE BOTTOM COVERING					1.00	1347.38	00.00	1347.38
X RH/F CAN BUS LOW VOLATE WIRING					1.00	358.12	00.00	358.12
X FUEL TANK FRONT DAMPENING					1.00	103.79	00.00	103.79
X FUEL TANK TOP DAMPENING					1.00	275.53	00.00	275.53
X FUEL TANK REAR DAMPENING					1.00	17.94	00.00	17.94
X FUEL TANK RIGHT SIDE DAMPENING					1.00	60.97	00.00	60.97
X FUEL TANK LEFT TOP & BOTTOM DAMPENING					2.00	60.97	00.00	121.94
X ROOF TRIM					1.00	1066.03	00.00	1066.03
X BOOT LID INNER TRIM					1.00	617.57	00.00	617.57
X REAR END PANEL TRIM GARNISH					1.00	161.53	00.00	161.53
X RH/R BOOT LID SIDE TRIM					1.00	124.43	00.00	124.43
X SPARE TYRE TIGHTENER					1.00	91.76	00.00	91.76
X RH/R CAN BUS HIGH VOLTAGE WIRING					1.00	456.01	00.00	456.01
X RH/R BOOTL ID SOFT TOP FLAP COVERING					1.00	466.53	00.00	466.53
X STOPPER RUBBER PLUG					2.00	40.43	00.00	80.86
X RH/R SOFT TOP HINGH					1.00	625.58	00.00	625.58

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKE9898K

### Finalization

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh  
#07-721  
Singapore 310215

Mobile: +6596662278

#### Vehicle & Document Information

WIP No **43219**  
Reg No/Reg Date **SKE9898K / 30/09/2008**  
Date In/Mileage **07/07/2020/ 136152**  
Chassis No **WDB2304582F149888**  
Engine No **27296831298168**  
Make/Model **MB/SL 350 (New Generation)**  
Colour/Trim **021 197 Obsidian Bl/ 042 217 Leather Fla**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	27/09/2021/ 12:20	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RH/R FENDER AIR FLAP	1.00	281.69	00.00	281.69
X FUSE	1.00	13.26	00.00	13.26
X FUSE	1.00	13.26	00.00	13.26
X NUT	14.00	3.96	00.00	55.44
X RH/R SOFT TOP HINGH SPRING	1.00	112.12	00.00	112.12
X INSULATION	1.00	38.98	00.00	38.98
X PIPE LINE (P/S:25)	5.00	8.17	00.00	40.85
X ELECTRIC LINE	1.00	599.10	00.00	599.10
X FRT WIRING HARNESS	1.00	229.79	00.00	229.79
X ELECTRIC LINE	1.00	241.45	00.00	241.45
X ELECTRIC LINE	1.00	76.56	00.00	76.56
X ELECTRIC LINE	1.00	380.14	00.00	380.14
X ELECTRIC LINE	1.00	381.99	00.00	381.99
X RELAY	1.00	130.78	00.00	130.78
X REAR WIRING HARNESS	1.00	1664.72	00.00	1664.72
X VACCUM HOSE	10.00	9.90	00.00	99.00
X PLUG	1.00	8.17	00.00	8.17
X COUPLING	3.00	9.30	00.00	27.90
X COUPLING	1.00	9.20	00.00	9.20
X FRONT WIRING HARNESS	1.00	847.20	00.00	847.20

burnt

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cvcicarriage.com.sg

Confirmed & accepted by

Nett 78,608.79  
7% GST on 78608.79 5502.62

Authorized signatory and company stamp

Total Payable 84,111.41

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg