

ASS. REC. BY:

CS4/ASM200054701 Dvf3

ASSIGNMENT

CDE Sept 2028

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. **SOM02MH6**Sum Insured: _____ Excess: **700**

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **24** days Res.: Yes or NoLum Sum: **24** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SKE 98981C** Yr Regn: **2008/Sept**Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Mercedes Benz SL350** c.c. **3497**Colour: **Black** A/C: Insured / Std / NI / NASp. Reading: **N-A.** T/Radio: Insured / Std / NI / NAEng/No: **27296831298168**C/No: **WDB2304582F149888**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **245/40 R19**R: **276/35 R19**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Goodyear**

Front

Rear

R/Bal. **6** mm R/Bal. **6** mmL/Bal. **6** mm L/Bal. **6** mmD.O.A. **15/04/2020** D.O.I. **29/04/2020**Survey held at **Trendy Automotive 160 s/Ming**Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or **#05-02****The vehicle caught fire. due to**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AXA OD Fire case. electrical origin of the rear boot
	10K compartment.
	MV 90K using to depreciation.
	LTA 28K
	HL 72K
	62K
	No estimate as owner KIV OD claim first.
27/12/22	Repair Sum \$62,000 (Red 17,308.79, 22%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

: Final Report

Date/Time, File Return to?

2) **27/12/22-typist**Days Of Repair: **24**Resurvey No. of Trip: **1**

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S+RS SI

Photos

Others

investigation

500

TOTAL

Report Format : **OD**Lump Sum / I.B.I. (\$ **RS \$62,000**)

Annex A

Transaction ref 20180727135216269382

The owner and vehicle particulars for Vehicle No. SKE9898K as at 27 Jul 2018 are as follows:

1. Name	: ANG BOON HOCK
2. Identification No. Type	: Singapore NRIC
3. Identification No.	: S1417709D
4. Country/Region	: -
5. Vehicle No.	: SKE9898K
6. Previous Vehicle No.	: -
7. Effective Date of Ownership	: 27 Jul 2018
8. Original Registration Date	: 30 Sep 2008
9. First Registration Date	: 30 Sep 2008
10. Vehicle Type	: P10 - Passenger Motor Car
11. Vehicle Scheme	: Normal
12. Attachment 1	: No Attachment
13. Attachment 2	: -
14. Attachment 3	: -
15. Vehicle Make	: MERCEDES BENZ
16. Vehicle Model	: SL350
17. Year of Manufacture	: 2008
18. Primary Colour	: Black
19. Secondary Colour	: -
20. Passenger Capacity	: 1
21. Chassis/Trailer Chassis No.	: WDB2304582F149888 / -
22. Propellant	: Petrol
23. Engine No./Motor No.	: 27296831298168 / -
24. Engine Capacity(cc)/Power Rating(kW)	: 3498 / -
25. Maximum Power Output(kW/bhp)	: 232.0 / 311
26. Unladen Weight(kg)	: 1825

Annex A

Transaction ref 20180727135216269382

The owner and vehicle particulars for Vehicle No. SKE9898K as at 27 Jul 2018 are as follows:

27. Maximum Laden Weight(kg)	: 2120
28. Open Market Value	: \$120,289.00
29. PARF Eligibility	: Yes
30. PARF Eligibility Expiry Date	: 29 Sep 2018
31. Minimum PARF Benefit	: \$60,144.00
32. No. of Transfers	: 2
33. IU Label No.	: 1124760439
34. COE No.	: 2008090103001276R
35. COE Expiry Date	: 29 Sep 2018
36. COE Category	: B - Car (1601cc & above)
37. Quota Premium/Prevailing Quota Premium	: \$13,890.00 / -
38. Actual Quota Premium/PQP Paid	: \$13,890.00
39. Actual ARF Paid	: \$120,289.00
40. CO2 Emission(g/km)	: -
41. CO Emission(g/km)	: -
42. HC Emission(g/km)	: -
43. NOx Emission(g/km)	: -
44. PM Emission(mg/km)	: -
45. Actual CEVS/VES Rebate Utilised	: -
46. CEVS/VES Surcharge Paid	: -
47. Actual Green Vehicle Rebate Utilised	: -
48. Vehicle Lifespan Expiry Date	: -
49. Road Tax Amount	: -
50. Road Tax Start Date	: -
51. Road Tax End Date	: -
52. Remarks	: To renew the COE, the Prevailing Quota Premium payable is that of Category B. The PARF eligibility of the vehicle will expire on 29 Sep 2018.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/04/2020 15:37
Date Of Accident	15/04/2020 15:45
Exact Location Of Accident	BLK 215 LORONG 8 TOA PAYOH OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE9898K
Insured/Policyholder	
Name Of Registered Owner	ANG BOON HOCK
NRIC No	SXXXX709D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96618677
Alternative Phone No	OFFICE-96618677

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	SL350-3.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA385315/1
Cover Note Number	

Driver

Name of Driver	ANG BOON HOCK
NRIC No	SXXXX709D
Date Of Birth	09/11/1960
Occupation	INDOOR
Date Of Driving Pass	31/12/1981
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96618677
Fax Number	
Contact Number	OFFICE-96618677
Email Address	NOEMAIL

Address	BLK 215 LORONG 8 TOA PAYOH #07-721
Postcode	310215
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN. DRIVING PASS DATE ESTIMATED 31 DEC 1981 (PER CLIENT).

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN


NO SKETCH

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY VEHICLE WAS PARKED AT MY HOME
OPEN CARPARK. MY DAUGHTER WENT DOWN
AND WANTED TO UNLOCK TO TAKE SOME
THINGS ON 15.4.2020 AND COULD NOT
UNLOCK. SHE SAW SMOKE FROM INSIDE THE
CAR AND SHE SCDF.
MY VEHICLE WAS TOWED TO MY OWN
WORKSHOP WORKSHOP TRENDY AUTOMOTIVE ON
THE SAME DATE.
I AM WAITING FOR MERCEDES AGENT TO
REPLY ME BEFORE I DECIDE TO DO OWN
DAMAGE OR WHERE TO REPAIR.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 17/4/20 @ 2p
 Policyholder's Signature
 Date & Time:
 Company Chop (if applicable)

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:





Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE9898K

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh
#07-721
Singapore 310215

Mobile: +6596662278

Vehicle & Document Information

WIP No **43219**
Reg No/Reg Date **SKE9898K / 30/09/2008**
Date In/Mileage **0**
Chassis No **WDB2304532F149888**
Engine No **27296831298168**
Make/Model **MB/SL 350 (New Generation)**
Colour/Trim **021 197 Obsidian Bl/ 042 217 Leather Fla**

Account No	Terms	Date/Time Printed	CSE	Operator	
CSM00128	Cash	22/06/2020/ 12:59	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 6A385315 // 15-04-2020

DRIVE IN/EXCESS : 10-06-2020 // TBA

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR

A BPILAB

REMOVE VARIO ROOF HYDRAULIC AND CYLINDER FOR NECESSARY REPAIR

A BPILAB

REMOVE & INSTALL INTERIOR GARNISH, SEAT AND UPHOLSTERY
FOR NECESSARY REPAIR.

A BPILAB

"REMOVE, RECTIFY & INSTALL ELECTRONIC WIRING HARNESS SYSTEM.

"

M CONTROL UNIT *Burnt*

M SPRING

M PUMP

M COVER

M CYLINDER

M CYLINDER

M CYLINDER

M CYLINDER

M CYLINDER

M CYLINDER

M CYLINDER

M CYLINDER

M CYLINDER

M CYLINDER

M CYLINDER

M CYLINDER

480.00 Nec

1440.00 960

? 1440.00 960

? 1920.00 1440

3day 4800.00 2880

ESTIMATE

M CONTROL UNIT <i>Burnt</i>	1.00	3033.40	00.00	3033.40	✓
M SPRING	1.00	171.39	00.00	171.39	✓
M PUMP	1.00	5777.16	00.00	5777.16	✓
M COVER	1.00	98.42	00.00	98.42	✓
M CYLINDER	1.00	753.31	00.00	753.31	✓
M CYLINDER	1.00	753.31	00.00	753.31	✓
M CYLINDER	1.00	1043.01	00.00	1043.01	✓
M CYLINDER	1.00	1043.01	00.00	1043.01	✓
M CYLINDER	1.00	753.31	00.00	753.31	✓
M CYLINDER	1.00	753.31	00.00	753.31	✓
M CYLINDER	1.00	579.43	00.00	579.43	✓
M CYLINDER	1.00	579.43	00.00	579.43	✓
M CYLINDER	1.00	1101.03	00.00	1101.03	✓
M CYLINDER	1.00	753.31	00.00	753.31	✓
M CYLINDER	1.00	1101.03	00.00	1101.03	✓

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE9898K

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh
#07-721
Singapore 310215

Mobile: +6596662278

Vehicle & Document Information

WIP No	43219
Reg No/Reg Date	SKE9898K / 30/09/2008
Date In/Mileage	0
Chassis No	WDB2304582F149888
Engine No	27296831298168
Make/Model	MB/SL 350 (New Generation)
Colour/Trim	021 197 Obsidian Bl/ 042 217 Leather Fla

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	22/06/2020/ 12:59	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M TRIM <i>Burnt</i>	1.00	582.10	00.00	582.10
M PANEL LINING <i>Burnt</i>	1.00	487.26	00.00	487.26
M WIRING HARNESS <i>Burnt</i>	1.00	6895.97	00.00	6895.97
M TRIM	1.00	772.09	00.00	772.09
M ELECTRIC MOTOR <i>Burnt (huge)</i>	1.00	1773.79	00.00	1773.79
M COVER	1.00	6522.90	00.00	6522.90
M COVER	1.00	1889.65	00.00	1889.65
M TRIM	1.00	986.05	00.00	986.05
M TRIM	1.00	507.87	00.00	507.87
M TRIM	1.00	507.87	00.00	507.87
M PIPE LINE (P/S:25) <i>Burnt (door lock) yellow</i>	5.00	8.01	00.00	40.05
M PARTITION PANEL <i>Burnt</i>	1.00	1293.31	00.00	1293.31
M INFORMATION LABEL	1.00	38.51	00.00	38.51
M HINGE <i>Burnt</i>	1.00	668.74	00.00	668.74

ESTIMATE

25/06/2020

yn
2 KK Andu

Not Antenn
Photo

redway
all plange
Parts.
10 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DD: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by
Signature:
Date:

Nett 51,340.02
7% GST on 51340.02 3593.80
Total Payable 54,933.82

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE9898K

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh
#07-721
Singapore 310215

Mobile: +6596662278

Vehicle & Document Information

WIP No **43219**
Reg No/Reg Date **SKE9898K / 30/09/2008**
Date In/Mileage **07/07/2020/ 136152**
Chassis No **WDB2304582F149888**
Engine No **27296831298168**
Make/Model **MB/SL 350 (New Generation)**
Colour/Trim **021 197 Obsidian Bl/ 042 217 Leather Fla**

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	15/09/2020/ 11:14	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN								
POLICY NO/ACC DATE : GA385315 // 15-04-2020								
DRIVE IN/EXCESS : 10-06-2020 // \$700								
DATE IN/DATE SURVEY: 25-06-2020 // LKK BRYAN								
BY/AUTHORIZED ON : VERON CHEN // 07-07-2020								
A BPILAB								480.00
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT								
A BPILAB								960.00
REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR								
A BPILAB								960.00
REMOVE VARIO ROOF HYDRAULIC AND CYLINDER FOR NECESSARY REPAIR								
A BPILAB								3840.00
REMOVE, RECTIFY & INSTALL ELECTRONIC WIRING HARNESS SYSTEM.								
S	REAR SAM CONTROL UNIT	Brnt			1.00	3033.40	00.00	3033.40
S	REAR COMPARTMENT SPRING FOR VARIO ROOF	Brnt			1.00	171.39	00.00	171.39
S	REAR VARIO ROOF PUMP	hose leaks			1.00	5777.16	00.00	5777.16
S	REAR VARIO ROOF PUMP TOP COVER	NA			1.00	98.42	00.00	98.42
S	CYLINDER				1.00	753.31	00.00	753.31
S	CYLINDER				1.00	753.31	00.00	753.31
V	CYLINDER				1.00	1043.01	00.00	1043.01
R	CYLINDER				1.00	1043.01	00.00	1043.01
S	CYLINDER				1.00	753.31	00.00	753.31
S	CYLINDER				1.00	753.31	00.00	753.31
S	CYLINDER				1.00	579.43	00.00	579.43
S	CYLINDER				1.00	579.43	00.00	579.43
S	CYLINDER				1.00	1101.03	00.00	1101.03
S	CYLINDER				1.00	753.31	00.00	753.31
S	CYLINDER				1.00	1101.03	00.00	1101.03
S	RH/R BOOT COMPARTMENT TRIM	Brnt			1.00	582.10	00.00	582.10
V	CT/R BOOT COMPARTMENT TRIM	Brnt			1.00	487.26	00.00	487.26
V	WIRING HARNESS	Brnt			1.00	6895.97	00.00	6895.97

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE9898K

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh
#07-721
Singapore 310215

Mobile: +6596662278

Vehicle & Document Information

WIP No **43219**
Reg No/Reg Date **SKE9898K / 30/09/2008**
Date In/Mileage **07/07/2020/ 136152**
Chassis No **WDB2304582F149888**
Engine No **27296831298168**
Make/Model **MB/SL 350 (New Generation)**
Colour/Trim **021 197 Obsidian Bl/ 042 217 Leather Fla**

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	15/09/2020/ 11:14	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
V	REAR VARIO ROOF PANEL TRIM	3vnt.			1.00	772.09	00.00	772.09
S	ELECTRIC MOTOR				1.00	1773.79	00.00	1773.79
V	REAR SOFT TOP COVER	4M			1.00	6522.90	00.00	6522.90
V	REAR SOFT TOP END COVER	4M			1.00	1889.65	00.00	1889.65
V	HEADLINER	4M			1.00	986.05	00.00	986.05
V	RIGHT C PILLAR INNER TRIM	Bond			1.00	507.87	00.00	507.87
V	LEFT C PILLAR INNER TRIM	nm			1.00	507.87	00.00	507.87
R	PIPE LINE (P/S:25)	most meet your.			5.00	8.01	00.00	40.05
V	PARTITION PANEL	?			1.00	1293.31	00.00	1293.31
S	INFORMATION LABEL	the			1.00	38.51	00.00	38.51
V	HINGE	1st Brnt			1.00	668.74	00.00	668.74
S	PROFILE SEAL	the			1.00	20.58	00.00	20.58
R	FUELING LABEL	the			1.00	38.39	00.00	38.39
S	AUXILIARY PUMP	MA			1.00	1050.70	00.00	1050.70
S	FUEL FILTER	the			1.00	297.26	00.00	297.26
R	[STR] RIVET	the			4.00	2.92	00.00	11.68
R	LOOM TIE	the			1.00	5.40	00.00	5.40
R	LOOM TIE	the			3.00	4.15	00.00	12.45
S	BINDER	the			1.00	5.09	00.00	5.09
V	CLAMP	the			4.00	1.01	00.00	4.04
S	STOPPER WASHER	the			1.00	3.93	00.00	3.93
S	BOOT	the			1.00	12.41	00.00	12.41
S	RIVET	the			6.00	3.61	00.00	21.66
S	BINDER	the			1.00	6.66	00.00	6.66
S	THD. ROLLING, HEAD BOLT	the			1.00	0.94	00.00	0.94
S	TS FUEL STRAINER	the			1.00	60.75	00.00	60.75
S	BOOT	the			1.00	15.30	00.00	15.30
S	GUIDE, RELEASE HANDLE				1.00	9.55	00.00	9.55
S	HANDLE				1.00	78.97	00.00	78.97
S	FUEL HOSE	the			1.00	140.61	00.00	140.61
S	FUEL TANK	Brnt.			1.00	3605.57	00.00	3605.57
S	HOSE	the			1.00	26.51	00.00	26.51
S	HOSE	the } fuel			1.00	15.02	00.00	15.02

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-B500111-X

ESTIMATE FOR SKE9898K

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh
#07-721
Singapore 310215

Mobile: +6596662278

Vehicle & Document Information

WIP No 43219
Reg No/Reg Date SKE9898K / 30/09/2008
Date In/Mileage 07/07/2020/ 136152
Chassis No WDB2304582F149888
Engine No 27296831298168
Make/Model MB/SL 350 (New Generation)
Colour/Trim 021 197 Obsidian Bl/ 042 217 Leather Fla

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	15/09/2020/ 11:14	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S HOSE	hlc				1.00	28.12	00.00	28.12
V BRACKET	hlc				1.00	270.73	00.00	270.73
V BRACKET	hlc				1.00	108.35	00.00	108.35
S INFORMATION LABEL	hlc				1.00	0.63	00.00	0.63
V PLATE					1.00	43.19	00.00	43.19
S RECESS					1.00	88.90	00.00	88.90
S RIGHT DASHBOARD UNDER COVER	hlc				1.00	1327.46	00.00	1327.46
V RAIL					1.00	329.60	00.00	329.60
V DAMPENING	hlc				1.00	101.69	00.00	101.69
V DAMPENING	hlc				1.00	269.88	00.00	269.88
V DAMPENING	hlc				1.00	17.59	00.00	17.59
V DAMPENING	hlc				1.00	59.75	00.00	59.75
V DAMPENING	hlc				2.00	59.75	00.00	119.50
V ROOF TRIM FRONT ABOVE W/SCREEN	hlc				1.00	1044.11	00.00	1044.11
V BOOT LID INNER TRIM	hlc				1.00	582.10	00.00	582.10
S REAR END PANEL TRIM GARNISH	hlc				1.00	158.20	00.00	158.20
S RIGHT REAR BOOT SIDE TRIM	hlc				1.00	121.89	00.00	121.89
S SPARE TYRE TIGHTENER	hlc				1.00	90.06	00.00	90.06
V RIGHT DOOR EDGE COVER	hlc				1.00	416.68	00.00	416.68
S RIGHT REAR SOFT TOP FLAP COVERING	hlc				1.00	456.95	00.00	456.95
V STOP	hlc				2.00	39.61	00.00	79.22
S PLUG	hlc				1.00	612.70	00.00	612.70
V REAR RIGHT FLAP	hlc				1.00	114.28	00.00	114.28
V COVERING	hlc				1.00	13.07	00.00	13.07
V COVERING	hlc				1.00	13.07	00.00	13.07
M HEXAGON NUT	hlc				14.00	1.04	00.00	14.56

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cvclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett** 59,425.77
4159.80

Authorized signatory and company stamp

Total Payable 63,585.57

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SKE9898K

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh
#07-721
Singapore 310215

Mobile: +6596662278

Bryan

Vehicle & Document Information

WIP No 43219
Reg No/Reg Date SKE9898K / 30/09/2008
Date In/Mileage 07/07/2020/ 136152
Chassis No WDB2304582F149888
Engine No 27296831298168
Make/Model MB/SL 350 (New Generation)
Colour/Trim 021 197 Obsidian Bl/ 042 217 Leather Fla

Account No	Terms	Date/Time Printed	CSE	Operator					
CSM00128	Cash	27/09/2021/ 12:20	AQ	305 / Alan Quek Ai Lun					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
M BPNSUN									
POLICY NO/ACC DATE :GA385315 // 15-04-2020									
DRIVE IN/EXCESS :10-06-2020 // \$700									
DATE IN/DATE SURVEY:25-06-2020 // LKK BRYAN									
BY/AUTHORIZED ON :VERON CHEN // 07-07-2020									
A BPILAB								480.00	
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT									
A BPILAB								960.00	
REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR									
A BPILAB								960.00	
REMOVE VARIO ROOF HYDRAULIC AND CYLINDER FOR NECESSARY REPAIR									
A BPILAB								11800	13440.00
REMOVE,RECTIFY & INSTALL ELECTRONIC WIRING HARNESS SYSTEM.									
A BPILAB								300.00	
REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL									
A BPILAB								480	1920.00
REMOVE & INSTALL INTERIOR GARNISH,SEAT AND UPHOLSTERY FOR NECESSARY REPAIR.									
A BPILAB								480	1920.00
REMOVE & INSTALL INSTRUMENT PANEL.									
A BPIRES								600.00	
RESPRAY REAR BOOT LID									
X BPNEXC								-700.00	
INSURANCE EXCESS									
* REAR SAM CONTROL UNIT					1.00	3033.40	00.00	3033.40	
* REAR COMPARTMENT SPRING FOR VARIO ROOF					1.00	171.39	00.00	171.39	
* REAR VARIO ROOF PUMP					1.00	5777.16	00.00	5777.16	
* REAR VARIO ROOF PUMP TOP COVER					1.00	98.42	00.00	98.42	burnt
* HYDRAULIC LINE CYLINDER					1.00	753.31	00.00	753.31	
* HYDRAULIC LINE CYLINDER					1.00	753.31	00.00	753.31	
* HYDRAULIC LINE CYLINDER					1.00	1043.01	00.00	1043.01	

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE9898K

Finalization

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh
#07-721
Singapore 310215

Mobile: +6596662278

WIP No

43219

Reg No/Reg Date

SKE9898K / 30/09/2008

Date In/Mileage

07/07/2020/ 136152

Chassis No

WDB2304582F149888

Engine No

27296831298168

Make/Model

MB/SL 350 (New Generation)

Colour/Trim

021 197 Obsidian Bl/ 042 217 Leather Fla

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	27/09/2021/ 12:20	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X HYDRAULIC LINE CYLINDER	1.00	1043.01	00.00	1043.01
X HYDRAULIC LINE CYLINDER	1.00	753.31	00.00	753.31
X HYDRAULIC LINE CYLINDER	1.00	753.31	00.00	753.31
X HYDRAULIC LINE CYLINDER	1.00	579.43	00.00	579.43
X HYDRAULIC LINE CYLINDER	1.00	579.43	00.00	579.43
X HYDRAULIC LINE CYLINDER	1.00	1101.03	00.00	1101.03
X HYDRAULIC LINE CYLINDER	1.00	753.31	00.00	753.31
X HYDRAULIC LINE CYLINDER	1.00	1101.03	00.00	1101.03
X RH/R BOOT COMPARTMENT TRIM	1.00	582.10	00.00	582.10
X CT/R BOOT COMPARTMENT TRIM	1.00	515.03	00.00	515.03
X FRONT FLOOR WIRING HARNESS	1.00	6999.42	00.00	6999.42
X REAR VARIO ROOF PANEL TRIM	1.00	772.09	00.00	772.09
X REAR BOOT LID ELECTRIC MOTOR	1.00	1773.79	00.00	1773.79
X REAR SOFT TOP COVER	1.00	6522.90	00.00	6522.90
X REAR SOFT TOP END COVER	1.00	1889.65	00.00	1889.65
X HEADLINER	1.00	986.05	00.00	986.05
X RIGHT C PILLAR INNER TRIM	1.00	507.87	00.00	507.87
X LEFT C PILLAR INNER TRIM	1.00	507.87	00.00	507.87
X PARTITION PANEL	1.00	1293.31	00.00	1293.31
X INFORMATION LABEL	1.00	38.51	00.00	38.51
X RH/R BOOT LID HINGE	1.00	668.74	00.00	668.74
X PROFILE SEAL	1.00	20.98	00.00	20.98
X FUELING LABEL	1.00	39.20	00.00	39.20
X AUXILIARY PUMP	1.00	1066.47	00.00	1066.47
X FUEL FILTER	1.00	303.50	00.00	303.50
X RIVET	4.00	2.95	00.00	11.80
X LOOM TIE	1.00	5.50	00.00	5.50
X LOOM TIE	3.00	4.37	00.00	13.11
X PLUG	1.00	5.15	00.00	5.15
X CLAMP	4.00	6.75	00.00	27.00
X CLAMP	4.00	1.01	00.00	4.04
X STOPPER WASHER PLUG	1.00	3.99	00.00	3.99
X BOOT PLUG	1.00	12.60	00.00	12.60

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SKE9898K

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh
#07-721
Singapore 310215

Mobile: +6596662278

Vehicle & Document Information

WIP No **43219**
Reg No/Reg Date **SKE9898K / 30/09/2008**
Date In/Mileage **07/07/2020/ 136152**
Chassis No **WDB2304582F149888**
Engine No **27296831298168**
Make/Model **MB/SL 350 (New Generation)**
Colour/Trim **021 197 Obsidian Bl/ 042 217 Leather Fla**

Account No	Terms	Date/Time Printed	CSE	Operator	
CSM00128	Cash	27/09/2021/ 12:20	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X RIVET		6.00	3.68	00.00	22.08
X NUT		1.00	6.75	00.00	6.75
X HEAD BOLT		1.00	0.97	00.00	0.97
X FUEL STRAINER		1.00	61.98	00.00	61.98
X RUBBER PLUG		1.00	15.52	00.00	15.52
X CLIP		1.00	9.77	00.00	9.77
X FRT SAM CONTROL UNIT RELAY		1.00	92.11	00.00	92.11
X FUEL HOSE		1.00	143.44	00.00	143.44
X FUEL TANK		1.00	3677.70	00.00	3677.70
X HOSE		1.00	27.05	00.00	27.05
X HOSE		1.00	15.33	00.00	15.33
X HOSE		1.00	28.68	00.00	28.68
X REAR CONTROL UNIT BOTTOM PLATE BRACKET		1.00	274.78	00.00	274.78
X REAR CONTROL UNIT SIDE PLATE BRACKET		1.00	109.98	00.00	109.98
X INFORMATION LABEL		1.00	15.68	00.00	15.68
X INFORMATION LABEL		1.00	44.11	00.00	44.11
X FUEL TANK RECESS HOLDER		1.00	90.76	00.00	90.76
X RH/R INSULATION SIDE BOTTOM COVERING		1.00	1347.38	00.00	1347.38
X RH/F CAN BUS LOW VOLATE WIRING		1.00	358.12	00.00	358.12
X FUEL TANK FRONT DAMPENING		1.00	103.79	00.00	103.79
X FUEL TANK TOP DAMPENING		1.00	275.53	00.00	275.53
X FUEL TANK REAR DAMPENING		1.00	17.94	00.00	17.94
X FUEL TANK RIGHT SIDE DAMPENING		1.00	60.97	00.00	60.97
X FUEL TANK LEFT TOP & BOTTOM DAMPENING		2.00	60.97	00.00	121.94
X ROOF TRIM		1.00	1066.03	00.00	1066.03
X BOOT LID INNER TRIM		1.00	617.57	00.00	617.57
X REAR END PANEL TRIM GARNISH		1.00	161.53	00.00	161.53
X RH/R BOOT LID SIDE TRIM		1.00	124.43	00.00	124.43
X SPARE TYRE TIGHTENER		1.00	91.76	00.00	91.76
X RH/R CAN BUS HIGH VOLTAGE WIRING		1.00	456.01	00.00	456.01
X RH/R BOOTL ID SOFT TOP FLAP COVERING		1.00	466.53	00.00	466.53
X STOPPER RUBBER PLUG		2.00	40.43	00.00	80.86
X RH/R SOFT TOP HINGH		1.00	625.58	00.00	625.58

burnt

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE9898K

Finalization

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh
#07-721
Singapore 310215

Mobile: +6596662278

Vehicle & Document Information

WIP No **43219**
Reg No/Reg Date **SKE9898K / 30/09/2008**
Date In/Mileage **07/07/2020/ 136152**
Chassis No **WDB2304582F149888**
Engine No **27296831298168**
Make/Model **MB/SL 350 (New Generation)**
Colour/Trim **021 197 Obsidian Bl/ 042 217 Leather Fla**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	27/09/2021/ 12:20	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RH/R FENDER AIR FLAP	1.00	281.69	00.00	281.69
X FUSE	1.00	13.26	00.00	13.26
X FUSE	1.00	13.26	00.00	13.26
X NUT	14.00	3.96	00.00	55.44
X RH/R SOFT TOP HINGH SPRING	1.00	112.12	00.00	112.12
X INSULATION	1.00	38.98	00.00	38.98
X PIPE LINE (P/S:25)	5.00	8.17	00.00	40.85
X ELECTRIC LINE	1.00	599.10	00.00	599.10
X FRT WIRING HARNESS	1.00	229.79	00.00	229.79
X ELECTRIC LINE	1.00	241.45	00.00	241.45
X ELECTRIC LINE	1.00	76.56	00.00	76.56
X ELECTRIC LINE	1.00	380.14	00.00	380.14
X ELECTRIC LINE	1.00	381.99	00.00	381.99
X RELAY	1.00	130.78	00.00	130.78
X REAR WIRING HARNESS	1.00	1664.72	00.00	1664.72
X VACCUM HOSE	10.00	9.90	00.00	99.00
X PLUG	1.00	8.17	00.00	8.17
X COUPLING	3.00	9.30	00.00	27.90
X COUPLING	1.00	9.20	00.00	9.20
X FRONT WIRING HARNESS	1.00	847.20	00.00	847.20

burnt

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
OID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cvclecarriage.com.sg

Confirmed & accepted by

Nett **78,608.79**
7% GST on **78608.79** **5502.62**

Total Payable **84,111.41**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SKE9898K

Ang Boon Hock

Blk 215 Lorong 8 Toa Payoh
#07-721
Singapore 310215

Mobile: +6596662278

Bryan

Vehicle & Document Information

WIP No 43219
Reg No/Reg Date SKE9898K / 30/09/2008
Date In/Mileage 07/07/2020/ 136152
Chassis No WDB2304582F149888
Engine No 27296831298168
Make/Model MB/SL 350 (New Generation)
Colour/Trim 021 197 Obsidian Bl/ 042 217 Leather Fla

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	27/09/2021/ 12:22	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :GA385315 // 15-04-2020 DRIVE IN/EXCESS :10-06-2020 // \$700 DATE IN/DATE SURVEY:25-06-2020 // LKK BRYAN BY/AUTHORIZED ON :VERON CHEN // 07-07-2020				
X BPNEXC INSURANCE EXCESS				-700.00
M MBPNLUMP LIMITSUM REPAIR				62000.00

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 61,300.00
7% GST on 61300.00 4291.00
Total Payable 65,591.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany