

cecilia

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Date : 29/4/2020

M/S AIG

DEAR SIR / MADAM *www.lkk.com.sg*

ESTIMATE REPAIR COST FOR SKB208C

TO SUPPLY :

List Items

- 01) 1 PC REAR BUMPER *1287.23*
02) 1 PC REAR BUMPER SIDE RETAINER
03) 7 PCS REAR BUMPER CLIPS *50*

<i>Deep cut</i>	\$ 1,600.51 ✓
<i>su</i>	\$ 70.40 X
<i>ner</i>	\$ 27.00 ✓
	<u>\$ 1,747.91</u>
LESS 5%	\$ (87.40)
	<u>\$ 1,660.51</u>
	\$ 30.00 <i>20</i>
<i>11</i>	\$ 80.00 X
	\$ 680.00 <i>300</i>
	\$ 80.00 <i>50</i>
	\$ 700.00 <i>500</i>
	<u>\$ 3,230.51</u>

- 04) Wiring
05) TUFF KOTE
06) LABOUR CHARGE
07) REMOVE AND REFIX SENSOR
08) SPRAY PAINTING

not Authorized
LKK
L/S # 1700
2 days
28/5/20

P-1337-23
\$2
P-1270-36
L-870.00
2140.36
1712.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer

Signature:

Date: