

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 55082**
Date Estimated : **28/04/2020**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Choong Zhi Jie (Zhong ZhiJie)
12A Hougang Street 11
#10-58

Singapore 534074

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMT1123M	WBAJR12090BR79774	30/01/2020	520i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper including remove attachments to facilitate repairs.	850.00		850.00
To respray front bumper.	934.00		934.00
To replace left LED AHL headlight.	450.00		450.00
To check electrical wiring systems at the front section for proper function.	150.00		150.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL PRIMED (PMA/PDC)	1,377.95	1.00		1,377.95
LH HEADLIGHT LED AHL HIGH (ICON LIG	4,879.55	1.00		4,879.55

SUPPLEMENTARY ITEMS

Total Labour :	2,464.00
Total Parts :	6,257.50
Total Labour & Parts :	8,721.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,721.50
GST @7%:	610.51
Grand Total :	9,332.01