



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2002867
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556

INV Date 13/05/2020
Reference NS/INC20005484/Fyf3n2
Code INC4



PROFESSIONAL SERVICE FEE

Vehicle No. SH 9384R
Insured Veh. GBJ 5915B
Claim No. MT/1091947-002
Policy No. 5110409450
Accident Date 27/04/2020
Inspection Date 29/04/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

National Assessment Centre Services

HYN




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20005484/Fyf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 13-05-2020	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 5915B	Veh. Inspected	SH 9384R	
Policy No.	5110409450	Coverage (\$)	0.00	
Claim No.	MT/1091947-002	Excess (\$)	0.00	
Assign From		Assign Date	29/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ (G3)	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVLU188765	Colour	BLUE	
Odometer	41872	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	8 mm	
L/H Front Tyre	195/65 R15	MICHELIN	8 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	27/04/2020	Inspection Date	29/04/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9384R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	418.30	-
1	FRONT BUMPER BRACKET-RH	NOT NECESSARY	28.00	-
1	FRONT BUMPER TOP BRACKET-RH	NOT NECESSARY	12.00	-
10	FRONT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FRONT FENDER-RH	TO REPAIR SEE LABOUR	490.70	-
1	FRONT FENDER EMBLEM-BLUEDRIVE	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-199.52	-5.32
			798.08	21.28
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER AND FRONT FENDER-RH.		700.00	640.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.	NOT NECESSARY	80.00	-
	TUFF KOTE.		80.00	30.00
			1,360.00	1,070.00
	GRAND TOTAL		2,158.08	1,091.28
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,091.28

Report Ref No. NS/INC20005484/Fyf3n2



PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SH 9384R

INSPECTION





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SH 9384R

RE-INSPECTION

