



Case Details

Case Reference Number : BUS/04/20/5007
Type of Repair : Accident Repair
Vehicle Registration Number : SMB1622J

Company Type : SMRT Buses Ltd
Estimation ID : EST-11324-JD
Assigned By : Claiming Case Owner Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 03/04/2020 12:00 AM
Vehicle Age(In Months) : 62

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SMRT LOGO	1	200,00	200,00	0,00	200,00	Replace	1	200,00	Replace	/ NEC
Total Spare Part Cost									200,00		Surveyor Total		200,00	
Lump Sum Discount (%)									20,00		Lump Sum Dis (%)		0	
Final Spare Part Cost									160,00		Final Sur Total		200,00	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	530,00	265	
Total:			530,00	265,00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	878,00	708	
Total:			878,00	708,00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0,00	0,00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	160,00	200,00
Total Labour Cost	530.00	265.00
Total Spray Painting	878.00	708,00
Other	0,00	0.00
Overall Total	160,00	1,173,00
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	1,173,00
Surveyor Approved Amount		1,173,00
No of Repair Days*	4	2 <i>2 days</i>
Remarks	-	L/S repair
Surveyor Name		Sun Pin (LKK)
Signature		 Save Clear
Survey Date	30/04/2020	

