

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005490/BGA3Q2

Date: 20/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800097225-01

Claimant

Vehicle No : SMM69E

Insured Vehicle No : SMD3085K

Date of Loss: 28/04/2020

Nature of Claim: TP

Claim No: 9788143581SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM69E

Make & Model: TESLA MODEL S 75D, (A)

Engine No: HIDDEN

Reg. Date: 07/02/2020 (Man. Year: 2018)

Chassis No: 5YJSB7E27JF260968

Colour: White

Odometer: 3006 km

Engine Capacity: 386 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 R19

Rear Tyre Size:

265/35 R19

Front Left Side: Michelin 8 mm

Rear Left Side:

Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side:

Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,307.20	13,805.60	2,501.60	15.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	1,400.00	2,460.00	63.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,167.20	15,205.60	4,961.60	24.60
Approved Total (Overridden) (S\$)		12,150.00		
Nett Amount (S\$)	20,167.20	12,150.00	8,017.20	39.75
+ Loss of Use (12.0 x S\$50.00/day) (S\$)		600.00		
(S\$)		12,750.00		
Liabe Amount (60.00%) (S\$)		7,650.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		7,766.45		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 29/04/2020

Date Inspected: 29/04/2020 Inspected At:

Team Autopro Pte Ltd - Sin Ming (HQ)
160 SIN MING DRIVE #02-12 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	4,068.00 F	*4,068.00 F
2	1		*REAR BUMPER DEFUSER	Not Damaged	1,298.00 F	*- F
3	1		*REAR BUMPER CARRIER	Necessary	48.00 F	*48.00 F
4	2		*REAR BUMPER SIDE RETAINER	Necessary	56.00 F	*56.00 F
5	2		*REAR BUMPER REFLECTOR	Broken (1 PCS ONLY)	207.20 F	*103.60 F
6	1		*REAR BUMPER REINFORCEMENT	Bent	2,900.00 F	*2,900.00 F
7	2		*REVERSE SENSOR	Cut (1 PCS ONLY)	560.00 F	*200.00 F
8	1		*REAR WEATHERSTRIP	Not Damaged	510.00 F	*- F
9	1		*REAR FENDER RH	Dented	2,890.00 F	*2,890.00 F
10	1		*TAILLAMP RH	Cut	1,450.00 F	*1,450.00 F
11	1		*REAR BUMPER CLIPS	Necessary	80.00 F	*30.00 F
12	1		*REAR FENDER SEALANT	Necessary	80.00 F	*30.00 F
13	1		*TAILLAMP CLIPS	Necessary	80.00 F	*30.00 F
14	1		*TAILLAMP SEAL	Not Necessary	80.00 F	*- F
15	1		*WRAP	Cut	2,000.00 F	*2,000.00 F
					Total Parts (S\$)	16,307.20 13,805.60

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REVERSE SENSOR	New	100.00	60.00
2	R&R SIDE GLASS	New	150.00	80.00
3	R&R INTERIOR UPHOLSTERY	New	150.00	0.00
4	PANEL BEAT	New	1,400.00	600.00
5	RUST PROOFING	New	100.00	50.00
6	SPRAY BASE PAINTING	New	800.00	400.00
7	DICHARGE FULL ELECTRICAL	New	200.00	0.00
8	CHARGE FULL ELECTRICAL	New	200.00	0.00
9	CHECK WIRING	New	60.00	60.00
10	DIAGNOSTIC RESET FAULT CODE & PROGRAMMING	New	600.00	150.00
11	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			3,860.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >