

Name of Survey: _____ Vehicle Nos: **SMM 69 E**
 Date of ReSurvey: _____ Model: **Tecla S75D**
 Contacts: _____ After-Paint: _____ Year: _____
 Chassis No: _____

* AGREED Cost Of Repair and Repair Day/s with SIE *
 Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit \$	TOTAL \$
Parts Sub Total:				
Discount:				
PARTS TOTAL:				

Nos.	SPECIAL NETT	Qty	Unit \$	TOTAL \$
1	Rear bumper	1	\$ 4,068.00	\$ 4,068.00
2	Rear bumper defuser	1	\$ 1,298.00	\$ 1,298.00
3	Rear bumper carrier	1	\$ 48.00	\$ 48.00
4	Rear bumper side retainer	2	\$ 28.00	\$ 56.00
5	Rear bumper reflector	1	\$ 103.60	\$ 103.60
6	Rear bumper reinforcement	1	\$ 2,900.00	\$ 2,900.00
7	Reverse sensor	2	\$ 280.00	\$ 560.00
8	Rear weatherstrip	1	\$ 510.00	\$ 510.00
9	Rear fender RH	1	\$ 2,890.00	\$ 2,890.00
10	Tail lamp RH	1	\$ 1,450.00	\$ 1,450.00
11	Rear bumper clips	1	\$ 80.00	\$ 80.00
12	Rear fender sealant	1	\$ 80.00	\$ 80.00
13	Tail lamp clips	1	\$ 80.00	\$ 80.00
14	Tail lamp seal	1	\$ 80.00	\$ 80.00
15	Wrap	1	\$ 2,000.00	\$ 2,000.00
SPECIAL NETT TOTAL:				\$13,805.60

Nos.	LABOUR	Qty	Unit \$	TOTAL \$
1	R&R reverse sensor	1	\$ 60.00	\$ 60.00
2	R&R side glass	1	\$ 80.00	\$ 80.00
3	R&R interior upholstery	1	\$ 150.00	\$ 150.00
4	Panel beat	1	\$ 600.00	\$ 600.00
5	Rust proofing	1	\$ 50.00	\$ 50.00
6	Spray base painting	1	\$ 400.00	\$ 400.00
7	Discharge full electrical	1	\$ 200.00	\$ 200.00
8	Charge full electrical	1	\$ 200.00	\$ 200.00
9	Check wiring	1	\$ 150.00	\$ 150.00
10	Diagnostic reset fault code & programming	1	\$ 60.00	\$ 60.00
11	Conduct water leakage test	1	\$ 100.00	\$ 100.00
LABOUR TOTAL:				\$1,440.00

PARTS TOTAL: \$
 SPECIAL NETT TOTAL: \$ 16,307.20
 LABOUR TOTAL: \$ 1,440.00
 GRAND TOTAL: \$ 17,747.20

1/5 12/15/20
 Repair days 8
 15/5/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be surveyed and is subject to final approval from Insurance Company

Authorised by Repairer
 Signature: _____
 Repaired by Eric (8269-9999) Page 1 of 1

TCIM Lin
 Survey 29/4/2020
 Repair 30/4/2020