



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CENTRAL NARCOTICS BUREAU

Ref : CC2/CNB20005491/Qee2

CORPORATE SERVICES DIVISION
BLK B
POLICE CANTONMENT COMPLEX
393 NEW BRIDGE ROAD
SINGAPORE 088763



Date : 12-05-2020

Code : CNB

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	QX 1312R (SLL 9217C)
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From SHIRLENE YEO	Assign Date	30/04/2020

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	KL1JA69E9GK347049	Colour	GREY
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R15	HANKOOK	6 mm
L/H Front Tyre	205/60 R15	HANKOOK	6 mm
R/H Rear Tyre	205/60 R15	HANKOOK	6 mm
L/H Rear Tyre	205/60 R15	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/03/2020	Inspection Date	30/04/2020
Survey held at	391 NEW BRIDGE ROAD		
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD		

5a. Remarks

--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Registration No. QX 1312R (SLL 9217C)

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front RH Fender	1	Dented	\$1,250.00	\$1,500.00	
1.2	Rear Bumper	1	Crumpled	\$1,270.00	\$2,100.00	
	COSTING	TOTAL PARTS COST			\$3,600.00	
2	SCOPE OF REPAIRS					
2.1	Remove, Replace & Spray Paint for Front RH Fender					4
2.2	Remove, Replace & Spray Paint for Rear Bumper					4
2.3	Panel Beating & Spray Paint for Front RH Door					3
2.4	Panel Beating & Spray Paint for Rear RH Wheel Arc Panel					2
2.5	Spray Paint for Rear RH Door					3
2.6	Repair & Spray Paint for Front Bumper					3
COSTING		TOTAL MAN-HOUR				19.00

Registration No. QX 1312R (SLL 9217C)

Vehicle Inspected By

OI SUN PIN
Asst. Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. QX 1312R (SLL 9217C)

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

