

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0169/20
DATE : 27-APR-2020

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 10B BUILDING
S(049711)
TEL : 63476100
FAX : 62344174
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : TAN CHENG KANG
ADDRESS : 102 JOO CHIAT TERRACE
#04-03
S(427256)
TELEPHONE NO : MR TAN 98392150

*Not Authorized
new
8/5/20
take photo before painting.
3 days.*

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1800083449-01
VEHICLE NO : SFH1269Y
MODEL CODE : BOTARCZB17EWA----K
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2017
ENGINE NO : HR16928819C
CHASSIS NO : MNTBBAB17Z0032471
MILEAGE : 37786 KM
DATE IN : 27/04/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 25/04/2020

9645 0084 elmer@faching.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFH1269Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR LH RADIATOR SUPPORT & FRT LH FENDER & BONNET RENEW FRT BUMPER 390	1950.00	390
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME 250	1100.00	500
3	ZZ/003	RENEW BOTH HEADLAMP AND FOCUS	48.00	/
TOTAL LABOUR CHARGES			3098.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFH1269Y

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	LH FOGLAMP	B61E0-3ST0A			600.80	?
2	SPINDRES	NPN			50.00	?
3	LH HEADLAMP	26060-3SB0D	815.00			
4	RH HEADLAMP	26010-3SB0D	815.00			
5	RADIATOR TOP MOULDING BRACKET	62322-3ST0A	397.90			
6	RADIATOR GRILLE	62312-3SB0A	796.80			
7	ENERGY ABSORBER	62090-3ST0A	244.50			
8	INNER BRACKET FRONT BUMPER	62663-3ST0A	210.70			
9	LH SIDE BRACKET FRT BUMPER	62225-3ST1A	25.10			
10	LOWER GRILLE FRONT BUMPER	62254-3ST0A	302.50			
11	TOP HOOK COVER FRT BUMPER	622A0-3ST0A	31.00			
12	CLIP FRONT BUMPER @ SGD \$ 1.30 EACH	01553-10501	7.80			
13	FRT LH FOGLAMP GARNISH	62257-3ST0B	130.10			
14	FRONT BUMPER	62022-9A76H			472.30	
SUB TOTAL			3776.40	0.00	1123.10	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			755.28	0.00	0.00	
GRAND TOTAL			3021.12	0.00	1123.10	
OVERALL TOTAL			4144.22			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLIFT INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFH1269Y

TOTAL LABOUR CHARGES	3098.00
TOTAL SPARE PARTS CHARGES	4144.22

GRAND TOTAL	7242.22 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.