

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20005497/UEA3Q2

**Date:** 31/08/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SLR9449T	<b>Insured Vehicle No :</b>	SHD4842U
Date of Loss: 28/04/2020	Nature of Claim: TP	Claim No: MCT20040251

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLR9449T</b>		
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Engine No:	P520454862
Reg. Date:	31/08/2017 (Man. Year: 2017)	Chassis No:	JM6BN22A8H0162668
Colour:	Grey	Odometer:	188856 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,074.88	819.52	1,255.36	60.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	950.00	790.00	45.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,814.88</b>	<b>1,769.52</b>	<b>2,045.36</b>	<b>53.62</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,400.00</b>		
<b>(S\$)</b>	3,814.88	1,400.00	2,414.88	63.30
<b>+ GST 7.00/7.00% (S\$)</b>	267.04	98.00	169.04	63.30
<b>Nett Amount (S\$)</b>	<b>4,081.92</b>	<b>1,498.00</b>	<b>2,583.92</b>	<b>63.30</b>
<b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>Nett Liability (S\$)</b>		<b>2,098.00</b>		

### INSPECTION

Date of Assignment:	30/04/2020	
Date Inspected:	30/04/2020 Inspected At:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2020)
<b>Parts:</b>	143	MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLR9449T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Repair	1,046.20 FL	*- FL
2	1		*FRONT DOOR RUBBER -LH	Not Necessary	246.40 FL	*- FL
3	1		*REAR DOOR -LH	Badly Dented	1,024.40 FL	*1,024.40 FL
4	1		*REAR DOOR HINGE LOWER-LH	Not Necessary	50.20 FL	*- FL
5	1		*REAR DOOR RUBBER -LH	Not Necessary	226.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,593.60</b>	<b>1,024.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	518.72	204.88
<b>Total Parts (\$)</b>	<b>2,074.88</b>	<b>819.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	750.00	300.00
2	TO REMOVE & REFIT DOOR ASSY	New	160.00	50.00
3	TO CHECK WIRING	New	80.00	0.00
4	TO SPRAY PAINT	New	750.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,740.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >