# 2,019.52LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Clara Li Zi Rong Date: 11 May 2020

## **Preliminary Advice**

Insured Vehicle No : SLR1835P

TP Vehicle No : SMF7686P Accident Date : 28/04/2020 Make : HYUNDAI ELANTRA Assignment Date : 30/04/2020 : 11/05/2020 Date of Inspection Est. Duration of Repair : 4 days

Inspection At : Precise Auto Service (HQ)

No 1 Kaki Bukit Ave 6, #02-34/36

Singapore 417883

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages ... N/S rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,071.84
Revised Amount	:S\$	2,019.52
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,019.52

Lump Sum Repair :S\$

#### **Total Loss Consideration**

Other comments: We have not authorized repairs.

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

### Remarks

( X )

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.